Subject Index
Technical Information Papers

This document was last updated September 3, 2015

A-

Abrasion
Selection criteria for wet end ceramics, 0502-15

Abrasion resistance
Selection criteria for wet end ceramics, 0502-15

Absorption
Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25

Acrylic fibers
see Polyacrylics, Synthetic fibers

Additives
Techniques for running "WRA" (water resistant starch adhesive), 0304-46

Adhesives
Buying, storing, and handling flexo folder gluer/rotary diecutter adhesives, 0305-25
Causes and corrections of common corrugator bonding problems, 0304-32
Evaluating glue lap adhesive properties, 0304-16
Procedure for setting up a raw material trial on the corrugator, 0304-01
Proper methods of measuring starch adhesive viscosity, 0304-33
Starch adhesive preparation and distribution systems: housekeeping, 0304-06
Starch adhesive trial, 0304-22
Statistical process control of starch gelatinization temperature, 0304-14
Statistical process control of starch viscosity, 0304-15
Stickies definition and classification, 0603-02
Techniques for bonding of densified liners, 0304-40
Techniques for running "WRA" (water resistant starch adhesive), 0304-46
Understanding wet strength: what are MRA, WRA, and WPA?, 0304-69
Understanding and troubleshooting hot melt adhesives, 0304-74
Using washup water as the vehicle in starch-based corrugating adhesive, 0304-44

After dryers
Paper machine drying rate, 0404-07

Agitation
Using washing water as the vehicle in starch based corrugating adhesive, 0304-44

Agitators
Guidelines for side-entering stock agitators, 0420-13

Air
Paper machine room ventilation guidelines, 0404-50

Air balance
see Air, Materials balance

Air flow
Measurement of vacuum pump air flow, 0420-12
Minimum dryer pocket air requirements, 0404-17
Guidelines for the design, operation, performance evaluation, and troubleshooting of a paper machine hood and air systems, 0404-24
Sheet handling devices, 0404-44

Air jets
Sheet handling devices, 0404-44

Air permeability
Physical characterization of press fabrics: basis weight, air permeability, void volume under loading and pressure uniformity, 0404-20

Air pollution
Collection and burning of concentrated noncondensible gases: regulations, design and operation, 0416-09
Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25

Air staging
Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25

Alignment
Checking the parallel of corrugating rolls with "NCR" paper, 0304-62

Alkali
Specific heat of caustic soda solutions, 0606-07

Alkaline sulfite pulping
Boiling point rise of spent sulfite liquors, 0607-21
Definitions of terms in the sulfite pulping process, 0607-25
Density of aqueous sodium sulfite solution, 0607-18
Density of milk of lime solution, 0607-05
Solubility of sulfur dioxide, $Ca(HSO_3)_2$ solutions, 0607-07
Sulfur burner gas strength volume, 0607-01
Viscosities of various spent sulfite liquors at 26.7°C, 0607-22

Alkalinity
Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03
Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Ammonia
Solubility of sulfur dioxide, 0607-06

Analysis
Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Angle of slide
see Slide angle

Anilox coaters
In-line coating at the corrugator, TIP 0304-39
Anilox rolls
see Flexography, Printing cylinders
Anvil
Troubleshooting the diecutting section, 0305-39
Approach flow systems
Headbox approach piping guidelines, 0404-54
Ash
Chloride and potassium measurement and control in the pulping and chemical recovery cycle, 0416-15
Drainage evaluation by mass measurement, 0502-12
Atmosphere
Testing atmospheres simulating end use conditions, 0808-05
Auditing
Checklist for a properly planned project, 0408-01
Automatic feeders
see Feeders

B-
Bacteria
Starch adhesive preparation and distribution systems: housekeeping, 0304-06
Bag papers
Paper machine performance guidelines, 0404-47
Bags
Paper machine drying rate, 0404-07
Bar Width Reduction (BWR)
see Product codes
Bar codes
see Product codes
Bases
see Hydroxides
Basis weight
Headbox approach piping guidelines, 0404-54
Batch digesters
Guidelines for inspecting batch digesters, 0402-22
Batch process
Measurement of dryer condensing rates (vertical separator method), 0404-18
Beams
Calibration of flexible beam crush tester, 0304-20
Bearings
Corrugator bearing clearance checks and their impact, 0304-47
Paper machine reel-spool journals: guidelines for crack testing and repair or replacement, 0402-34
Total indicated runout and its impact on combined board quality, 0304-56
Biocide
Using washing water as the vehicle in starch based corrugating adhesive, 0304-44
Biomass
Performance test procedure for boilers using biomass as fuel, 0416-18
Sampling procedures for biomass fuel for boiler performance testing, 0416-17
Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25
Biomechanics
see Human factors
Bisulfites
Physical and chemical properties of magnesia-base pulping solutions, 0607-04
Solubility of sulfur dioxide, 0607-06
Solubility of sulfur dioxide in magnesium bisulfite solution, 0607-09
Solubility of sulfur dioxide in saturated magnesium bisulfite solution, 0607-10
Black liquors
Field welding of pin studs in black liquor recovery boilers, 0402-15
Recommended test procedure for black liquor evaporators, 0416-11
Recovery boiler performance calculation – short form, 0416-01
Response to contamination of high purity boiler feedwater, 0416-05
Ultrasonic testing (UT) for tube thickness in black liquor recovery boilers, 0402-18
Blade coaters
see also Coaters
In-line coating at the corrugator, TIP 0304-39
Bleach plants
Bleaching plant washer efficiency guide, 0606-23
Bleached board
Paper machine drying rate, 0404-07
Paper machine performance guidelines, 0404-47
Bleaching
Boiling point rise of spent sulfite liquors, 0607-21
Cotton in nonwovens, 1205-02
Chlorine gas curve, 0606-02
Definitions of terms in the sulfite pulping process, 0607-25
Density of aqueous sodium sulfite solution, 0607-18
Density of chlorine gas, 0606-03
Density of milk of lime solution, 0607-05
Energy checklist: pulp mill, 0416-24
Heat of vaporization of liquid chlorine, 0606-04
Recommended pulp bleaching stage designation method, 0606-21
Relative enthalpy (heat content) of sodium hydroxide solutions, 0606-08
Solubility of sulfur dioxide, $Ca(HSO_3)_2$ solutions, 0607-07
Specific gravity and density of caustic soda solutions, 0606-20
Specific gravity of sodium chloride solutions, 0606-10
Sulfur burner gas strength volume, 0607-01
Viscosities of various spent sulfite liquors at 26.7°C, 0607-22
Viscosity of liquid chlorine 0606-05
Viscosity of sodium hydroxide solutions, 0606-11
Bleaching stages
see Bleaching

Blind-drilled rolls
see Vacuum rolls
Blistering
Addendum to *Corrugating Defect Terminology Manual* - defects related to the use of fingerless singlefacers, 0304-17
Blow boxes
Sheet handling devices, 0404-44
Blowdown
see also Blowing
Design engineer decisions tree: paper mill boiler feedwater, 0416-04
Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14
Blowing
Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03
Board caliper
see Thickness
Boiler feed water
see Boilers, Feedwater
Boiler tubes
Guideline for obtaining high quality radiographic testing of butt welds in boiler tubes, 0402-33
Guidelines for evaluating quality of boiler tube butt welds with ultrasonic testing, 0402-31
Guidelines for specification and inspection of electric resistance welded (ERW) and seamless boiler tube for critical and noncritical service, 0402-13
Boilers
Best practice guidelines for detecting and mitigating waterside cracking (stress-assisted corrosion) in power and recovery boilers, 0402-38
Design engineer decisions tree: paper mill boiler feedwater, 0416-04
Explanation of recovery boiler leak indications, 0416-23
Evaluating reverse osmosis for treating makeup to the boiler feedwater in a pulp and paper mill, 0416-07
Guidelines for detection, monitoring and prevention of flow accelerated corrosion (FAC) in the pulp and paper mill, 0402-36
Guidelines for replacement of generating bank tubes with expanded joints in two-drum boilers, 0416-08
Guidelines for evaluating quality of boiler tube butt welds with ultrasonic testing, 0402-31
Keys to successful chemical cleaning of boilers, 0416-06
Performance test procedure for boilers using biomass as fuel, 0416-18
Sampling procedures for biomass fuel for boiler performance testing, 0416-17
Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03
Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14
Water treatment-related opportunities for energy conservation in a paper mill powerhouse, 0416-13
Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25
Best Practice for Recovery Boiler Inspection (Optimizing Inspection Scope), 0416-26
Bonding
Techniques for bonding of densified liners, 0304-40
Box compression
see Compression strength
Box flaps
see Flaps
Box machines
Troubleshooting a glue lap problem, 0304-10
Box plants
see Converting plants
Boxes
Corrugated boxplant-list of potential hazards, 0301-01
Critical properties to consider when unitizing, 0304-72
High vacuum sheet dewatering, 0404-60
Squaring flap cut (center special) boxes, 0305-45
Broke
Broke loss calculations, 0502-10
Bronze
Guidelines for nondestructive examination of suction roll shells, 0402-19
Weld repairs on new suction roll shells, 0402-17
Burners
Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25
Burst testers
Calibration and maintenance of, 0304-24
Butt joints
Guidelines for evaluating quality of boiler tube butt welds with ultrasonic testing, 0402-31
Butt welds
Guidelines for evaluating quality of boiler tube butt welds with ultrasonic testing, 0402-31

C-
CADCAM
Computer-assisted machinery, 0305-02
CONEG
see Regulations
Cadmium
An explanation of the CONEG heavy metal guidelines, 0304-58
Calcination
Physical data of calcined kaolin-water suspensions, 0106-09
Calcium base liquors
Solubility of sulfur dioxide, $Ca(HSO_3)_2$ solutions, 0607-07
Calcium bisulfite
Solubility of sulfur dioxide, $Ca(HSO_3)_2$ solutions, 0607-07
Calcium carbonate
Physical data of calcium carbonate-water suspensions,

0106-01
Calcium hydroxide
Density of milk of lime solution, 0607-05
Calculations
see Computation
Calibration
Basic guidelines for image analysis measurements, 0804-09
Calibration and maintenance of the manually operated micrometer, 0304-30
Calibration of flexible beam crush tester, 0304-20
Of burst testers, 0304-24
Calibration technique for the drum style chip thickness classifier, 0602-03
Suggestions for developing a box plant quality manual, 0304-49
Caliper
see Thickness
Canadian standard freeness
Interconversion of freeness, 0809-01
Carbon steel
Inspection for cracking of composite tubes in black liquor recovery boilers, 0402-30
Carbonates
Chloride and potassium measurement and control in the pulping and chemical recovery cycle, 0416-15
Estimating the first melting temperature of fireside deposits in recovery boilers, 0416-12
Physical data of calcium carbonate-water suspensions, 0106-01
Cast iron
Guide for increasing the maximum allowable working pressure of cast iron, ASME constructed paper machine dryers, 0420-14
Castings
Guidelines for procurement of cast stainless steels for large pumps and valves for the pulp and paper industry, 0402-25
Caustic soda
see Sodium hydroxide
Causticizing
Energy checklist: pulp mill, 0416-24
Material balance equations relating to digester requirements, 0418-02
Ceramic coatings
Press roll cover application guidelines, 0404-37
Ceramics
Selection criteria for wet end ceramics, 0502-15
Use of ceramics on the forming section: diagnosing and preventing forming fabric wear, 0502-19
Certification
Guideline for obtaining high quality radiographic testing of butt welds in boiler tubes, 0402-33
Chalk
see Calcium carbonate
Charting
Introduction to the flow chart, 0305-26
Short-run statistical process control: a basic charting method, 0304-70
Statistical process control pin adhesion, 0304-23
Statistical process control - procedures for charting warp, 0304-13
Checklist
see Maintenance
Chemical preparation
Specific gravity and density of caustic soda solutions, 0606-20
Specific gravity of sodium chloride solutions, 0606-10
Chemical properties
Chlorine dioxide (ClO_2) safe storage and handling, 0606-30
Fluoropolymer properties and applications in pulp and paper mills, 0402-37
Magnesia-base pulping solutions, 0607-04
Sodium chlorate ($NaClO_3$) safe handling and storage, 0606-31
Chemical pulps
Boiling point rise of spent sulfite liquors, 0607-21
Definitions of terms in the sulfite pulping process, 0607-25
Density of aqueous sodium sulfite solution, 0607-18
Density of milk of lime solution, 0607-05
Solubility of sulfur dioxide, $Ca(HSO_3)_2$ solutions, 0607-07
Sulfur burner gas strength volume, 0607-01
Viscosities of various spent sulfite liquors at 26.7°C, 0607-22
Chemical recovery
Recausticizing material balance equations relating to digester requirements, 0418-02
Chemicals
Material safety data sheets, what to look for - how to understand them, 0304-38
Chests
see Stock chests
Chip classifiers
Calibration technique for the drum style chip thickness classifier, 0602-03
Chip silos
see Chip bins
Chips
Calibration technique for the drum style chip thickness classifier, 0602-03
Chlorides
Chloride and potassium measurement and control in the pulping and chemical recovery cycle, 0416-15
Estimating the first melting temperature of fireside deposits in recovery boilers, 0416-12
Chlorine
Chlorine gas curve, 0606-02
Density of chlorine gas, 0606-03
Heat of vaporization of liquid chlorine, 0606-04
Viscosity of liquid chlorine, 0606-05
Chlorine dioxide
Safe storage and handling of, 0606-30
Specific gravity of sodium chloride solutions, 0606-10

Chrome
Tests for corrugator roll wear, 0304-53
Chromium
An explanation of the CONEG heavy metal guidelines, 0304-58
Clad-steel plate
see Plates
Classification
Paper grade classifications, 0404-36
Clay
Kaolin clay pigment index, 0106-06
Physical data of calcined kaolin-water suspensions, 0106-09
Physical data of hydrous Kaolin-water suspensions, 0106-02
Cleaners
Catalog of stock prep pilot plants, 0502-20
Introduction to centrifugal cleaners, 0508-10
Cleaning
Cleaning anilox rolls: procedures and options, 0306-18
Cleanup procedures for flexo folder gluer/rotary diecutters, 0305-33
Daily, weekly, and monthly maintenance checklists, 0305-34
Dryer fabric cleaning, 0404-38
Housekeeping at order and shift change and weekly, 0305-32
Introduction to centrifugal cleaners, 0508-10
Keys to successful chemical cleaning of boilers, 0416-06
Paper machine clothing cleaning and conditioning for recycled fiber use, 0404-51
Paper machine shower recommendations, 0404-61
Post-fabrication cleaning of stainless steel in the pulp and paper industry, 0402-35
Cleaning chemicals
see Cleansers
Cleansers
Keys to successful chemical cleaning of boilers, 0416-06
Clogging
Nozzle maintenance and clogging, 0420-15
Clothing
see Felts, Machine clothing
Coating color
see Color
Coating thickness
Tests for corrugator roll wear, 0304-53
Coatings
Guidelines for thermal spray coatings installed to prevent corrosion in pulp mill process equipment, 0402-32
Tests for corrugator roll wear, 0304-53
Coefficient of friction
see Friction factor
Combined boards
Common curtain coating problems: causes, detection, and correction, 0304-26
Obtaining off the corrugator for use in statistical process control procedures, 0304-12
Total indicated runout and its impact on combined board quality, 0304-56
Compression
Corrugated caliper: why is it so important?, 0304-04
Compression resistance
see Compression strength
Compression strength
Corrugated caliper: why is it so important?, 0304-04
Obtaining a combined board caliper off the corrugator for use in statistical process control procedures, 0304-12
Statistical process control techniques to assist in meeting specification at finishing crush process control points to the paper and paperboard industries, 0304-11
Computation
Paper machine drying rate, 0404-07
Computer-assisted
see CADCAM
Concentricity
Total indicated runout and its impact on combined board quality, 0304-56
Condensates
Guidelines for detection, monitoring and prevention of flow accelerated corrosion (FAC) in the pulp and paper mill, 0402-36
Measurement of dryer condensing rates (continuous method), 0404-03
Measurement of dryer condensing rates (vertical separator method), 0404-18
Stripping of kraft pulping process condensates: regulations, design and operation, 0416-10
Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03
Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14
Water treatment-related opportunities for energy conservation in a paper mill powerhouse, 0416-13
Yankee dryer steam condensing rates, 0404-49
Condensation
Dryer condensing rates (batch method), 0404-02
Dryer condensing rates (continuous method), 0404-03
Condensing rates
see Condensation
Conditioning
Paper machine clothing cleaning and conditioning for recycled fiber use, 0404-51
Testing atmospheres simulating end use conditions, 0808-05
Conductivity
Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03
Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14
Conical refiners
Conical refining intensity, 0508-07
Consistency
Drainage evaluation by mass measurement, 0502-12
Generalized method for determining the pipe friction loss

of flowing pulp suspensions, 0410-14
Optimum for pumping pulp, 0410-15
Construction materials
Sodium chlorate ($NaClO_3$) safe handling and storage, 0606-31
Contact bearings
see Bearings
Contact technique
Guideline for obtaining high quality radiographic testing of butt welds in boiler tubes, 0402-33
Container boards
Friction -- slide angle, 0304-34
Contaminants
see Impurities
Contamination
see Pollution control
Continuous digesters
Guidelines for inspection of continuous digesters and impregnation vessels, 0402-27
Contraction
Flow from a 45° slice, 0410-03
Flow from a nozzle (slice) with inclined upper lip, 0410-04
Flow from a vertical slice, 0410-02
Control charts
see Charting
Control systems
Short-run statistical process control: a basic charting method, 0304-70
Conversion factors
Units of measurement and, 0800-01
Converting factors
Moisture content of paper: terminology and conversion, 0808-02
Converting plants
Boxplant quality measurement: why test?, 0304-02
Computer-assisted machinery, 0305-02
Corrugated boxplant - list of potential hazards, 0301-01
Machinery considerations and selection, 0305-06
Copper
Role of in a printing ink, 0304-61
Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03
Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14
Copper sulfate
Tests for corrugator roll wear, 0304-53
Cores
Determination of winder sets per reel, 0502-02
Reel diameter for various reel spool and roll core sizes, 0502-03
Corrosion
see also Corrosion inhibitors
Best practice guidelines for detecting and mitigating waterside cracking (stress-assisted corrosion) in power and recovery boilers, 0402-38
Estimating the first melting temperature of fireside deposits in recovery boilers, 0416-12
Fluoropolymer properties and applications in pulp and paper mills, 0402-37
Guide to the use of stainless steel pipe specifications, 0402-24
Guidelines for corrosion resistant weld metal overlay of digester vessels in alkaline pulping service, 0402-03
Guidelines for detection, monitoring and prevention of flow accelerated corrosion (FAC) in the pulp and paper mill, 0402-36
Guidelines for inspecting batch digesters, 0402-22
Guidelines for inspection of continuous digesters and impregnation vessels, 0402-27
Guidelines for inspecting used fiber-reinforced plastics (FRP) equipment, 0402-28
Guidelines for nondestructive examination of suction roll shells, 0402-19
Nozzle maintenance and clogging, 0420-15
Post-fabrication cleaning of stainless steel in the pulp and paper industry, 0402-35
Ultrasonic technician performance test for boiler tube inspection, 0402-21
Ultrasonic testing (UT) for tube thickness in black liquor recovery boilers, 0402-18
Best Practice for Recovery Boiler Inspection (Optimizing Inspection Scope), 0416-26
Corrosion inhibitors
Keys to successful chemical cleaning of boilers, 0416-06
Corrosion prevention
Guidelines for thermal spray coatings installed to prevent corrosion in pulp mill process equipment, 0402-32
Guidelines for corrosion resistant weld metal overlay of digester vessels in alkaline pulping service, 0402-03
Corrugated boards
Copper in a printing ink, 0304-61
Critical properties to consider when unitizing, 0304-72
Important quality parameters of a printing ink, 0304-59
Obtaining caliper off the corrugator for use in statistical process control procedures, 0304-12
Proofing a flexo printing ink, 0304-60
Statistical process control friction-slide angle, 0304-34
Techniques to minimize twist warp, 0304-50
Warp in corrugated board, 0304-07
Corrugated boxes
see Boxes, Corrugated boards
Corrugated containers
see Boxes, Corrugated board, Folder gluers, Die cutters
Corrugated medium
An alternative method for designating flute sizes, 0302-04
Corrugating
An alternative method for designating flute sizes, 0302-04
Corrugating adhesives
see Adhesives
Corrugating machines
Checking for coating wear on corrugating rolls, 0304-73
Checking the flute depth of corrugating rolls, 0304-75
Checking the parallel of corrugating rolls with “NCR”

paper, 0304-62
Computer-assisted machinery, 0305-02
Conducting a corrugator temperature audit, 0304-65
Corrugator bearing clearance checks and their impact, 0304-47
Impact of doublebacker hot plate level on board quality and how to measure it, 0304-66
Improved techniques to measure corrugator glue machine meter gaps, 0304-68
Prevention of score cracking in a box plant, 0304-37
Procedure for setting up a raw material trial on the corrugator, 0304-01
Starch viscosity in corrugating adhesives, 0304-15
Tests for corrugator roll wear, 0304-53
Corrugating medium
Causes and corrections of common corrugator bonding problems, 0304-32
Edge crush test (ECT): its relationship to box compression and its derivation from containerboard edge stiffness, 0304-09
Paper machine performance guidelines, 0404-47
Paper machine drying rate, 0404-07
Procedure for setting up a raw material trial on the corrugator, 0304-01
Splicer defects and cures, 0304-31
Corrugating plants
see Operations
Corrugating rolls
see Rolls
Corrugator-double backer
see Corrugating machines
Corrugators
see Corrugating machines
Costs
Press section economic evaluation, 0404-22
Cotton
In nonwovens, 1205-02
Couch rolls
Paper machine vacuum selection factors, 0502-01
Counters
Counter ejector section, 0305-44
Cracks
Best practice guidelines for detecting and mitigating waterside cracking (stress-assisted corrosion) in power and recovery boilers, 0402-38
Guidelines for inspection and nondestructive testing of paper machine dryers, 0402-16
Guidelines for inspection of continuous digesters and impregnation vessels, 0402-27
Guidelines for nondestructive examination of suction roll shells, 0402-19
Inspection for cracking of composite tubes in black liquor recovery boilers, 0402-30
Crescent formers
Paper machine vacuum selection factors, 0502-01
Cross direction
Calculation and partitioning of variance using paper machine scanning sensor measurements, 1101-01
Statistical process control -- procedures for charting warp, 0304-13
Troubleshooting cross-machine direction moisture profile problems, 0404-57
Warp in corrugated board, 0304-07
Crown
see Roll crown
Crush
Calibration of flexible beam crush tester, 0304-20
Statistical process control techniques to assist in meeting specification at finishing crush process control points to the paper and paperboard industries, 0304-11
Cubical contents
see Volumetry
Curing
Drying and curing techniques for in-line flexographic printing, 0306-06
Curtain coating
Common curtain coating problems: causes, detection, and correction, 0304-26
Weight test, 0304-19
Cutters
see Die cutters
Cutting dies
see Die cutters, Rotary machines

D-
Damage
Guidelines for inspecting used fiber-reinforced plastics (FRP) equipment, 0402-28
Best Practice for Recovery Boiler Inspection (Optimizing Inspection Scope), 0416-26
Dandy rolls
Dandy roll applications, 0404-53
Data storage
Calculation and partitioning of variance using paper machine scanning sensor measurements, 1101-01
Data tables
Moisture content of paper: terminology and conversion, 0808-02
Deaerators
Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03
Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14
Defects
Addendum to *Corrugating Defect Terminology Manual* -- defects related to the use of fingerless singlefacers, 0304-17
Corrugator bearing clearance checks and their impact, 0304-47
Definitions
see Nomenclature
Degradation
Guidelines for inspecting used fiber-reinforced plastics (FRP) equipment, 0402-28
Densified liners
see Liners

Density
Density of aqueous sodium bicarbonate solution, 0607-13
Density of aqueous sodium carbonate solution, 0607-14
Density of chlorine gas, 0606-03
Milk of lime solution, 0607-05
Physical data of calcined kaolin-water suspensions, 0106-09
Physical data of calcium carbonate-water suspensions, 0106-01
Physical data of hydrous Kaolin-water suspensions, 0106-02
Sodium sulfite solution, 0607-18
Specific gravity and density of caustic soda solutions, 0606-20
Specific gravity of sodium chloride solutions, 0606-10
Deposits
Chloride and potassium measurement and control in the pulping and chemical recovery cycle, 0416-15
Estimating the first melting temperature of fireside deposits in recovery boilers, 0416-12
Keys to successful chemical cleaning of boilers, 0416-06
Deterioration
see Degradation
Dewatering
see Drainage, Water removal
Diameter
Roll diameter for various reel spool and roll core sizes, 0502-03
Dictionaries
see Nomenclature
Die cutters
see also Rotary machines
Buying, storing, and handling flexo folder gluer/rotary diecutter adhesives, 0305-25
Checklist: preparing die cuts for shipment, 0305-49
Cleanup procedures for flexo folder gluer/rotary diecutters, 0305-33
Troubleshooting the diecutting section, 0305-39
Drying and curing techniques for in-line flexographic printing, 0306-06
Introduction to flexo folder gluer/rotary diecutter TIPs, 0305-04
Minimizing rolling scores on lightweight and high-performance liners in diecutting operations, 0304-64
Ordering cutting dies, 0305-21
Project leader, 0305-13
Proper use of pull bands, 0305-18
Reduction or elimination of ink and/or varnish smear when printing and rotary die cutting in one pass, 0305-40
Rotary cutting die maintenance, 0305-23
Rotary diecutter urethane anvil maintenance, 0305-35
Squaring flap cut (center special) boxes, 0305-45
Dieboard
Multiple-out rotary diecut stacking, 0305-47
Stacking off the rotary diecutter, 0305-46
Diecut
Multiple-out rotary diecut stacking, 0305-47
Stacking off the rotary diecutter, 0305-46
Differential steam pressures
see Pressure gradiant
Digester balance equation
Recausticizing material balance equations relating to digester requirements, 0418-02
Digesters
Energy checklist: pulp mill, 0416-24
Guidelines for corrosion resistant weld metal overlay of digester vessels in alkaline pulping service, 0402-03
Guidelines for inspecting batch digesters, 0402-22
Guidelines for inspection of continuous digesters and impregnation vessels, 0402-27
Dimensional measurement
Calibration technique for the drum style chip thickness classifier, 0602-03
Dispersions
Physical data of calcined kaolin-water suspensions, 0106-09
Physical data of calcium carbonate-water suspensions, 0106-01
Physical data of hydrous Kaolin-water suspensions, 0106-02
Dissolved oxygen
Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03
Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14
Dissolving pulps
Boiling point rise of spent sulfite liquors, 0607-21
Definitions of terms in the sulfite pulping process, 0607-25
Density of aqueous sodium sulfite solution, 0607-18
Density of milk of lime solution, 0607-05
Solubility of sulfur dioxide, $Ca(HSO_3)_2$ solutions, 0607-07
Sulfur burner gas strength volume, 0607-01
Viscosities of various spent sulfite liquors at 26.7°C, 0607-22
Doctor blades
Ink metering systems for corrugated flexo presses, 0306-09
Overview of the selection process for a laser engraved ceramic anilox roll, 0306-17
Documentation
Press fabric record book, 0404-21
Suggestions for developing a box plant quality manual, 0304-49
Documents
Purchase order, 0305-07
Doublefacers
Impact of doublebacker hot plate level on board quality and how to measure it, 0304-66
Splicer defects and cures, 0304-31
Doublewall corrugated boards
Causes and corrections of common corrugator bonding problems, 0304-32
Downtime

The need for planned maintenance, 0305-30
Drainage
Drainage evaluation by mass measurement, 0502-12
Fourdrinier drainage performance evaluation – blow test method, 0410-07
High vacuum sheet dewatering, 0404-60
Interconversion of freeness, 0809-01
Drainage factor
Interconversion of freeness, 0809-01
Dry bulb temperature
Relative humidity tables, 0808-06
Dry ends
Procedure for setting up a raw material trial on the corrugator, 0304-01
Dryer bars
see Dryers
Dryer condensing rates
see Dryers
Dryer felts
see also Felts
Dryer fabric cleaning, 0404-38
Recommended tensions in dryer fabrics, 0404-04
Dryer hoods
see Exhaust hoods
Dryer pockets
Recommended minimum dryer pocket air requirements, 0404-17
Troubleshooting cross-machine direction moisture profile problems, 0404-57
Dryer sections
Performance of, 0404-33
Guidelines for the design, operation, performance evaluation, and troubleshooting of a paper machine hood and air systems, 0404-24
Sheet handling devices, 0404-44
Dryers
Application of dryer bars, 0404-35
Dryer condensing rates (batch method), 0404-02
Dryer condensing rates (continuous method), 0404-03
Dryer condensing rates (vertical separator method), 0404-18
Dryer fabric cleaning, 0404-38
Dryer section performance monitoring, 0404-33
Dryer surface temperature measurement, 0404-39
Drying and curing techniques for in-line flexographic printing, 0306-06
Guide for increasing the maximum allowable working pressure of cast iron, ASME constructed paper machine dryers, 0420-14
Guidelines for inspection and nondestructive testing of paper machine dryers, 0402-16
High-velocity dryers, 0404-05
Inspection guidelines for Yankee hood systems, 0425-02
Paper machine drying rate, 0404-07
Papermaker's formulas, 0502-17
Press fabric record book, 0404-21
Recommended dryer differential pressures, 0404-31
Recommended minimum dryer pocket air requirements, 0404-17
Guidelines for the design, operation, performance evaluation, and troubleshooting of a paper machine hood and air systems, 0404-24
Recommended tensions in dryer fabrics, 0404-04
Steam shower applications in the forming section, 0404-58
Troubleshooting cross-machine direction moisture profile problems, 0404-57
Yankee dryer steam condensing rates, 0404-49
Drying
Dryer condensing rates (continuous method), 0404-03
Dryer condensing rates (vertical separator method), 0404-18
Dryer section performance monitoring, 0404-33
Drying and curing techniques for in-line flexographic printing, 0306-06
Paper machine drying rate, 0404-07
Through drying, 0404-25
Drying rate
see Drying
Dry-laid nonwovens
Pilot paper machines, 0502-16
Duplex stainless steel
see Stainless steel
Dust
Paper machine room ventilation guidelines, 0404-50

E-
Economics
Press section economic evaluation, 0404-22
Economizers
Guideline specification for procurement of an economizer for a recovery boiler, 0416-21
Guidelines for operating and maintenance practices impacting an economizer on a recovery boiler, 0416-22
Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03
Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14
Edge crush tests (ECT)
Calibration of flexible beam crush tester, 0304-20
Edge crush test (ECT): its relationship to box compression and its derivation from containerboard edge stiffness, 0304-09
Efficiency
Paper machine performance guidelines, 0404-47
Press section monitoring, 0404-19
Recovery boiler energy efficiency improvements, 0416-16
Water treatment-related opportunities for energy conservation in a paper mill powerhouse, 0416-13
Elliptical technique
Guideline for obtaining high quality radiographic testing of butt welds in boiler tubes, 0402-33
Emissions
Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25
Employee injuries

see Human factors
Energy
Energy checklist: pulp mill, 0416-24
Paper machine energy conservation, 0404-63
Recovery boiler energy efficiency improvements, 0416-16
Water treatment-related opportunities for energy conservation in a paper mill powerhouse, 0416-13
Energy conservation
Paper machine room ventilation guidelines, 0404-50
Guidelines for the design, operation, performance evaluation, and troubleshooting of a paper machine hood and air systems, 0404-24
Enthalpy
Relative enthalpy (heat content) of sodium hydroxide solutions, 0606-08
Environmental factors
see Environments
Environments
Caustic soda (NaOH) safe storage and handling, 0606-27
Chlorine dioxide (ClO_2) safe storage and handling, 0606-30
Gaseous ozone (O_3) safe handling, 0606-28
Hydrogen peroxide (H_2O_2) safe storage and handling, 0606-24
Methanol (CH_3OH) safe storage and handling, 0606-25
Oxygen (O_2) bulk storage and safe handling, 0606-29
Sodium chlorate ($NaClO_3$) safe handling and storage, 0606-31
Sulfuric acid (H_2SO_4) safe storage and handling, 0606-26
Equations
Papermaker's formulas, 0502-17
Equilibrium
Relative humidities over saturated salt solutions, 0808-03
Equipment
Starch adhesive trial, 0304-22
Quality techniques using existing equipment, 0306-11
Ergonomics
see Human factors
Erosion
Nozzle maintenance and clogging, 0420-15
Evaluation
see also Performance
Drainage evaluation by mass measurement, 0502-12
Evaporation
see also Drying
Guidelines for the design, operation, performance evaluation, and troubleshooting of a paper machine hood and air systems, 0404-24
Evaporators
Energy checklist: pulp mill, 0416-24
Recommended test procedure for black liquor evaporators, 0416-11
Exhaust gas
Paper machine room ventilation guidelines, 0404-50
Collection and burning of concentrated noncondensible gases: regulations, design and operation, 0416-09
Exhaust hoods
Guidelines for the design, operation, performance evaluation, and troubleshooting of a paper machine hood and air systems, 0404-24
Extrusion coating
Guidelines for web conveyance and winding tension levels, 0200-01

F-
Fabric
See also Forming fabrics, Dryer felts
Paper machine clothing performance analysis, 0404-26
Fan pumps
Headbox approach piping guidelines, 0404-54
Feed section
see Feeding
Feedback control
see Control systems
Feeders
Material handling considerations for flexo folder gluers, 0305-54
Feedwater
Best practice guidelines for detecting and mitigating waterside cracking (stress-assisted corrosion) in power and recovery boilers, 0402-38
Design engineer decisions tree: paper mill boiler feedwater, 0416-04
Evaluating reverse osmosis for treating makeup to the boiler feedwater in a pulp and paper mill, 0416-07
Response to contamination of high purity boiler feedwater, 0416-05
Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03
Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14
Felts
see also Press felts
Dryer fabric cleaning, 0404-38
Methods to minimize sheet rewet in the press section, 0404-59
Porosity measurement of press felts on the paper machine (HSPT), 0404-29
Press fabric record book, 0404-21
Troubleshooting cross-machine direction moisture profile problems, 0404-57
Water permeability of press fabrics, 0404-43

Fiber length
Cotton in nonwovens, 1205-02
Fiberboards
see Boxes, Corrugated boards
Fiberglass-reinforced plastic
see Plastic
Field tests
see Test methods
Film
Guidelines for web conveyance and winding tension levels, 0200-01
Quality techniques using existing equipment, 0306-11
Filters
Paper machine room ventilation guidelines, 0404-50
Fine papers
Paper machine drying rate, 0404-07
Paper machine performance guidelines, 0404-47
Fingerless singlefacers
see Singlefacers
Fingerprints
Quality techniques using existing equipment, 0306-11
Flaps
Squaring flap cut (center special) boxes, 0305-45
Understanding and troubleshooting hot melt adhesives, 0304-74
Flat boxes
see Vacuum boxes
Flat crush tests
Calibration of flexible beam crush tester, 0304-20
Flexibility
Calibration of flexible beam crush tester, 0304-20
Flexible beam crush tester
Calibration of flexible beam crush tester, 0304-20
Felexible packaging
Guidelines for web conveyance and winding tension levels, 0200-01
Flexo folder-gluers
see Folder gluers, Die cutters, Rotary machines
Flexo ink
Printing section, 0305-38
Flexography
Cleaning anilox rolls: procedures and options, 0306-18
Guide to proper wipe roll selection for the corrugated box industry, 0306-20
Identifying anilox roll volume measuring equipment, 0306-15
Ink metering systems for corrugated flexo presses, 0306-09
Quality techniques using existing equipment, 0306-11
Overview of the selection process for a laser engraved ceramic anilox roll, 0306-17
Viscosity reading procedure for flexographic corrugated inks, 0304-18
Flow
Generalized method for determining the pipe friction loss of lowing pulp suspensions, 0410-14
Guidelines for detection, monitoring and prevention of flow accelerated corrosion (FAC) in the pulp and paper mill, 0402-36
Paper machine shower recommendations, 0404-61
Flow charts
Introduction to the flow chart, 0305-26
Flow measurement
Flow determination by chemical method, 0410-09
Weirs and flumes, 0410-10
Flow rates
see Flow measurement
Flumes
Weirs and flumes, 0410-10
Fluoropolymers
Fluoropolymer properties and applications in pulp and paper mills, 0402-37
Flutes
An alternative method for designating flute sizes, 0302-04
Fogging
Steam shower applications in the forming section, 0404-58
Folder gluers
Buying, storing, and handling flexo folder gluer/rotary diecutter adhesives, 0305-25
Cleanup procedures for flexo folder gluer/rotary diecutters, 0305-33
Counter ejector section, 0305-44
Extruded glue mechanism supplement, 0305-43
Folding section, 0305-42
Introduction to flexo folder gluer/rotary diecutter TIPs, 0305-04
Installation, 0305-12
Machinery considerations and selection: yoked scoring slotting section, 0305-53
Material handling considerations for flexo folder gluers, 0305-54
Computer assisted mounting systems, 0306-02
Project leader, 0305-13
Proper use of pull bands, 0305-18
Reduction or elimination of ink and/or varnish smear when printing and rotary die cutting in one pass, 0305-40
Squaring flap cut (center special) boxes, 0305-45
Folding
Folding section, 0305-42
Formaldehyde
Understanding formaldehyde management, 0304-25
Formation
Dandy roll applications, 0404-53
Forming
Forming section monitoring, 0502-14
Paper machine shower recommendations, 0404-61
Steam shower applications in the forming section, 0404-58
Forming fabrics
Drainage evaluation by mass measurement, 0502-12
Forming section monitoring, 0502-14
Methods to minimize sheet rewet in the press section, 0404-59

Paper machine clothing cleaning and conditioning for recycled fiber use, 0404-51
Paper machine vacuum selection factors, 0502-01
Press fabric dewatering and conditioning – suction box (Uhle box) design and vacuum requirements. 0404-27
Use of ceramics on the forming section: diagnosing and preventing forming fabric wear, 0502-19
Water permeability of press fabrics, 0404-43
Forming sections
Fourdrinier drainage performance evaluation – blow test method, 0410-07
Troubleshooting cross-machine direction moisture profile problems, 0404-57
Fossil fuels
Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25
Fourdrinier machines
Control of stock activity on a fourdrinier table, 0410-08
Drainage performance evaluation – blow test method, 0410-07
Papermaker's formulas, 0502-17
Free sheet
Paper machine drying rate, 0404-07
Freeness
Interconversion of, 0809-01
Friction
Generalized method for determining the pipe friction loss of lowing pulp suspensions, 0410-14
Friction factor
Statistical process control friction - slide angle, 0304-34
Fuel oil
Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25
Furnaces
see Recovery furnaces

G-
Gas
Collection and burning of concentrated noncondensible gases: regulations, design and operation, 0416-09
Gauges
see Measuring instruments
Gel temperature
see Gels
Gelatinization temperature
see Gels
Gels
Some questions and answers on gel temperatures and on the gel temperature test for corrugating adhesives, 0304-08
Statistical process control of starch gelatinization temperature, 0304-14
Gin motes
see Cotton
Ginning
see Cotton
Glass fibers
Guidelines for inspecting used fiber-reinforced plastics (FRP) equipment, 0402-28
Glossaries
see Nomenclature
Glue
Evaluating glue lap adhesive properties, 0304-16
Extruded glue mechanism supplement, 0305-43
Folding section, 0305-42
Glue lap
see Glued joints
Glue machine
see Gluers
Glue pattern
see Gluing
Glued joints
Troubleshooting a glue lap problem, 0304-10
Gluers
Causes and corrections of common corrugator bonding problems, 0304-32
How to prevent score cracking in a box plant, 0304-37
Improved techniques to measure corrugator glue machine meter gaps, 0304-68
Procedure for setting up a raw material trial on the corrugator, 0304-01
Some questions and answers on gel temperatures and on the gel temperature test for corrugating adhesives, 0304-08
Troubleshooting a glue lap problem, 0304-10
Gluing
Addendum to *Corrugating Defect Terminology Manual* - defects related to the use of fingerless singlefacers, 0304-17
Gluing machines
see Gluers
Grab truck
see Lift trucks
Granite
Roll material and surface requirements, 0404-41
Green liquors
Recausticizing material balance equations relating to digester requirements, 0418-02
Grinders
Grinder pulpstones – cubical contents, 0605-01
Pulpstone speed chart, 0605-02
Grinding
Granite roll material and surface requirements, 0404-41
Grooved rolls
Press roll cover application guidelines, 0404-37
Ground calcium carbonate (GCC)
see Calcium carbonate
Guides
Press fabric guiding, 0404-64
Guide rolls
Press fabric guiding, 0404-64

H-
Halogens
see specific term, e.g., Chlorine
Hardness
Response to contamination of high purity boiler feedwater, 0416-05
Water quality guidelines and monitoring requirements for

paper mill boilers operating with softened makeup water, 0416-14
Hazards
Corrugated boxplant-list of potential hazards, 0301-01
Material safety data sheets, what to look for - how to understand them, 0304-38
Hazardous materials
Collection and burning of concentrated noncondensible gases: regulations, design and operation, 0416-09
Formaldehyde management, 0304-25
Material safety data sheets – what to look for, how to understand them, 0304-38
Stripping of kraft pulping process condensates: regulations, design and operation, 0416-10
Understanding hazardous materials warning labels, 0304-41
Headboxes
Flow from a 45° slice, 0410-03
Flow from a nozzle (slice) with inclined upper lip, 0410-04
Flow from a vertical slice, 0410-02
Head of stock behind slice (head/jet relationships), 0410-05
Papermaker's formulas, 0502-17
Heat
Paper machine room ventilation guidelines, 0404-50
Heat content
see Enthalpy
Heat of vaporization
Liquid chlorine, 0606-04
Heat recovery
Paper machine room ventilation guidelines, 0404-50
Heat transfer
Application of dryer bars, 0404-35
Recommended test procedure for black liquor evaporators, 0416-11
Heat transfer coefficient
Recommended test procedure for black liquor evaporators, 0416-11
Heating
Conducting a corrugator temperature audit, 0304-65
Heating equipment
Steam shower applications in the forming section, 0404-58
Heavy metals
see Metals
High density
High density liners…what are they?, 0304-43
High density liners
see Liners
High intensity presses
Terminology for high temperature pressing, 0404-48
High performance liners
see Liners
High temperature
Terminology for high temperature pressing, 0404-48
High vacuum
High vacuum sheet dewatering, 0404-60
Hoods
Inspection guidelines for Yankee hood systems, 0425-02
Guidelines for the design, operation, performance evaluation, and troubleshooting of a paper machine hood and air systems, 0404-24
Hot melts
Understanding and troubleshooting hot melt adhesives, 0304-74
Hot pressing
Terminology for high temperature pressing, 0404-48
Housekeeping
see Maintenance, Cleaning
Humidity
Dryer section performance monitoring, 0404-33
Equilibrium relative humidities over saturated salt solutions, 0808-03
Psychrometric charts, 0404-45
Recommended minimum dryer pocket air requirements, 0404-17
Guidelines for the design, operation, performance evaluation, and troubleshooting of a paper machine hood and air systems, 0404-24
Relative humidity tables, 0808-06
Testing atmospheres simulating end use conditions, 0808-05
Troubleshooting cross-machine direction moisture profile problems, 0404-57
Humidity measurement
Relative humidity tables, 0808-06
Humidity rooms
Paper test rooms: design considerations, 0808-04
Hydrocyclones
Introduction to centrifugal cleaners, 0508-10
Hydrogen peroxide
Hydrogen peroxide (H_2O_2) safe storage and handling, 0606-24
Hydroxides
Definitions of terms in the sulfite pulping process, 0607-25
Density of aqueous sodium sulfite solution, 0607-18
Density of milk of lime solution, 0607-05
Solubility of sulfur dioxide, $Ca(HSO_3)_2$ solutions, 0607-07
Sulfur burner gas strength volume, 0607-01
Hypochlorite bleaching
see Hypochlorites, Bleaching

I-
Illumination
Basic guidelines for image analysis measurements, 0804-09
Image analysis
Basic guidelines for image analysis measurements, 0804-09
Image quality
Guideline for obtaining high quality radiographic testing of butt welds in boiler tubes, 0402-33

Impregnation
Guidelines for inspection of continuous digesters and impregnation vessels, 0402-27
Impulse drying
see Drying
Impurities
Dryer fabric cleaning, 0404-38
Paper machine clothing cleaning and conditioning for recycled fiber use, 0404-51
Stickies definition and classification, 0603-02
In-process checklist
see Production
Infiltration
Paper machine room ventilation guidelines, 0404-50
Infrared detectors
Troubleshooting cross-machine direction moisture profile problems, 0404-57
Infrared dryers
Drying and curing techniques for in-line flexographic printing, 0306-06
Ink
Copper in a printing ink, 0304-61
Guideline for direct contact printing of bar code symbols on corrugated, 0306-16
Ink metering systems for corrugated flexo presses, 0306-09
Proofing a flexo printing ink, 0304-60
Quality parameters of a printing ink, 0304-59
Quality techniques using existing equipment, 0306-11
Reduction or elimination of ink and/or varnish smear when printing and rotary die cutting in one pass, 0305-40
Viscosity reading procedure for flexographic corrugated inks, 0304-18
Inorganic salts
Equilibrium relative humidities over saturated salt solutions, 0808-03
Inspection
Guidelines for inspecting batch digesters, 0402-22
Guidelines for detection, monitoring and prevention of flow accelerated corrosion (FAC) in the pulp and paper mill, 0402-36
Guidelines for inspection and nondestructive testing of paper machine dryers, 0402-16
Guidelines for routine periodic inspection and testing of cast iron Yankee and MG dryers, 0425-01
Guidelines for specification and inspection of electric resistance welded (ERW) and seamless boiler tube for critical and noncritical service, 0402-13
Inspecting used fiber-reinforced plastics (FRP) equipment, 0402-28
Inspection for cracking of composite tubes in black liquor recovery boilers, 0402-30
Inspection of continuous digesters and impregnation vessels, 0402-27
Inspection guidelines for Yankee hood systems, 0425-02
Nondestructive examination of suction roll shells, 0402-19
Paper machine reel-spool journals: guidelines for crack testing and repair or replacement, 0402-34
Ultrasonic technician performance test for boiler tube inspection, 0402-21
Ultrasonic testing (UT) for tube thickness in black liquor recovery boilers, 0402-18
Best Practice for Recovery Boiler Inspection (Optimizing Inspection Scope), 0416-26
Installation
Flexo folder gluers, 0305-12
Project leader, 0305-13
Press section monitoring, 0404-19
Instruments
Forming section monitoring, 0502-14
Intensity
Conical refining intensity, 0508-07
Internal bond strength
Troubleshooting a glue lap problem, 0304-10
Iron
Response to contamination of high purity boiler feedwater, 0416-05
Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03
Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

J-
Jet dryers
Methods of evaluating high velocity dryers, 0404-05
Jet velocity
Head of stock behind slice (head/jet relationship), 0410-05
Jets
Flow from a 45° slice, 0410-03
Flow from a nozzle (slice) with inclined upper lip, 0410-04
Flow from a vertical slice, 0410-02
Joints
Troubleshooting a glue lap problem, 0304-10
Jordans
see Conical refiners
Jumbo rolls
Reel diameter for various reel spool and roll core sizes, 0502-03

K-
Kaolin
Kaolin clay pigment index, 0106-06
Kraft papers
Paper machine drying rate, 0404-07
Kraft pulping
Stripping of kraft pulping process condensates: regulations, design and operation, 0416-10

L-
Labels
Understanding hazardous materials warning labels, 0304-41

Laboratories
Paper test rooms: design considerations, 0808-04
Laminates
Guidelines for web conveyance and winding tension levels, 0200-01
Lead
An explanation of the CONEG heavy metal guidelines, 0304-58
Leakage
Collection and burning of concentrated noncondensible gases: regulations, design and operation, 0416-09
Explanation of recovery boiler leak indications, 0416-23
Lignosulfonates
Boiling point rise of spent sulfite liquors, 0607-21
Definitions of terms in the sulfite pulping process, 0607-25
Density of aqueous sodium sulfite solution, 0607-18
Density of milk of lime solution, 0607-05
Solubility of sulfur dioxide, $Ca(HSO_3)_2$ solutions, 0607-07
Sulfur burner gas strength volume, 0607-01
Viscosities of various spent sulfite liquors at 26.7°C, 0607-22
Lime mud
see White liquor mud
Lime reburning
Energy checklist: pulp mill, 0416-24
Lime-base solutions
see Calcium base liquors
Linerboards
Paper machine drying rate, 0404-07
Liners
Causes and corrections of common corrugator bonding problems, 0304-32
Edge crush test (ECT): its relationship to box compression and its derivation from containerboard edge stiffness, 0304-09
High density liners…what are they?, 0304-43
How to minimize rolling scores on lightweight and high-performance liners in diecutting operations, 0304-64
Paper machine performance guidelines, 0404-47
Procedure for setting up a raw material trial on the corrugator, 0304-01
Splicer defects and cures, 0304-31
Techniques for bonding of densified liners, 0304-40
Linters
Cotton in nonwovens, 1205-02

M-
Machine clothing
Paper machine clothing cleaning and conditioning for recycled fiber use, 0404-51
Paper machine clothing performance analysis, 0404-26
Machine direction
Calculation and partitioning of variance using paper machine scanning sensor measurements, 1101-01
Machine operation
see also Maintenance
Project leader, 0305-13
Machine rooms
Paper machine room ventilation guidelines, 0404-50
Machine speed
Pulpstone speed chart, 0605-02
Machinery
Computer-assisted machinery, 0305-02
Machinery considerations and selection, 0305-06
Project leader, 0305-13
Magnesia
see Magnesium oxide
Magnesium bisulfite
Solubility of sulfur dioxide in saturated magnesium bisulfite solution, 0607-10
Magnesium bisulfite liquor
see Magnesium base liquors
Magnesium oxide
Physical and chemical properties of magnesia-base pulping solutions, 0607-04
Solubility of sulfur dioxide in magnesium bisulfite solution, 0607-09
Maintenance
Burst testers, 0304-24
Calibration and maintenance of the manually operated micrometer, 0304-30
Checking for coating wear on corrugating rolls, 0304-73
Checking the flute depth of corrugating rolls, 0304-75
Checking the parallel of corrugating rolls with "NCR" paper, 0304-62
Cleaning anilox rolls: procedures and options, 0306-18
Cleanup procedures for flexo folder gluer/rotary diecutters, 0305-33
Computer-assisted machinery, 0305-02
Counter ejector section, 0305-44
Daily, weekly, and monthly maintenance checklists, 0305-34
Extruded glue mechanism supplement, 0305-43
Field welding of pin studs in black liquor recovery boilers, 0402-15
Guidelines for operating and maintenance practices impacting an economizer on a recovery boiler, 0416-22
Housekeeping at order and shift change and weekly, 0305-32
Need for planned maintenance, 0305-30
Nozzle maintenance and clogging, 0420-15
Rotary cutting die maintenance, 0305-23
Rotary diecutter urethane anvil maintenance, 0305-35
Tests for corrugator roll wear, 0304-53
Troubleshooting a glue lap problem, 0304-10
Weld repairs on new suction roll shells, 0402-17
Management
Project leader, 0305-13

Manuals
Suggestions for developing a box plant quality manual, 0304-49
Manufacturers joints
Evaluating glue lap adhesive properties, 0304-16
Folding section, 0305-42
Go/no go gauge devices for the boxplant, 0304-42
Mass
Drainage evaluation by mass measurement, 0502-12
Material safety data sheets
see Safety
Materials
Oxygen (O_2) bulk storage and safe handling, 0606-29
Materials balance
Paper machine room ventilation guidelines, 0404-50
Materials handling
Caustic soda (NaOH) safe storage and handling, 0606-27
Gaseous ozone (O_3) safe handling, 0606-28
Hydrogen peroxide (H_2O_2) safe storage and handling, 0606-24
Material safety data sheets – what to look for, how to understand them, 0304-38
Methanol (CH_3OH) safe storage and handling, 0606-25
Oxygen (O_2) bulk storage and safe handling, 0606-29
McKee equation
see Edge crush tests
Measurement
Conducting a corrugator temperature audit, 0304-65
Drainage evaluation by mass measurement, 0502-12
Dryer condensing rates (batch method), 0404-02
Dryer condensing rates (continuous method), 0404-03
Troubleshooting cross-machine direction moisture profile problems, 0404-57
Units of and conversion factors, 0800-01
Utilizing statistical process control techniques to assist in meeting specification at finishing crush process control points to the paper and paperboard industries, 0304-11
Measuring instruments
Gauge repeatability and reproducibility study, 0304-71
Mechanical papers
Paper machine drying rate, 0404-07
Medium
see Corrugating medium
Melting point
Estimating the first melting temperature of fireside deposits in recovery boilers, 0416-12
Mercury
CONEG heavy metal guidelines, 0304-58
Metals
An explanation of the CONEG heavy metal guidelines, 0304-58
Field welding of pin studs in black liquor recovery boilers, 0402-15
Metering equipment
Ink metering systems for corrugated flexo presses, 0306-09
Methanol
Methanol (CH_3OH) safe storage and handling, 0606-25
Collection and burning of concentrated noncondensible gases: regulations, design and operation, 0416-09
Stripping of kraft pulping process condensates: regulations, design and operation, 0416-10
Microbes
see Bacteria
Micrometers
Calibration and maintenance of the manually operated micrometer, 0304-30
Milk of lime solution
see Calcium hydroxide
Moisture
Determination of water removal by wet presses, 0404-01
Moisture content of paper: terminology and conversion, 0808-02
Steam shower applications in the forming section, 0404-58
Moisture content
Determination of water removal by wet presses, 0404-01
Psychrometric charts, 0404-45
Troubleshooting cross-machine direction moisture profile problems, 0404-57
Moisture control
Cotton in nonwovens, 1205-02
Troubleshooting cross-machine direction moisture profile problems, 0404-57
Warp in corrugated board, 0304-07
Moisture regain
see Moisture content, Sorption
Monitoring
Press section monitoring, 0404-19
Monitors
Forming section monitoring, 0502-14
Paper test rooms: design considerations, 0808-04
Monosulfite
see Neutral sulfite pulping
Motors
Paper machine room ventilation guidelines, 0404-50
Mounting
Computer assisted mounting systems, 0306-02
Mullen
see Burst strength
Multistage process
see Bleaching

N-
Natrual gas
Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25
Needle punched
see Needling
Needling
Cotton in nonwovens, 1205-02
Neutral sulfite liquors
Viscosity of a neutral sulfite spent liquor (Ostwald capillary viscometer), 0607-23
Neutral sulfite pulping
Boiling point rise of spent sulfite liquors, 0607-21

Definitions of terms in the sulfite pulping process, 0607-25
Density of aqueous sodium sulfite solution, 0607-18
Density of milk of lime solution, 0607-05
Physical and chemical properties of magnesia-base pulping solutions, 0607-04
Solubility of sulfur dioxide, 0607-06
Solubility of sulfur dioxide, $Ca(HSO_3)_2$ solutions, 0607-07
Solubility of sulfur dioxide in magnesium bisulfite solution, 0607-09
Sulfur burner gas strength volume, 0607-01
Viscosities of various spent sulfite liquors at 26.7°C, 0607-22

Newsprint
Paper machine drying rate, 0404-07
Paper machine performance guidelines, 0404-47
Weight of newsprint rolls, 0502-11

Nip
Methods to minimize sheet rewet in the press section, 0404-59
Techniques for nip impressions, 0404-46
Troubleshooting cross-machine direction moisture profile problems, 0404-57

Nip pressure
see Nip

Nitrogen oxides
Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25

Nomenclature
Recommended pulp bleaching stage designation method, 0606-21
Retention definitions, 0402-13
Moisture content of paper: terminology and conversion, 0808-02
Sulfite pulping process, 0607-25
Terminology for high temperature pressing, 0404-48

Noncondensibles
Collection and burning of concentrated noncondensible gases: regulations, design and operation, 0416-09

Nondestructive tests
Best practice guidelines for detecting and mitigating waterside cracking (stress-assisted corrosion) in power and recovery boilers, 0402-38
Guide to the use of stainless steel pipe specifications, 0402-24
Guidelines for corrosion resistant weld metal overlay of digester vessels in alkaline pulping service, 0402-03
Guidelines for inspection and nondestructive testing of paper machine dryers, 0402-16
Guidelines for specification and inspection of electric resistance welded (ERW) and seamless boiler tube for critical and noncritical service, 0402-13
Drainage evaluation by mass measurement, 0502-12
Guidelines for evaluating quality of boiler tube butt welds with ultrasonic testing, 0402-31
Inspection for cracking of composite tubes in black liquor recovery boilers, 0402-30
Inspection of continuous digesters and impregnation vessels, 0402-27
Liquid penetrant testing of new suction roll shells, 0402-11
Nondestructive examination of suction roll shells, 0402-19
Paper machine reel-spool journals: guidelines for crack testing and repair or replacement, 0402-34
Ultrasonic technician performance test for boiler tube inspection, 0402-21
Ultrasonic testing (UT) for tube thickness in black liquor recovery boilers, 0402-18

Nonwood fibers
Catalog of stock prep pilot plants, 0502-20

Nonwovens
Cotton in, 1205-02
Pilot paper machines, 0502-16

Nonwovens machines
Pilot paper machines, 0502-16

Nozzles
Nozzle maintenance and clogging, 0420-15
Paper machine shower recommendations, 0404-61

NSSC pulping
Viscosity of a neutral sulfite spent liquor (Ostwald capillary viscometer), 0607-23

O-

Opacifiers
Physical data of calcium carbonate-water suspensions, 0106-01

Open time
Troubleshooting a glue lap problem, 0304-10

Openings
Measurement of vacuum pump air flow, 0420-12

Operations
Guidelines for operating and maintenance practices impacting an economizer on a recovery boiler, 0416-22
Machinery considerations and selection, 0305-06

Optical measurement
Basic guidelines for image analysis measurements, 0804-09

Optimization
Press section optimization, 0404-52

Orifices
see Openings

Osmosis
Evaluating reverse osmosis for treating makeup to the boiler feedwater in a pulp and paper mill, 0416-07

Overfire air
Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25

Overlays
Guidelines for corrosion resistant weld metal overlay of digester vessels in alkaline pulping service, 0402-03
Guidelines for inspecting batch digesters, 0402-22

Oxidation
Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25
Oxygen
Bulk storage and safe handling of, 0606-29
Ozone
Safe handling of gaseous, 0606-28
Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25

P-
Packaging
CONEG heavy metal guidelines, 0304-58
Understanding and troubleshooting hot melt adhesives, 0304-74
Palletization
Checklist: preparing die cuts for shipment, 0305-49
Material handling considerations for flexo folder gluers, 0305-54
Paper
Guidelines for web conveyance and winding tension levels, 0200-01
Moisture content of paper: terminology and conversion, 0808-02
Paper grade classifications, 0404-36
Through drying, 0404-25
Paper grades
Paper grade classifications, 0404-36
Paper machines
Guide for increasing the maximum allowable working pressure of cast iron, ASME constructed paper machine dryers, 0420-14
Guidelines for inspection and nondestructive testing of paper machine dryers, 0402-16
Guidelines for routine periodic inspection and testing of cast iron Yankee and MG dryers, 0425-01
Paper machine clothing performance analysis, 0404-26
Paper machine energy conservation, 0404-63
Paper machine performance guidelines, 0404-47
Paper machine reel-spool journals: guidelines for crack testing and repair or replacement, 0402-34
Papermaker's formulas, 0502-17
Performance evaluation techniques for paper machine vacuum systems, 0404-55
Pilot paper machines, 0502-16
Press section monitoring, 0404-19
Guidelines for the design, operation, performance evaluation, and troubleshooting of a paper machine hood and air systems, 0404-24
Water permeability of press fabrics, 0404-43
Paper mills
Design engineer decisions tree: paper mill boiler feedwater, 0416-04
Fluoropolymer properties and applications in pulp and paper mills, 0402-37
Paper rolls
see Rolls, Wound rolls
Paper stock
Guidelines for side-entering stock agitators, 0420-13
Paperboard
Guidelines for web conveyance and winding tension levels, 0200-01
Papermakers alum
see Aluminum sulfate
Paraffin wax
Common curtain coating problems: causes, detection, and correction, 0304-26
Papermaking
Papermaker's formulas, 0502-17
Parallelism
see Alignment
Parameters
Paper machine performance guidelines, 0404-47
Penetrants
Liquid penetrant testing of new suction roll shells, 0402-11
Performance
Dryer section performance monitoring, 0404-33
Paper machine clothing performance analysis, 0404-26
Paper machine room ventilation guidelines, 0404-50
Press fabric record book, 0404-21
Press section economic evaluation, 0404-22
Press section optimization, 0404-52
Recovery boiler performance calculation – short form, 0416-01
Performance evaluation
Methods of evaluating high velocity dryers, 0404-05
Paper machine performance guidelines, 0404-47
Performance evaluation techniques for paper machine vacuum systems, 0404-55
Performance tests
Performance test procedure for boilers using biomass as fuel, 0416-18
Sampling procedures for biomass fuel for boiler performance testing, 0416-17
Ultrasonic technician performance test for boiler tube inspection, 0402-21
Permeability
Water permeability of press fabrics, 0404-43
Personnel
Project leader, 0305-13
Petroleum wax
see Paraffin wax
pH
Response to contamination of high purity boiler feedwater, 0416-05
Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03
Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14
Phosphates
Water quality and monitoring requirements for paper mill

boilers operating on high purity feedwater, 0416-03
Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14
Physical properties
Chlorine dioxide (ClO2) safe storage and handling, 0606-30
Chlorine gas curve, 0606-02
Density of chlorine gas, 0606-03
Heat of vaporization of liquid chlorine, 0606-04
Magnesia-base pulping solutions, 0607-04
Relative enthalpy (heat content) of sodium hydroxide solutions, 0606-08
Sodium chlorate ($NaClO_3$) safe handling and storage, 0606-31
Specific gravity and density of caustic soda solutions, 0606-20
Specific gravity of sodium chloride solutions, 0606-10
Viscosity of liquid chlorine, 0606-05
Viscosity of sodium hydroxide solutions, 0606-11
Pigment
Kaolin clay pigment index, 0106-06
Physical data of calcium carbonate-water suspensions, 0106-01
Pilot paper machines
see Paper machines
Pilot plants
Catalog of stock prep pilot plants, 0502-20
Pilot paper machines, 0502-16
Pin adhesion tests
Statistical process control pin adhesion, 0304-23
Pin register
see Register
Pin register mounting
see Register, Mounting
Pin studs
see Welding
Pipelines
Optimum consistency for pumping pulp, 0410-15
Piping
Guidelines for detection, monitoring and prevention of flow accelerated corrosion (FAC) in the pulp and paper mill, 0402-36
Generalized method for determining the pipe friction loss of lowing pulp suspensions, 0410-14
Guide to the use of stainless steel pipe specifications, 0402-24
Headbox approach piping guidelines, 0404-54
Planning
Checklist for a properly planned project, 0408-01
Installation, 0305-12
Project leader, 0305-13
Plastics
Guidelines for inspecting used fiber-reinforced plastics (FRP) equipment, 0402-28
Refiner systems, their inspection and maintenance, 0508-06
Plates
see also Printing plates, Refiner disks
Conducting a corrugator temperature audit, 0304-65
Impact of doublebacker hot plate level on board quality and how to measure it, 0304-66
Plugging
Estimating the first melting temperature of fireside deposits in recovery boilers, 0416-12
Pocket humidity
see Humidity
Polymers
Guidelines for web conveyance and winding tension levels, 0200-01
Polyurethanes
Press roll cover application guidelines, 0404-37
Porosity
Porosity measurement of press felts on the paper machine (HSPT), 0404-29
Water permeability of press fabrics, 0404-43
Potassium
Chloride and potassium measurement and control in the pulping and chemical recovery cycle, 0416-15
Estimating the first melting temperature of fireside deposits in recovery boilers, 0416-12
Power plants
Water treatment-related opportunities for energy conservation in a paper mill powerhouse, 0416-13
Precipitated calcium carbonate (PCC)
see Calcium carbonate
Precipitators
Chloride and potassium measurement and control in the pulping and chemical recovery cycle, 0416-15
Estimating the first melting temperature of fireside deposits in recovery boilers, 0416-12
Prefeeder
see Feeders
Preservatives
Starch adhesive preparation and distribution systems: housekeeping, 0304-06
Press
Methods to minimize sheet rewet in the press section, 0404-59
Multiple-out rotary diecut stacking, 0305-47
Stacking off the rotary diecutter, 0305-46
Press drying
see also Drying
Terminology for high temperature pressing, 0404-48
Press fabrics
Press fabric guiding, 0404-64
Dewatering and conditioning – suction box (Uhle box) design and vacuum requirements, 0404-27
Press felts
see also Felts
Physical characterization of press fabrics: basis weight, air permeability, void volume under loading and pressure uniformity, 0404-20
Porosity measurement of press felts on the paper machine (HSPT), 0404-29

Press fabric guiding, 0404-64
Press fabric record book, 0404-21
Thickness of wet press fabrics, 0404-28
Water permeability of press fabrics, 0404-43
Press rolls
Granite roll material and surface requirements, 0404-41
Press roll cover application guidelines, 0404-37
Weld repairs on new suction roll shells, 0402-17
Press sections
Determination of water removal by wet presses, 0404-01
Press section economic evaluation, 0404-22
Press section monitoring, 0404-19
Press section optimization, 0404-52
Sheet handling devices, 0404-44
Steam shower applications in the forming and press section, 0404-58
Water permeability of press fabrics, 0404-43
Presses
Papermaker's formulas, 0502-17
Pressing
Physical characterization of press fabrics: basis weight, air permeability, void volume under loading and pressure uniformity, 0404-20
Methods to minimize sheet rewet in the press section, 0404-59
Paper machine shower recommendations, 0404-61
Pressure
Guide for increasing the maximum allowable working pressure of cast iron, ASME constructed paper machine dryers, 0420-14
Guidelines for routine periodic inspection and testing of cast iron Yankee and MG dryers, 0425-01
Techniques for nip impressions, 0404-46
Pressure gradient
Recommended dryer differential pressures, 0404-31
Pressure roll
Paper machine vacuum selection factors, 0502-01
Preventative maintenance
see Maintenance
Print section
Printing section, 0305-38
Printing
Copper in a printing ink, 0304-61
Guide to proper wipe roll selection for the corrugated box industry, 0306-20
Guideline for direct contact printing of bar code symbols on corrugated, 0306-16
Important quality parameters of a printing ink, 0304-59
In-process checklist, 0305-27
Proofing a flexo printing ink, 0304-60
Proper use of pull bands, 0305-18
Quality techniques using existing equipment, 0306-11
Reduction or elimination of ink and/or varnish smear when printing and rotary die cutting in one pass, 0305-40
Overview of the selection process for a laser engraved ceramic anilox roll, 0306-17
Printing cylinders
Cleaning anilox rolls: procedures and options, 0306-18
Identifying anilox roll volume measuring equipment, 0306-15
Overview of the selection process for a laser engraved ceramic anilox roll, 0306-17
Printing ink
see Ink
Printing papers
Paper machine drying rate, 0404-07
Printing plates
Guideline for direct contact printing of bar code symbols on corrugated, 0306-16
Computer assisted mounting systems, 0306-02
Quality techniques using existing equipment, 0306-11
Printing section, 0305-38
Printing proofs
Method to proof a flexo printing ink, 0304-60
Process control
Obtaining combined board caliper off the corrugator for use in statistical procedures, 0304-12
Short-run statistical process control: a basic charting method, 0304-70
Starch viscosity in corrugating adhesives, 0304-15
Statistical of starch gelatinization temperature, 0304-14
Statistical process control friction-slide angle, 0304-34
Statistical process control -- procedures for charting warp, 0304-13
Processes
In-process checklist, 0305-27
Introduction to the flow chart, 0305-26
Product codes
Guideline for direct contact printing of bar code symbols on corrugated, 0306-16
Production
In-process checklist, 0305-27
Papermaker's formulas, 0502-17
Production control
In-process checklist, 0305-27
Profiles
Troubleshooting cross-machine direction moisture profile problems, 0404-57
Steam shower applications in the forming section, 0404-58
Project planning
see Planning
Projects
see Planning
Protective coatings
Guidelines for thermal spray coatings installed to prevent corrosion in pulp mill process equipment, 0402-32
Psychrometric charts
see also Humidity
Psychrometric charts, 0404-45
Pull collars
Troubleshooting the diecutting section, 0305-39
Pull rolls
Printing section, 0305-38
Pulp mill equipment
Guidelines for thermal spray coatings installed to prevent

corrosion in pulp mill process equipment, 0402-32
Pulp mills
Energy checklist: pulp mill, 0416-24
Fluoropolymer properties and applications in pulp and paper mills, 0402-37
Pulpers
Catalog of stock prep pilot plants, 0502-20
Pulping
Density of chlorine gas, 0606-03
Pulpstones
Grinder pulpstones: cubical contents, 0605-01
Pulpstone speed chart, 0605-02
Pulps
Generalized method for determining the pipe friction loss of lowing pulp suspensions, 0410-14
Optimum consistency for pumping, 0410-15
Paper machine drying rate, 0404-07
Pumping
Generalized method for determining the pipe friction loss of lowing pulp suspensions, 0410-14
Pulp, optimum consistency for, 0410-15
Pumps
Guidelines for procurement of cast stainless steels for large pumps and valves for the pulp and paper industry, 0402-25
Purchase
Buying, storing, and handling flexo folder gluer/rotary diecutter adhesives, 0305-25
Purchase orders
Purchase order, 0305-07
Pyrometry
Dryer surface temperature measurement, 0404-39

Q-
Quality
Box plant quality measurement: why test?, 0304-02
Important quality parameters of a printing ink, 0304-59
Quality techniques using existing equipment, 0306-11
Starch adhesive trial, 0304-22
Suggestions for developing a box plant quality manual, 0304-49
Quality control
Calculation and partitioning of variance using paper machine scanning sensor measurements, 1101-01
Guideline for direct contact printing of bar code symbols on corrugated, 0306-16
Guidelines for specification and inspection of electric resistance welded (ERW) and seamless boiler tube for critical and noncritical service, 0402-13
Liquid penetrant testing of new suction roll shells, 0402-11
Quality manual
see Quality

R-
Radiography
Guideline for obtaining high quality radiographic testing of butt welds in boiler tubes, 0402-33
Raw materials
Procedure for setting up a raw material trial on the corrugator, 0304-01
Recausticizing
see Causticizing
Reclaimed fibers
Paper machine clothing cleaning and conditioning for recycled fiber use, 0404-51
Record books
see Documentation
Recovery
Energy checklist: pulp mill, 0416-24
Best Practice for Recovery Boiler Inspection (Optimizing Inspection Scope), 0416-26
Recovery boilers
Estimating the first melting temperature of fireside deposits in recovery boilers, 0416-12
Explanation of recovery boiler leak indications, 0416-23
Field welding of pin studs in black liquor recovery boilers, 0402-15
Guideline specification for procurement of an economizer for a recovery boiler, 0416-21
Guidelines for operating and maintenance practices impacting an economizer on a recovery boiler, 0416-22
Recovery boiler energy efficiency improvements, 0416-16
Recovery boiler performance calculation – short form, 0416-01
Recovery boiler sootblowers: practical guidelines, 0416-20
Recovery boiler sootblowers: the basics, 0416-19
Ultrasonic testing (UT) for tube thickness in black liquor recovery boilers, 0402-18
Recovery furnaces
Chloride and potassium measurement and control in the pulping and chemical recovery cycle, 0416-15
Explanation of recovery boiler leak indications, 0416-23
Field welding of pin studs in black liquor recovery boilers, 0402-15
Guidelines for replacement of generating bank tubes with expanded joints in two-drum boilers, 0416-08
Inspection for cracking of composite tubes in black liquor recovery boilers, 0402-30
Recovery boiler performance calculation – short form, 0416-01
Ultrasonic technician performance test for boiler tube inspection, 0402-21
Recycled fibers
see Reclaimed fibers
Recycled paperboard
Paper machine performance guidelines, 0404-47
Recycled papers
Paper machine performance guidelines, 0404-47
Recycling
Stickies definition and classification, 0603-02
Reels
Determination of winder sets per reel, 0502-02
Paper machine reel-spool journals: guidelines for crack testing and repair or replacement, 0402-34

Reel diameter for various reel spool and roll core sizes, 0502-03
TAPPI Roll number for inventory/tracking systems and bar codes, 1004-01
Refiner plates
see Refiner disks
Refiners
Catalog of stock prep pilot plants, 0502-20
Conical refining intensity, 0508-07
Refiner systems, their inspection and maintenance, 0508-06
Refining
Conical refining intensity, 0508-07
Refiner systems, their inspection and maintenance, 0508-06
Register
Computer assisted mounting systems, 0306-02
Regulating systems
see Control systems
Regulations
CONEG heavy metal guidelines, 0304-58
Relative enthalpy
see Enthalpy
Relative humidity
see Humidity
Relief
Water quality and monitoring requirements for paper mill boilers, operating on high purity feedwater, 0416-03
Removal
Chloride and potassium measurement and control in the pulping and chemical recovery cycle, 0416-15
Repair
see Maintenance
Repeatability
How to perform a gauge repeatability and reproducibility study, 0304-71
Reporting
Press fabric record book, 0404-21
Replacement
Guidelines for replacement of generating bank tubes with expanded joints in two-drum boilers, 0416-08
Reproducibility
How to perform a gauge repeatability and reproducibility study, 0304-71
Resolution
Basic guidelines for image analysis measurements, 0804-09
Retention
Definitions, 0502-13
Fourdrinier drainage performance evaluation – blow test method, 0410-07
Reverse osmosis
Evaluating reverse osmosis for treating makeup to the boiler feedwater in a pulp and paper mill, 0416-07
Reverse warp
see Warpage
Rewetting
Methods to minimize sheet rewet in the press section, 0404-59
Rider rolls
Total indicated runout and its impact on combined board quality, 0304-56
Ring crush resistance
Techniques for bonding of densified liners, 0304-40
Ring crush tests
Calibration of flexible beam crush tester, 0304-20
Techniques for bonding of densified liners, 0304-40
Rod coaters
see also Coaters
In-line coating at the corrugator, TIP 0304-39
Roll coaters
see also Coaters
In-line coating at the corrugator, TIP 0304-39
Roll core
see Cores
Roll crown
Techniques for nip impressions, 0404-46
Roll density
see Rolls
Roll handling
see Materials handling, Jumbo rolls
Roll identification
see Rolls
Roll length
see Rolls
Roll number
see Rolls
Roll stands
Splicer defects and cures, 0304-31
Roll tracking
see Rolls
Roll weight
see Rolls
Rolling contact bearings
see Bearings
Rolling scores
see Scores
Rolls
An alternative method for designating flute sizes, 0302-04
Checking the flute depth of corrugating rolls, 0304-75
Checking for coating wear on corrugating rolls, 0304-73
Corrugator temperature audit, 0304-65
Granite roll material and surface requirements, 0404-41
Parallel of corrugating rolls with “NCR” paper, 0304-62
Press roll cover application guidelines, 0404-37
TAPPI Roll number for inventory/tracking systems and bar codes, 1004-01
Techniques for nip impressions, 0404-46
Tests for corrugator roll wear, 0304-53
Total indicated runout and its impact on combined board quality, 0304-56
Weight of newsprint rolls, 0502-11
Rotary diecutter
see Rotary machines, Die cutters; see also Folder gluers
Rotary filters
Bleaching plant washer efficiency guide, 0606-23

Rotary machines
Buying, storing, and handling flexo folder gluer/rotary diecutter adhesives, 0305-25
Cleanup procedures for flexo folder gluer/rotary diecutters, 0305-33
Introduction to flexo folder gluer/rotary diecutter TIPs, 0305-04
Ordering cutting dies, 0305-21
Project leader, 0305-13
Proper use of pull bands, 0305-18
Rotary cutting die maintenance, 0305-23
Rotary diecutter urethane anvil maintenance, 0305-35
Rotation
Pulpstone speed chart, 0605-02
Roundness
see Shape
Rubbing
see also Abrasion resistance
Runnability
Sheet handling devices, 0404-44

S-
Safety
Caustic soda (NaOH) safe storage and handling, 0606-27
Chlorine dioxide (ClO_2) safe storage and handling, 0606-30
Corrugated boxplant-list of potential hazards, 0301-01
Gaseous ozone (O_3) safe handling, 0606-28
Hydrogen peroxide (H_2O_2) safe storage and handling, 0606-24
Material safety data sheets, 0304-38
Methanol (CH_3OH) safe storage and handling, 0606-25
Oxygen (O_2) bulk storage and safe handling, 0606-29
Sodium chlorate ($NaClO_3$) safe handling and storage, 0606-31
Sulfuric acid (H_2SO_4) safe storage and handling, 0606-26
Safety equipment
Chlorine dioxide (ClO_2) safe storage and handling, *0606-33
Salt
see Sodium chloride
Sampling
Sampling procedures for biomass fuel for boiler performance testing, 0416-17
Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03
Saturated solutions
see Solutions
Scanners
Calculation and partitioning of variance using paper machine scanning sensor measurements, 1101-01
Scheduling
Checklist for a properly planned project, 0408-01
Housekeeping at order and shift change and weekly, 0305-32
Schopper Riegler freeness
Interconversion of freeness, 0809-01
Score breaks
How to prevent score cracking in a box plant, 0304-37
Score cracking
Troubleshooting the diecutting section, 0305-39
Score cracks
see Score breaks
Scores
Minimizing rolling scores on lightweight and high-performance liners in diecutting operations, 0304-64
Preventing score cracking in a box plant, 0304-37
Scoring
Machinery considerations and selection: yoked scoring slotting section, 0305-53
Screens
Catalog of stock prep pilot plants, 0502-20
Seal water
see Sealants, Water
Sealants
Guidelines for measurement of vacuum pump air flow, 0420-12
Seamless materials
Guide to the use of stainless steel pipe specifications, 0402-24
Secondary fibers
Stickies definition and classification, 0603-02
Selection
A guide to proper wipe selection for the corrugated box industry, 0306-20
Machinery considerations and selection, 0305-06
Selective catalytic reduction
Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25
Selective noncatalytic reduction
Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25
Semichemical pulps
Boiling point rise of spent sulfite liquors, 0607-21
Definitions of terms in the sulfite pulping process, 0607-25
Density of aqueous sodium sulfite solution, 0607-18
Density of milk of lime solution, 0607-05
Solubility of sulfur dioxide, $Ca(HSO_3)_2$ solutions, 0607-07
Sulfur burner gas strength volume, 0607-01
Viscosities of various spent sulfite liquors at 26.7°C and other temperatures, 0607-22
Sensitivity
Basic guidelines for image analysis measurements, 0804-09
Sensors
Calculation and partitioning of variance using paper machine scanning sensor measurements, 1101-01
Setting time
Understanding and troubleshooting hot melt adhesives, 0304-74
Shafts

Paper machine reel-spool journals: guidelines for crack testing and repair or replacement, 0402-34
Shape
Total indicated runout and its impact on combined board quality, 0304-56
Sheet water content
see Moisture content
Shells
Guidelines for inspection and nondestructive testing of paper machine dryers, 0402-16
Weld repairs on new suction roll shells, 0402-17
Shipping containers
Guideline for direct contact printing of bar code symbols on corrugated, 0306-16
Shock drying
Terminology for high temperature pressing, 0404-48
Showers
Paper machine clothing cleaning and conditioning for recycled fiber use, 0404-51
Paper machine shower recommendations, 0404-61
Press fabric dewatering and conditioning – suction box (Uhle box) design and vacuum requirements. 0404-27
Steam shower applications in the forming section, 0404-58
Silica
Response to contamination of high purity boiler feedwater, 0416-05
Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03
Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14
Singlefacers
Addendum to *Corrugating Defect Terminology Manual* - defects related to the use of fingerless singlefacers, 0304-17
Alternative method for designating flute sizes, 0302-04
Causes and corrections of common corrugator bonding problems, 0304-32
Checking for coating wear on corrugating rolls, 0304-73
Checking the flute depth of corrugating rolls, 0304-75
Parallel of corrugating rolls with "NCR" paper, 0304-62
Preventing score cracking in a box plant, 0304-37
Setting up a raw material trial on the corrugator, 0304-01
Some questions and answers on gel temperatures and on the gel temperature test for corrugating adhesives, 0304-08
Splicer defects and cures, 0304-31
Recommended dryer differential pressures, 0404-31
Skid
Material handling considerations for flexo folder gluers, 0305-54
Slabbing
Broke loss calculations, 0502-10
Slices
Flow from a 45° slice, 0410-03
Flow from a nozzle (slice) with inclined upper lip, 0410-04
Flow from a stock behind slice (head/jet relationship), 0410-05
Flow from a vertical slice, 0410-02
Slide angle
Statistical process control, friction, 0304-34
Slotting
Machinery considerations and selection: yoked scoring slotting section, 0305-53
Slurry
Physical data of calcined kaolin-water suspensions, 0106-09
Physical data of calcium carbonate-water suspensions, 0106-01
Physical data of hydrous Kaolin-water suspensions, 0106-02
Slushed paper stock
see Paper stock
Smearing
Reduction or elimination of ink and/or varnish smear when printing and rotary die cutting in one pass, 0305-40
Smog
Nitrogen oxide emissions control from biomass and kraft recovery boilers in the pulp and paper industry, 0416-25
Sodium
Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03
Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14
Sodium bicarbonate
Density of aqueous sodium bicarbonate solution, 0607-13
Sodium bisulfite
Vapor pressure of water and sulfur dioxide above sodium bisulfite solutions (25°C), 0607-12
Sodium borate
Some questions and answers on gel temperatures and on the gel temperature test for corrugating adhesives, 0304-08
Sodium carbonate
Density of aqueous sodium carbonate solution, 0607-14
Specific heat of sodium carbonate solution, 0607-15
Vapor pressure of sodium carbonate solution, 0607-16
Viscosity of sodium carbonate solution, 0607-17
Sodium chlorate
Safe storage of, 0606-31
Sodium chloride
Specific gravity of sodium chloride solutions, 0606-10
Sodium hydroxide
Caustic soda (NaOH) safe storage and handling, 0606-27
Relative enthalpy of solution, 0606-08
Some questions and answers on gel temperatures and on the gel temperature test for corrugating adhesives, 0304-08
Specific gravity and density of caustic soda solutions, 0606-20
Specific heat of caustic soda solutions, 0606-07
Viscosity of sodium hydroxide solutions, 0606-11
Sodium sulfite
Density of aqueous sodium sulfite solution, 0607-18
Solids content
Physical data of calcined kaolin-water suspensions, 0106-09

Physical data of calcium carbonate-water suspensions, 0106-01
Physical data of hydrous Kaolin-water suspensions, 0106-02
Solubility
Solubility of sulfur dioxide, 0607-06
Solubility of sulfur dioxide, $Ca(HSO_3)_2$ solutions, 0607-07
Solubility of sulfur dioxide in magnesium bisulfite solution, 0607-09
Solubility of sulfur dioxide in saturated magnesium bisulfite solution, 0607-10
Solutions
Equilibrium relative humidities over saturated salt solutions, 0808-03
Specific heat of caustic soda solutions, 0606-07
Sorption
Cotton in nonwovens, 1205-02
Soot blowers
Recovery boiler sootblowers: practical guidelines, 0416-20
Recovery boiler sootblowers: the basics, 0416-19
SPC techniques
see Statistical methods
Specialty coating pigment
see Pigment
Specific gravity
see Density
Specific heat
Specific heat of caustic soda solutions, 0606-07
Specific heat of sodium carbonate solution, 0607-15
Specifications
Guideline specification for procurement of an economizer for a recovery boiler, 0416-21
Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03
Speed
see Velocity
Spent sulfite liquors
Density of aqueous sodium sulfite solution, 0607-18
Splicers
Splicer defects and cures, 0304-31
Spools
Paper machine reel-spool journals: guidelines for crack testing and repair or replacement, 0402-34
Reel diameter for various reel spool and roll core sizes, 0502-03
Spunlaced fabric
Cotton in nonwovens, 1205-02
Spray coaters
see also Coaters
In-line coating at the corrugator, TIP 0304-39
Squared paper
Squaring flap cut (center special) boxes, 0305-45
Squaring
see Squared papers, Trimming
Stackers
Multiple-out rotary diecut stacking, 0305-47
Stacking off the rotary diecutter, 0305-46
Stacking
Corrugated caliper: why is it so important?, 0304-04
Stacking strength
see Compression strength
Stainless steel
Guide to the use of stainless steel pipe specifications, 0402-24
Guidelines for corrosion resistant weld metal overlay of digester vessels in alkaline pulping service, 0402-03
Guidelines for nondestructive examination of suction roll shells, 0402-19
Guidelines for procurement of cast stainless steels for large pumps and valves for the pulp and paper industry, 0402-25
Inspection for cracking of composite tubes in black liquor recovery boilers, 0402-30
Post-fabrication cleaning of stainless steel in the pulp and paper industry, 0402-35
Weld repairs on new suction roll shells, 0402-17
Standard conditions
Testing atmospheres simulating end use conditions, 0808-05
Starch
Proper methods of measuring starch adhesive viscosity, 0304-33
Starch adhesive preparation and distribution systems: housekeeping, 0304-06
Starch adhesive trial, 0304-22
Statistical process control of starch gelatinization temperature, 0304-14
Statistical process control of starch viscosity, 0304-15
Techniques for running “WRA” (water resistant starch adhesive), 0304-46
Understanding wet strength: what are MRA, WRA, and WPA?, 0304-69
Using washup water as the vehicle in starch-based corrugating adhesive, 0304-44
Starch conversion
Statistical process control of starch gelatinization temperature, 0304-14
Statistical analysis
How to perform a gauge repeatability and reproducibility study, 0304-71
Obtaining combined board caliper off the corrugator for use statistical process control procedures, 0304-12
Starch viscosity in corrugating adhesives, 0304-15
Statistical distribution
Calculation and partitioning of variance using paper machine scanning sensor measurements, 1101-01
Statistical methods
Boxplant quality measurement: why test?, 0304-02
Obtaining combined board caliper off the corrugator, 0304-12
Procedures for charting warp, 0304-13
Procedures for utilizing statistical control techniques to monitor the tare weight of a run of boxes, 0304-35
Short-run statistical process control: a basic charting

method, 0304-70
Statistical process control: friction - slide angle, 0304-34
Statistical process control of starch gelatinization temperature, 0304-14
Statistical process control of starch viscosity, 0304-15
Statistical process control pin adhesion, 0304-23
Statistical process control techniques to assist in meeting specification at finishing crush process control points to the paper and paperboard industries, 0304-11
Statistical process control
see Statistical methods
Statistical quality control
see Statistical methods
Statistics
Calculation and partitioning of variance using paper machine scanning sensor measurements, 1101-01
Obtaining combined board caliper off the corrugator for use in statistical process control procedures, 0304-12
Starch viscosity in corrugating adhesives, 0304-15
Statistical process control of starch gelatinization temperature, 0304-14
Status reports
see Reporting
Steam
Application of dryer bars, 0404-35
Guide for increasing the maximum allowable working pressure of cast iron, ASME constructed paper machine dryers, 0420-14
Guidelines for detection, monitoring and prevention of flow accelerated corrosion (FAC) in the pulp and paper mill, 0402-36
Guidelines for routine periodic inspection and testing of cast iron Yankee and MG dryers, 0425-01
Response to contamination of high purity boiler feedwater, 0416-05
Steam shower applications in the forming section, 0404-58
Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03
Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14
Yankee dryer steam condensing rates, 0404-49
Steam chests
Terminology for high temperature pressing, 0404-48
Steam pressure
see Pressure gradient
Sterilization
Starch adhesive preparation and distribution systems: housekeeping, 0304-06
Stickies
Stickies definition and classification, 0603-02
Stitch bonding
Cotton in nonwovens, 1205-02
Stock flow
Optimum consistency for pumping pulp, 0410-15
Stock (pulp)
Control of stock activity on a fourdrinier table, 0410-08
Head of stock behind slice (head/jet relationships), 0410-05
Stock flow
Control of stock activity on a fourdrinier table, 0410-08
Stock preparation
Catalog of stock prep pilot plants, 0502-20
Stones
see Pulpstones
Storage
Buying, storing, and handling flexo folder gluer/rotary diecutter adhesives, 0305-25
Caustic soda (NaOH) safe storage and handling, 0606-27
Chlorine dioxide (ClO_2) safe storage and handling, 0606-30
Hydrogen peroxide (H_2O_2) safe storage and handling, 0606-24
Methanol (CH_3OH) safe storage and handling, 0606-25
Oxygen (O_2) bulk storage and safe handling, 0606-29
Sodium chlorate ($NaClO_3$) safe handling and storage, 0606-31
Sulfuric acid (H_2SO_4) safe storage and handling, 0606-26
Strapping
Critical properties to consider when unitizing, 0304-72
Material handling considerations for flexo folder gluers, 0305-54
Stress
Best practice guidelines for detecting and mitigating waterside cracking (stress-assisted corrosion) in power and recovery boilers, 0402-38
Stress assisted corrosion
Best practice guidelines for detecting and mitigating waterside cracking (stress-assisted corrosion) in power and recovery boilers, 0402-38
Stress corrosion
Guidelines for inspection of continuous digesters and impregnation vessels, 0402-27
Strippers
Stripping of kraft pulping process condensates: regulations, design and operation, 0416-10
Stripping
Troubleshooting the diecutting section, 0305-39
Stuff boxes
Headbox approach piping guidelines, 0404-54
Suction
see Vacuum
Suction press rolls
see Press rolls, Vacuum rolls
Suction presses
Paper machine vacuum selection factors, 0502-01
Suction rolls
see Vacuum rolls
Sulfite liquors
Boiling point rise of spent sulfite liquors, 0607-21
Definitions of terms in the sulfite pulping process, 0607-25
Density of aqueous sodium sulfite solution, 0607-18
Density of milk of lime solution, 0607-05

Solubility of sulfur dioxide, $Ca(HSO_3)_2$ solutions, 0607-07
Sulfur burner gas strength volume, 0607-01
Viscosities of various spent sulfite liquors at 26.7°C and other temperatures, 0607-22
Sulfite pulping
Boiling point rise of spent sulfite liquors, 0607-21
Definitions of terms in the sulfite pulping process, 0607-25
Density of aqueous sodium sulfite solution, 0607-18
Density of milk of lime solution, 0607-05
Physical and chemical properties of magnesia-base pulping solutions, 0607-04
Solubility of sulfur dioxide, $Ca(HSO_3)_2$ solutions, 0607-07
Solubility of sulfur dioxide, 0607-06
Solubility of sulfur dioxide in magnesium bisulfite solution, 0607-09
Solubility of sulfur dioxide in saturated magnesium bisulfite solution, 0607-10
Sulfur burner gas strength volume, 0607-01
Vapor pressure of sulfur dioxide solutions, 0607-11
Vapor pressure of water and sulfur dioxide above sodium bisulfite solutions (25°C), 0607-12
Viscosities of various spent sulfite liquors at 26.7°C, 0607-22
Sulfite waste liquor
see Spent sulfite liquors
Sulfur burners
Sulfur burner gas strength volume, 0607-01
Sulfur dioxide
Boiling point rise of spent sulfite liquors, 0607-21
Definitions of terms in the sulfite pulping process, 0607-25
Physical and chemical properties of magnesia-base pulping solutions, 0607-04
Solubility of sulfur dioxide, 0607-06
Solubility of sulfur dioxide, $Ca(HSO_3)_2$ solutions, 0607-07
Solubility of sulfur dioxide in magnesium bisulfite solution, 0607-09
Solubility of sulfur dioxide in saturated magnesium bisulfite solution, 0607-10
Sulfur burner gas strength volume, 0607-01
Vapor pressure of sulfur dioxide solutions, 0607-11
Viscosities of various spent sulfite liquors at 26.7°C, 0607-22
Viscosity of a neutral sulfite spent liquor (Ostwald capillary viscometer), 0607-23
Vapor pressure of water and sulfur dioxide above sodium bisulfite solutions (25°C), 0607-12
Sulfuric acid
Sulfuric acid (H_2SO_4) safe storage and handling, 0606-26
Supervision
Project leader, 0305-13
Surface properties
Granite roll material and surface requirements, 0404-41
Surface speed
see Retention, Machine speed
Suspended solids
Generalized method for determining the pipe friction loss of lowing pulp suspensions, 0410-14
Symbols
Guideline for direct contact printing of bar code symbols on corrugated, 0306-16
Systems
Chloride and potassium measurement and control in the pulping and chemical recovery cycle, 0416-15

T-
Tare weight
Statistical control techniques to monitor the tare weight of a run of boxes, 0304-35
Task time
see Time
Technical nomenclature
see Nomenclature
Temperature
Conducting a corrugator temperature audit, 0304-65
Density of aqueous sodium bicarbonate solution, 0607-13
Density of aqueous sodium carbonate solution, 0607-14
Dryer section performance monitoring, 0404-33
Dryer surface temperature measurement, 0404-39
Guidelines for the design, operation, performance evaluation, and troubleshooting of a paper machine hood and air systems, 0404-24
Solubility of sulfur dioxide in magnesium bisulfite solution, 0607-09
Solubility of sulfur dioxide in saturated magnesium bisulfite solution, 0607-10
Some questions and answers on gel temperatures and on the gel temperature test for corrugating adhesives, 0304-08
Specific heat of sodium carbonate solution, 0607-15
Statistical process control of starch gelatinization temperature, 0304-14
Statistical process control of starch viscosity, 0304-15
Testing atmospheres simulating end use conditions, 0808-05
Troubleshooting cross-machine direction moisture profile problems, 0404-57
Vapor pressure of sodium carbonate solution, 0607-16
Vapor pressure of sulfur dioxide solutions, 0607-11
Viscosity of a neutral sulfite spent liquor (Ostwald capillary viscometer), 0607-23
Viscosity of sodium carbonate solution, 0607-17
Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03
Tension
Recommended tensions in dryer fabrics, 0404-04
Terminology
see Nomenclature
Test conditions
Testing atmospheres simulating end use conditions, 0808-05
Test equipment

Paper test rooms: design considerations, 0808-04
Test facilities
Paper test rooms: design considerations, 0808-04
Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03
Test methods
Guidelines for measurement of vacuum pump air flow, 0420-12
Testing
Basic guidelines for image analysis measurements, 0804-09
Catalog of stock prep pilot plants, 0502-20
Drainage evaluation by mass measurement, 0502-12
Forming section monitoring, 0502-14
Paper machine reel-spool journals: guidelines for crack testing and repair or replacement, 0402-34
Paper test rooms: design considerations, 0808-04
Recommended test procedure for black liquor evaporators, 0416-11
Water removal by wet presses, 0404-01
Thermal measurement
Recovery boiler performance calculation – short form, 0416-01
Thermal spray
Guidelines for thermal spray coatings installed to prevent corrosion in pulp mill process equipment, 0402-32
Guidelines for inspecting batch digesters, 0402-22
Thermobonding
Cotton in nonwovens, 1205-02
Thermography
Troubleshooting cross-machine direction moisture profile problems, 0404-57
Thermoplastics
Fluoropolymer properties and applications in pulp and paper mills, 0402-37
Thick stock
see High consistency
Thickness
Corrugated caliper: why is it so important?, 0304-04
Method for evaluating thickness of wet press fabrics, 0404-28
Obtaining combined board caliper off the corrugator for use in statistical process control procedures, 0304-12
Statistical process control techniques to assist in meeting specification at finishing crush process control points to the paper and paperboard industries, 0304-11
Ultrasonic testing (UT) for tube thickness in black liquor recovery boilers, 0402-18
Through drying
Through drying, 0404-25
Tissue
Inspection guidelines for Yankee hood systems, 0425-02
Tolerance
Corrugator bearing clearance checks and their impact, 0304-47
Total indicated runout
see also Combined boards
Total indicated runout and its impact on combined board quality, 0304-56
Total reduced sulfur
Collection and burning of concentrated noncondensible gases: regulations, design and operation, 0416-09
Transport
Checklist: preparing die cuts for shipment, 0305-49
Sodium chlorate ($NaClO_3$) safe handling and storage, 0606-31
Sulfuric acid (H_2SO_4) safe storage and handling, 0606-26
Trim
Broke loss calculations, 0502-10
Paper machine room ventilation guidelines, 0404-50
Trimming
Machinery considerations and selection: yoked scoring slotting section, 0305-53
Squaring flap cut (center special) boxes, 0305-45
Troubleshooting
Forming section monitoring, 0502-14
Glue lap problem, 0304-10
Press section monitoring, 0404-19
Recommended test procedure for black liquor evaporators, 0416-11
Steam shower applications in the forming section, 0404-58
Tubes
Best practice guidelines for detecting and mitigating waterside cracking (stress-assisted corrosion) in power and recovery boilers, 0402-38
Guidelines for detection, monitoring and prevention of flow accelerated corrosion (FAC) in the pulp and paper mill, 0402-36
Guidelines for operating and maintenance practices impacting an economizer on a recovery boiler, 0416-22
Guidelines for replacement of generating bank tubes with expanded joints in two-drum boilers, 0416-08
Inspection for cracking of composite tubes in black liquor recovery boilers, 0402-30
Keys to successful chemical cleaning of boilers, 0416-06
Ultrasonic technician performance test for boiler tube inspection, 0402-21
Ultrasonic testing (UT) for tube thickness in black liquor recovery boilers, 0402-18
Tungsten carbide
Tests for corrugator roll wear, 0304-53
Tuning
see Control
Turpentine
Collection and burning of concentrated noncondensible gases: regulations, design and operation, 0416-09
Twisting
Techniques to minimize twist warp, 0304-50

U-
Uhle boxes
See also Vacuum boxes
Press fabric dewatering and conditioning – suction box (Uhle box) design and vacuum requirements. 0404-27
Ultrafine ground limestone

see Limestone
Ultraviolet radiation
Drying and curing techniques for in-line flexographic printing, 0306-06
Ultrasonic tests
Guidelines for evaluating quality of boiler tube butt welds with ultrasonic testing, 0402-31
Guidelines for inspecting batch digesters, 0402-22
Ultrasonic technician performance test for boiler tube inspection, 0402-21
Ultrasonic testing (UT) for tube thickness in black liquor recovery boilers, 0402-18
Unitized handling
Critical properties to consider when unitizing, 0304-72
Units of measurement
Units of measurement and conversion factors, 0800-01
Unloading
Sodium chlorate ($NaClO_3$) safe handling and storage, 0606-31
Sulfuric acid (H_2SO_4) safe storage and handling, 0606-26
U.P.C.
see Product codes
Urethanes
Rotary diecutter urethane anvil maintenance, 0305-35

V-
Vacuum
High vacuum sheet dewatering, 0404-60
Paper machine vacuum selection factors, 0502-01
Papermaker's formulas, 0502-17
Steam shower applications in the forming section, 0404-58
Vacuum boxes
High vacuum sheet dewatering, 0404-60
Paper machine vacuum selection factors, 0502-01
Performance evaluation techniques for paper machine vacuum systems, 0404-55
Vacuum equipment
Press fabric dewatering and conditioning – suction box (Uhle box) design and vacuum requirements, 0404-27
Vacuum filters
Bleaching plant washer efficiency guide, 0606-23
Vacuum pumps
Guidelines for measurement of vacuum pump air flow, 0420-12
Performance evaluation techniques for paper machine vacuum systems, 0404-55
Press fabric dewatering and conditioning – suction box (Uhle box) design and vacuum requirements. 0404-27
Vacuum rolls
Guidelines for nondestructive examination of suction roll shells, 0402-19
Liquid penetrant testing of new suction roll shells, 0402-11
Paper machine vacuum selection factors, 0502-01
Press roll cover application guidelines, 0404-37
Techniques for nip impressions, 0404-46
Weld repairs on new suction roll shells, 0402-17
Vacuum washers
Bleaching plant washer efficiency guide, 0606-23
Valves
Guidelines for procurement of cast stainless steels for large pumps and valves for the pulp and paper industry, 0402-25
Headbox approach piping guidelines, 0404-54
Vapor pressure
Chlorine gas curve, 0606-02
Vapor pressure of sulfur dioxide solutions, 0607-11
Vapor pressure of sodium carbonate solution, 0607-16
Vapor pressure of water and sulfur dioxide above sodium bisulfite solutions (25°C), 0607-12
Variance
Calculation and partitioning of variance using paper machine scanning sensor measurements, 1101-01
Varnish
Reduction or elimination of ink and/or varnish smear when printing and rotary die cutting in one pass, 0305-40
Velocity
see also Machine speed
Pulpstone speed chart, 0605-02
Ventilation
Paper machine room ventilation guidelines, 0404-50
Recommended minimum dryer pocket air requirements, 0404-17
Guidelines for the design, operation, performance evaluation, and troubleshooting of a paper machine hood and air systems, 0404-24
Viscosity
Density of aqueous sodium sulfite solution, 0607-18
Liquid chlorine, 0606-05
Proper methods of measuring starch adhesive viscosity, 0304-33
Quality techniques using existing equipment, 0306-11
Statistical process control of starch viscosity, 0304-15
Viscosities of spent sulfite liquors at 26.7° C (Oswalt capillary viscometer), 0607-22
Viscosity of a neutral sulfite spent liquor (Ostwald capillary viscometer), 0607-23
Viscosity of sodium carbonate solution, 0607-17
Viscosity of sodium hydroxide solutions, 0606-11
Viscosity reading procedure for flexographic corrugated inks, 0304-18
Vision
Basic guidelines for image analysis measurements, 0804-09
Volume
Grinder pulpstones – cubical contents, 0605-01
Identifying anilox volume measuring equipment, 0306-15

W-
Warning labels
see Hazardous materials
Warpage
Go/no go gauge devices for the boxplant, 0304-42
Statistical process control -- procedures for charting warp, 0304-13

Techniques to minimize twist warp, 0304-50
Warp in corrugated board, 0304-07
Wash waters
Using washing water as the vehicle in starch based corrugating adhesive, 0304-44
Washers
Energy checklist: pulp mill, 0416-24
Bleaching plant washer efficiency guide, 0606-23
Washing
Bleaching plant washer efficiency guide, 0606-23
Recommended pulp bleaching stage designation method, 0606-21
Wastewater treatment equipment
see Effluent treatment
Water
see also Solubility
Design engineer decisions tree: paper mill boiler feedwater, 0416-04
Guidelines for measurement of vacuum pump air flow, 0420-12
Vapor pressure of water and sulfur dioxide above sodium bisulfite solutions (25°C), 0607-12
Water treatment-related opportunities for energy conservation in a paper mill powerhouse, 0416-13
Water content
see Moisture content
Water hardness
Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03
Water permeability
Troubleshooting cross-machine direction moisture profile problems, 0404-57
Water removal
Determination of water removal by wet presses, 0404-01
High vacuum sheet dewatering, 0404-60
Methods to minimize sheet rewet in the press section, 0404-59
Paper machine drying rate, 0404-07
Water resistance
Techniques for running "WRA" (water resistant starch adhesive), 0304-46
Understanding wet strength: what are MRA, WRA, and WPA?, 0304-69
Water treatment
Design engineer decisions tree: paper mill boiler feedwater, 0416-04
Water treatment-related opportunities for energy conservation in a paper mill powerhouse, 0416-13
Water vapor
Paper machine room ventilation guidelines, 0404-50
Waterside cracking
Best practice guidelines for detecting and mitigating waterside cracking (stress-assisted corrosion) in power and recovery boilers, 0402-38
Wax
Common curtain coating problems: causes, detection, and correction, 0304-26
Curtain coating weight test, 0304-19
Wear resistance
see Abrasion resistance
Web tension
Guidelines for web conveyance and winding tension levels, 0200-01
Webs
see also Paper webs
Guidelines for web conveyance and winding tension levels, 0200-01
Weight
Physical characterization of press fabrics: basis weight, air permeability, void volume under loading and pressure uniformity, 0404-20
Procedure for utilizing statistical control techniques to monitor the tare weight of a run of boxes, 0304-35
Weight of newsprint rolls, 0502-11
Weirs
Weirs and flumes, 0410-10
Welding
Guide to the use of stainless steel pipe specifications, 0402-24
Guidelines for corrosion resistant weld metal overlay of digester vessels in alkaline pulping service, 0402-03
Guidelines for evaluating quality of boiler tube butt welds with ultrasonic testing, 0402-31
Guidelines for inspection of continuous digesters and impregnation vessels, 0402-27
Guidelines for procurement of cast stainless steels for large pumps and valves for the pulp and paper industry, 0402-25
Field welding of pin studs in black liquor recovery boilers, 0402-15
Wet bulb temperature
Relative humidity tables, 0808-06
Wet ends
Drainage evaluation by mass measurement, 0502-12
Forming section monitoring, 0502-14
How to prevent score cracking in a box plant, 0304-37
Selection criteria for wet end ceramics, 0502-15
Wet felts
see also Felts
Porosity measurement of press felts on the paper machine (HSPT), 0404-29
Wet presses
Determination of water removal by, 0404-01
Wet pressing
Terminology for high temperature pressing, 0404-48
Wet strength
Understanding wet strength: whaqt are MRA, WRA, and WPA?, 0304-69
Wet-laid nonwovens
Pilot paper machines, 0502-16
White liquors
Recausticizing material balance equations relating to digester requirements, 0418-02
White water
Drainage evaluation by mass measurement, 0502-12
Flow determination by chemical method, 0410-09

Weirs and flumes, 0410-10
Width
Weight of newsprint rolls, 0502-11
Winding
Guidelines for web conveyance and winding tension levels, 0200-01
Wire
Use of ceramics on the forming section: diagnosing and preventing forming fabric wear, 0502-19
Williams freeness
Interconversion of freeness, 0809-01
Winders
Determination of winder sets per reel, 0502-02
Wiperoll
see Flexography
Wood
Calibration technique for the drum style chip thickness classifier, 0602-03
Wood chips
see Chips
Wood containing papers
see Mechanical papers
Wood free papers
Paper machine drying rate, 0404-07
Work place
see Human factors
Working conditions
see Environments
Wound rolls
Reel diameter for various reel spool and roll core sizes, 0502-03
TAPPI Roll number for inventory/tracking systems and bar codes, 1004-01
Writing papers
Paper machine drying rate, 0404-07

X-Y-Z-
Yankee cylinders
see Yankee dryers
Yankee dryers
Guidelines for routine periodic inspection and testing of cast iron Yankee and MG dryers, 0425-01
Inspection guidelines for Yankee hood systems, 0425-02
Techniques for nip impressions, 0404-46
Yankee dryer steam condensing rates, 0404-49