

Subject Index

Technical Information Papers

This document was last updated September 1, 2009

A-

Abrasion

Selection criteria for wet end ceramics, 0502-15

Abrasion resistance

Selection criteria for wet end ceramics, 0502-15

Acrylic fibers

see Polyacrylics, Synthetic fibers

Additives

Techniques for running "WRA" (water resistant starch adhesive), 0304-46

Adhesives

Buying, storing, and handling flexo folder gluer/rotary diecutter adhesives, 0305-25

Causes and corrections of common corrugator bonding problems, 0304-32

Evaluating glue lap adhesives, 0304-16

Green peel bond test at the corrugator, 0304-27

Procedure for setting up a raw material trial on the corrugator, 0304-01

Proper methods of measuring starch adhesive viscosity, 0304-33

Starch adhesive preparation and distribution systems: housekeeping, 0304-06

Starch adhesive trial, 0304-22

Statistical process control of starch gelatinization temperature, 0304-14

Statistical process control of starch viscosity, 0304-15

Techniques for bonding of densified liners, 0304-40

Techniques for running "WRA" (water resistant starch adhesive), 0304-46

Understanding wet strength: what are MRA, WRA, and WPA?, 0304-69

Understanding and troubleshooting hot melt adhesives, 0304-74

Using washup water as the vehicle in starch-based corrugating adhesive, 0304-44

After dryers

Paper machine drying rate, 0404-07

Agitation

Using washing water as the vehicle in starch based corrugating adhesive, 0304-44

Agitators

Guidelines for side-entering stock agitators, 0420-13

Air

Paper machine room ventilation guidelines, 0404-50

Air balance

see Air, Materials balance

Air flow

Measurement of vacuum pump air flow, 0420-12

Minimum dryer pocket air requirements, 0404-17

Recommended operation of dryer section hood air systems, 0404-24

Sheet handling devices, 0404-44

Air jets

Sheet handling devices, 0404-44

Air permeability

Physical characterization of press fabrics: basis weight, air permeability, void volume under loading and pressure uniformity, 0404-20

Air pollution

Collection and burning of concentrated noncondensable gases: regulations, design and operation, 0416-09

Alignment

Checking the parallel of corrugating rolls with "NCR" paper, 0304-62

Alkali

Specific heat of caustic soda solutions, 0606-07

Alkaline sulfite pulping

Boiling point rise of spent sulfite liquors, 0607-21

Definitions of terms in the sulfite pulping process, 0607-25

Density of aqueous sodium sulfite solution, 0607-18

Density of milk of lime solution, 0607-05

Solubility of sulfur dioxide, $\text{Ca}(\text{HSO}_3)_2$ solutions, 0607-07

Sulfur burner gas strength volume, 0607-01

Viscosities of various spent sulfite liquors at 26.7°C, 0607-22

Alkalinity

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Ammonia

Solubility of sulfur dioxide, 0607-06

Anatase

Titanium dioxide pigment index, 0106-07

Analysis

Method for determining length and other properties in rolls of various diameters and basis weights, 1008-02

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Angle of slide

see Slide angle

Anilox coaters

In-line coating at the corrugator, TIP 0304-39

Anilox rolls

see Flexography, Printing cylinders

Anvil

Troubleshooting the diecutting section, 0305-39

Approach flow systems

Headbox approach piping guidelines, 0404-54

Ash

Chloride and potassium measurement and control in the pulping and chemical recovery cycle, 0416-15

Drainage evaluation by mass measurement, 0502-12

Atmosphere

Testing atmospheres simulating end use conditions, 0808-05

Auditing

Checklist for a properly planned project, 0408-01

Automatic feeders

see Feeders

B-**Bacteria**

Starch adhesive preparation and distribution systems: housekeeping, 0304-06

Bag papers

Paper machine performance guidelines, 0404-47

Bags

Paper machine drying rate, 0404-07

Bar Width Reduction (BWR)

see Product codes

Bar codes

see Product codes

Bases

see Hydroxides

Basis weight

Headbox approach piping guidelines, 0404-54

Method for determining length and other properties in rolls of various diameters and basis weights, 1008-02

Batch digesters

Guidelines for inspecting batch digesters, 0402-22

Batch process

Dryer condensing rates, 0404-02

Measurement of dryer condensing rates (vertical separator method), 0404-18

Beams

Calibration of flexible beam crush tester, 0304-20

Bearings

Corrugator bearing clearance checks and their impact, 0304-47

Guidelines for inspection and nondestructive examination of paper machine dryers, 0402-16

Paper machine reel spool journals: guidelines for the in-service inspection to detect cracking and repair/replacement considerations, 0402-34

Total indicated runout and its impact on combined board quality, 0304-56

Biocide

Using washing water as the vehicle in starch based corrugating adhesive, 0304-44

Biomass

Performance test procedure for boilers using biomass as fuel, 0416-18

Sampling procedures for biomass fuel for boiler

performance testing, 0416-17

Biomechanics

see Human factors

Bisulfites

Physical and chemical properties of magnesia-base pulping solutions, 0607-04

Solubility of sulfur dioxide, 0607-06

Solubility of sulfur dioxide in magnesium bisulfite solution, 0607-09

Solubility of sulfur dioxide in saturated magnesium bisulfite solution, 0607-10

Black liquors

Field welding of pin studs in black liquor recovery boilers, 0402-15

Recommended test procedure for black liquor evaporators, 0416-11

Recovery boiler performance calculation – short form, 0416-01

Response to contamination of high purity boiler feedwater, 0416-05

Blade coaters

see also Coaters

In-line coating at the corrugator, TIP 0304-39

Bleach plants

Bleaching plant washer efficiency guide, 0606-23

Bleached board

Paper machine drying rate, 0404-07

Paper machine performance guidelines, 0404-47

Bleaching

Boiling point rise of spent sulfite liquors, 0607-21

Cotton in nonwovens, 1205-02

Chlorine gas curve, 0606-02

Definitions of terms in the sulfite pulping process, 0607-25

Density of aqueous sodium sulfite solution, 0607-18

Density of chlorine gas, 0606-03

Density of milk of lime solution, 0607-05

Heat of vaporization of liquid chlorine, 0606-04

Recommended pulp bleaching stage designation method, 0606-21

Relative enthalpy (heat content) of sodium hydroxide solutions, 0606-08

Solubility of sulfur dioxide, $\text{Ca}(\text{HSO}_3)_2$ solutions, 0607-07

Specific gravity and density of caustic soda solutions, 0606-20

Specific gravity of sodium chloride solutions, 0606-10

Sulfur burner gas strength volume, 0607-01

Viscosities of various spent sulfite liquors at 26.7°C, 0607-22

Viscosity of liquid chlorine 0606-05

Viscosity of sodium hydroxide solutions, 0606-11

Bleaching stages

see Bleaching

Blind-drilled rolls

see Vacuum rolls

Blistering

Addendum to *Corrugating Defect Terminology*

Manual - defects related to the use of fingerless singlefacers, 0304-17

Blow boxes

Sheet handling devices, 0404-44

Blowdown

see also Blowing

Design engineer decisions tree: paper mill boiler feedwater, 0416-04

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Blowing

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Board caliper

see Thickness

Boiler feed water

see Boilers, Feedwater

Boiler tubes

Guideline for obtaining high quality radiographic testing of butt welds in boiler tubes, 0402-33

Guidelines for evaluating quality of boiler tube butt welds with ultrasonic testing, 0402-31

Guidelines for specification and inspection of electric resistance welded (ERW) and seamless boiler tube for critical and noncritical service, 0402-13

Boilers

Design engineer decisions tree: paper mill boiler feedwater, 0416-04

Evaluating reverse osmosis for treating makeup to the boiler feedwater in a pulp and paper mill, 0416-07

Guidelines for evaluating quality of boiler tube butt welds with ultrasonic testing, 0402-31

Keys to successful chemical cleaning of boilers, 0416-06

Performance test procedure for boilers using biomass as fuel, 0416-18

Sampling procedures for biomass fuel for boiler performance testing, 0416-17

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Water treatment-related opportunities for energy conservation in a paper mill powerhouse, 0416-13

Bonding

Green peel bond test at the corrugator, 0304-27

Techniques for bonding of densified liners, 0304-40

Box compression

see Compression strength

Box flaps

see Flaps

Box machines

Troubleshooting a glue lap problem, 0304-10

Box plants

see Converting plants

Boxes

Corrugated boxplant-list of potential hazards, 0301-

01

Critical properties to consider when unitizing, 0304-

72

High vacuum sheet dewatering, 0404-60

Squaring flap cut (center special) boxes, 0305-45

Brightness

Titanium dioxide pigment index, 0106-07

Broke

Broke loss calculations, 0502-10

Bronze

Guidelines for nondestructive examination of suction roll shells, 0402-19

Weld repairs on new suction roll shells, 0402-17

Burst testers

Calibration and maintenance of, 0304-24

Butt joints

Guidelines for evaluating quality of boiler tube butt welds with ultrasonic testing, 0402-31

Butt welds

Guidelines for evaluating quality of boiler tube butt welds with ultrasonic testing, 0402-31

C-

CADCAM

Computer-assisted machinery, 0305-02

CONEG

see Regulations

Cadmium

An explanation of the CONEG heavy metal guidelines, 0304-58

Calcination

Physical data of calcined kaolin-water suspensions, 0106-09

Calcium base liquors

Solubility of sulfur dioxide, $\text{Ca}(\text{HSO}_3)_2$ solutions, 0607-07

Calcium bisulfite

Solubility of sulfur dioxide, $\text{Ca}(\text{HSO}_3)_2$ solutions, 0607-07

Calcium carbonate

Calcium carbonate pigment index, 0106-05

Physical data of calcium carbonate-water suspensions, 0106-01

Calcium hydroxide

Density of milk of lime solution, 0607-05

Calculations

see Computation

Calibration

Basic guidelines for image analysis measurements, 0804-09

Calibration and maintenance of the manually operated micrometer, 0304-30

Calibration of flexible beam crush tester, 0304-20

Of burst testers, 0304-24

Calibration technique for the drum style chip thickness classifier, 0602-03

Suggestions for developing a box plant quality manual, 0304-49

Caliper

see Thickness

Canadian standard freeness

Interconversion of freeness, 0809-01

Carbon steel

Inspection for cracking of composite tubes in black liquor recovery boilers, 0402-30

Carbonates

Chloride and potassium measurement and control in the pulping and chemical recovery cycle, 0416-15

Estimating the first melting temperature of fireside deposits in recovery boilers, 0416-12

Physical data of calcium carbonate-water suspensions, 0106-01

Castings

Guidelines for procurement of cast stainless steels for large pumps and valves for the pulp and paper industry, 0402-25

Caustic soda

see Sodium hydroxide

Causticizing

Material balance equations relating to digester requirements, 0418-02

Ceramic coatings

Press roll cover application guidelines, 0404-37

Ceramics

Selection criteria for wet end ceramics, 0502-15

Certification

Guideline for obtaining high quality radiographic testing of butt welds in boiler tubes, 0402-33

Chalk

see Calcium carbonate

Charting

Introduction to the flow chart, 0305-26

Short-run statistical process control: a basic charting method, 0304-70

Statistical process control pin adhesion, 0304-23

Statistical process control - procedures for charting warp, 0304-13

Checklist

see Maintenance

Chemical preparation

Specific gravity and density of caustic soda solutions, 0606-20

Specific gravity of sodium chloride solutions, 0606-10

Chemical properties

Chlorine dioxide (ClO₂) safe storage and handling, 0606-10

Magnesia-base pulping solutions, 0607-04

Sodium chlorate (NaClO₃) safe handling and storage

Chemical pulps

Boiling point rise of spent sulfite liquors, 0607-21

Definitions of terms in the sulfite pulping process, 0607-25

Density of aqueous sodium sulfite solution, 0607-18

Density of milk of lime solution, 0607-05

Solubility of sulfur dioxide, Ca(HSO₃)₂ solutions, 0607-07

Sulfur burner gas strength volume, 0607-01

Viscosities of various spent sulfite liquors at 26.7°C, 0607-22

Chemical recovery

Recausticizing material balance equations relating to digester requirements, 0418-02

Chemicals

Material safety data sheets, what to look for - how to understand them, 0304-38

Chests

see Stock chests

Chip classifiers

Calibration technique for the drum style chip thickness classifier, 0602-03

Chip silos

see Chip bins

Chips

Calibration technique for the drum style chip thickness classifier, 0602-03

Chlorides

Chloride and potassium measurement and control in the pulping and chemical recovery cycle, 0416-15

Estimating the first melting temperature of fireside deposits in recovery boilers, 0416-12

Chlorine

Chlorine gas curve, 0606-02

Density of chlorine gas, 0606-03

Heat of vaporization of liquid chlorine, 0606-04

Viscosity of liquid chlorine, 0606-05

Chlorine dioxide

Safe storage and handling of, 0606-10

Specific gravity of sodium chloride solutions, 0606-10

Chromium

An explanation of the CONEG heavy metal guidelines, 0304-58

Clad-steel plate

see Plates

Classification

Paper grade classifications, 0404-36

Clay

Kaolin clay pigment index, 0106-06

Physical data of calcined kaolin-water suspensions, 0106-09

Physical data of hydrous Kaolin-water suspensions, 0106-02

Cleaners

Introduction to centrifugal cleaners, 0508-10

Cleaning

Cleaning anilox rolls: procedures and options, 0306-18

Cleanup procedures for flexo folder gluer/rotary diecutters, 0305-33

Daily, weekly, and monthly maintenance checklists, 0305-34

Dryer fabric cleaning, 0404-38

Housekeeping at order and shift change and weekly, 0305-32

Introduction to centrifugal cleaners, 0508-10

Keys to successful chemical cleaning of boilers, 0416-06

Paper machine clothing cleaning and conditioning for recycled fiber use, 0404-51

Paper machine shower recommendations, 0404-61

Post-fabrication cleaning of stainless steel in the pulp and paper industry, 0402-35

Cleaning chemicals

see Cleansers

Cleansers

Keys to successful chemical cleaning of boilers, 0416-06

Clogging

Nozzle maintenance and clogging, 0420-15

Clothing

see Felts

Coating color

see Color

Coatings

Guidelines for applying thermal spray coatings to protect pulp mill process equipment against corrosion, 0402-32

Coding

Increasing the steam pressure rating of ASME coded paper machine dryers, 0420-14

Coefficient of friction

see Friction factor

Combined boards

Common curtain coating problems: causes, detection, and correction, 0304-26

Obtaining off the corrugator for use in statistical process control procedures, 0304-12

Total indicated runout and its impact on combined board quality, 0304-56

Compression

Corrugated caliper: why is it so important?, 0304-04

Compression resistance

see Compression strength

Compression strength

Corrugated caliper: why is it so important?, 0304-04

Obtaining a combined board caliper off the corrugator for use in statistical process control procedures, 0304-12

Statistical process control techniques to assist in meeting specification at finishing crush process control points to the paper and paperboard industries, 0304-11

Computation

Paper machine drying rate, 0404-07

Computer-assisted

see CAD/CAM

Concentricity

Total indicated runout and its impact on combined board quality, 0304-56

Condensates

Measurement of dryer condensing rates (continuous method), 0404-03

Measurement of dryer condensing rates (vertical separator method), 0404-18

Stripping of kraft pulping process condensates:

regulations, design and operation, 0416-10

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Water treatment-related opportunities for energy conservation in a paper mill powerhouse, 0416-13

Yankee dryer steam condensing rates, 0404-49

Condensation

Dryer condensing rates (batch method), 0404-02

Dryer condensing rates (continuous method), 0404-03

Condensing rates

see Condensation

Conditioning

Paper machine clothing cleaning and conditioning for recycled fiber use, 0404-51

Testing atmospheres simulating end use conditions, 0808-05

Conductivity

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Conical refiners

Conical refining intensity, 0508-07

Consistency

Drainage evaluation by mass measurement, 0502-12

Generalized method for determining the pipe friction loss of flowing pulp suspensions, 0410-14

Optimum for pumping pulp, 0410-15

Construction materials

Sodium chlorate (NaClO_3) safe handling and storage

Contact bearings

see Bearings

Contact technique

Guideline for obtaining high quality radiographic testing of butt welds in boiler tubes, 0402-33

Container boards

Determination of moisture in containerboard using a hand held moisture meter, 0304-63

Friction -- slide angle, 0304-34

Contaminants

see Impurities

Contamination

see Pollution control

Continuous digesters

Guidelines for inspection of continuous digesters and impregnation vessels, 0402-27

Contraction

Flow from a 45° slice, 0410-03

Flow from a nozzle (slice) with inclined upper lip, 0410-04

Flow from a vertical slice, 0410-02

Control charts

see Charting

Control systems

Short-run statistical process control: a basic charting method, 0304-70

Conversion factors

Units of measurement and, 0800-01

Converting factors

Moisture content of paper: terminology and conversion, 0808-02

Converting plants

Boxplant quality measurement: why test?, 0304-02

Computer-assisted machinery, 0305-02

Corrugated boxplant - list of potential hazards, 0301-01

Machinery considerations and selection, 0305-06

Copper

Role of in a printing ink, 0304-61

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Copper sulfate

Copper sulfate test for corrugator roll wear, 0304-53

Cores

Determination of winder sets per reel, 0502-02

Reel diameter for various reel spool and roll core sizes, 0502-03

Corrosion

see also Corrosion inhibitors

Clad-steel plate use, 0402-04

Estimating the first melting temperature of fireside deposits in recovery boilers, 0416-12

Guide to the use of stainless steel pipe specifications, 0402-24

Guidelines for corrosion resistant weld metal overlay of digester vessels in alkaline pulping service, 0402-03

Guidelines for inspecting batch digesters, 0402-22

Guidelines for inspection of continuous digesters and impregnation vessels, 0402-27

Guidelines for inspecting used fiber-reinforced plastics (FRP) equipment, 0402-28

Guidelines for nondestructive examination of suction roll shells, 0402-19

Guidelines for welding and inspection of stainless alloy piping, 0402-26

Nozzle maintenance and clogging, 0420-15

Post-fabrication cleaning of stainless steel in the pulp and paper industry, 0402-35

Ultrasonic technician performance test for boiler tube inspection, 0402-21

Corrosion inhibitors

Keys to successful chemical cleaning of boilers, 0416-06

Corrosion prevention

Guidelines for applying thermal spray coatings to protect pulp mill process equipment against corrosion, 0402-32

Guidelines for corrosion resistant weld metal overlay of digester vessels in alkaline pulping service, 0402-03

Corrugated boards

Copper in a printing ink, 0304-61

Critical properties to consider when unitizing, 0304-72

Important quality parameters of a printing ink, 0304-59

Obtaining caliper off the corrugator for use in statistical process control procedures, 0304-12

Proofing a flexo printing ink, 0304-60

Statistical process control friction-slide angle, 0304-34

Techniques to minimize twist warp, 0304-50

Warp in corrugated board, 0304-07

Corrugated boxes

see Boxes, Corrugated boards

Corrugated containers

see Boxes, Corrugated board, Folder gluers, Die cutters

Corrugated medium

An alternative method for designating flute sizes, 0302-04

Corrugating

An alternative method for designating flute sizes, 0302-04

Corrugating adhesives

see Adhesives

Corrugating machines

Checking the flute depth of corrugating rolls, 0304-75

Checking the parallel of corrugating rolls with "NCR" paper, 0304-62

Computer-assisted machinery, 0305-02

Conducting a corrugator temperature audit, 0304-65

Copper sulfate test for corrugator roll wear, 0304-53

Corrugator bearing clearance checks and their impact, 0304-47

Impact of doublebacker hot plate level on board quality and how to measure it, 0304-66

Improved techniques to measure corrugator glue machine meter gaps, 0304-68

Prevention of score cracking in a box plant, 0304-37

Procedure for setting up a raw material trial on the corrugator, 0304-01

Starch viscosity in corrugating adhesives, 0304-15

Corrugating medium

Causes and corrections of common corrugator bonding problems, 0304-32

Edge crush test (ECT): its relationship to box compression and its derivation from containerboard edge stiffness, 0304-09

Paper machine performance guidelines, 0404-47

Paper machine drying rate, 0404-07

Procedure for setting up a raw material trial on the corrugator, 0304-01

Splicer defects and cures, 0304-31

Corrugating plants

see Operations

Corrugating rolls

see Rolls

Corrugator-double backer

see *Corrugating machines*

Corrugators

see *Corrugating machines*

Costs

Press section economic evaluation, 0404-22

Cotton

In nonwovens, 1205-02

Couch rolls

Paper machine vacuum selection factors, 0502-01

Counters

Counter ejector section, 0305-44

Cracks

Guidelines for inspection and nondestructive examination of paper machine dryers, 0402-16

Guidelines for inspection of continuous digesters and impregnation vessels, 0402-27

Guidelines for nondestructive examination of suction roll shells, 0402-19

Inspection for cracking of composite tubes in black liquor recovery boilers, 0402-30

Crescent formers

Paper machine vacuum selection factors, 0502-01

Cross direction

Calculation and partitioning of variance using paper machine scanning sensor measurements, 1101-01

Statistical process control -- procedures for charting warp, 0304-13

Troubleshooting cross-machine direction moisture profile problems, 0404-57

Warp in corrugated board, 0304-07

Crown

see *Roll crown*

Crush

Calibration of flexible beam crush tester, 0304-20

Statistical process control techniques to assist in meeting specification at finishing crush process control points to the paper and paperboard industries, 0304-11

Cubical contents

see *Volumetry*

Curing

Drying and curing techniques for in-line flexographic printing, 0306-06

Curtain coating

Common curtain coating problems: causes, detection, and correction, 0304-26

Weight test, 0304-19

Cutters

see *Die cutters*

Cutting dies

see *Die cutters, Rotary machines*

D-**Damage**

Guidelines for inspecting used fiber-reinforced plastics (FRP) equipment, 0402-28

Dandy rolls

Dandy roll applications, 0404-53

Data storage

Calculation and partitioning of variance using paper

machine scanning sensor measurements, 1101-01

Data tables

Moisture content of paper: terminology and conversion, 0808-02

Deaerators

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Defects

Addendum to *Corrugating Defect Terminology Manual* -- defects related to the use of fingerless singlefacers, 0304-17

Corrugator bearing clearance checks and their impact, 0304-47

Guidelines for inspection and nondestructive examination of paper machine dryers, 0402-16

Definitions

see *Nomenclature*

Degradation

Guidelines for inspecting used fiber-reinforced plastics (FRP) equipment, 0402-28

Densified liners

see *Liners*

Density

Density of aqueous sodium bicarbonate solution, 0607-13

Density of aqueous sodium carbonate solution, 0607-14

Density of chlorine gas, 0606-03

Method for determining length and other properties in rolls of various diameters and basis weights, 1008-02

Milk of lime solution, 0607-05

Physical data of calcined kaolin-water suspensions, 0106-09

Physical data of calcium carbonate-water suspensions, 0106-01

Physical data of hydrous Kaolin-water suspensions, 0106-02

Sodium sulfite solution, 0607-18

Specific gravity and density of caustic soda solutions, 0606-20

Specific gravity of sodium chloride solutions, 0606-10

Deposits

Chloride and potassium measurement and control in the pulping and chemical recovery cycle, 0416-15

Estimating the first melting temperature of fireside deposits in recovery boilers, 0416-12

Keys to successful chemical cleaning of boilers, 0416-06

Deterioration

see *Degradation*

Dewatering

see *Drainage, Water removal*

Diameter

Roll diameter for various reel spool and roll core sizes, 0502-03

Dictionaries

see Nomenclature

Die cutters

see also Rotary machines

Buying, storing, and handling flexo folder gluer/rotary diecutter adhesives, 0305-25

Checklist: preparing die cuts for shipment, 0305-49

Cleanup procedures for flexo folder gluer/rotary diecutters, 0305-33

Troubleshooting the diecutting section, 0305-39

Drying and curing techniques for in-line flexographic printing, 0306-06

Introduction to flexo folder gluer/rotary diecutter TIPS, 0305-04

Minimizing rolling scores on lightweight and high-performance liners in diecutting operations, 0304-64

Ordering cutting dies, 0305-21

Project leader, 0305-13

Proper use of pull bands, 0305-18

Reduction or elimination of ink and/or varnish smear when printing and rotary die cutting in one pass, 0305-40

Rotary cutting die maintenance, 0305-23

Rotary diecutter urethane anvil maintenance, 0305-35

Squaring flap cut (center special) boxes, 0305-45

Dieboard

Multiple-out rotary diecut stacking, 0305-47

Stacking off the rotary diecutter, 0305-46

Diecut

Multiple-out rotary diecut stacking, 0305-47

Stacking off the rotary diecutter, 0305-46

Dielectric constant

Determination of moisture in containerboard using a hand held moisture meter, 0304-63

Differential steam pressures

see Pressure gradient

Digester balance equation

Recausticizing material balance equations relating to digester requirements, 0418-02

Digesters

Energy checklist: pulp mill, 0422-01

Guidelines for corrosion resistant weld metal overlay of digester vessels in alkaline pulping service, 0402-03

Guidelines for inspecting batch digesters, 0402-22

Guidelines for inspection of continuous digesters and impregnation vessels, 0402-27

Dimensional measurement

Calibration technique for the drum style chip thickness classifier, 0602-03

Dispersions

Physical data of calcined kaolin-water suspensions, 0106-09

Physical data of calcium carbonate-water suspensions, 0106-01

Physical data of hydrous Kaolin-water suspensions, 0106-02

Dissolved oxygen

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Dissolving pulps

Boiling point rise of spent sulfite liquors, 0607-21

Definitions of terms in the sulfite pulping process, 0607-25

Density of aqueous sodium sulfite solution, 0607-18

Density of milk of lime solution, 0607-05

Solubility of sulfur dioxide, $\text{Ca}(\text{HSO}_3)_2$ solutions, 0607-07

Sulfur burner gas strength volume, 0607-01

Viscosities of various spent sulfite liquors at 26.7°C, 0607-22

Doctor blades

Ink metering systems for corrugated flexo presses, 0306-09

Overview of the selection process for a laser engraved ceramic anilox roll, 0306-17

Documentation

Press fabric record book, 0404-21

Suggestions for developing a box plant quality manual, 0304-49

Documents

Daily and month-to-date status report, 0305-31

Purchase order, 0305-07

Doublefacers

Impact of doublebacker hot plate level on board quality and how to measure it, 0304-66

Splicer defects and cures, 0304-31

Doublewall corrugated boards

Causes and corrections of common corrugator bonding problems, 0304-32

Downtime

Daily and month-to-date status report, 0305-31

The need for planned maintenance, 0305-30

Drainage

Drainage evaluation by mass measurement, 0502-12

Fourdrinier drainage performance evaluation – blow test method, 0410-07

High vacuum sheet dewatering, 0404-60

Interconversion of freeness, 0809-01

Drainage factor

Interconversion of freeness, 0809-01

Dry bulb temperature

Relative humidity tables, 0808-06

Dry ends

Procedure for setting up a raw material trial on the corrugator, 0304-01

Dryer bars

see Dryers

Dryer condensing rates

see Dryers

Dryer felts

see also Felts

Dryer fabric cleaning, 0404-38

Recommended tensions in dryer fabrics, 0404-04

Dryer hoods

see Exhaust hoods

Dryer pockets

Recommended minimum dryer pocket air requirements, 0404-17

Troubleshooting cross-machine direction moisture profile problems, 0404-57

Dryer sections

Performance of, 0404-33

Recommended operation of dryer section hood air systems, 0404-24

Sheet handling devices, 0404-44

Dryers

Application of dryer bars, 0404-35

Dryer condensing rates (batch method), 0404-02

Dryer condensing rates (continuous method), 0404-03
Dryer condensing rates (vertical separator method), 0404-18

Dryer fabric cleaning, 0404-38

Dryer section performance monitoring, 0404-33

Dryer surface temperature measurement, 0404-39

Drying and curing techniques for in-line flexographic printing, 0306-06

Guidelines for inspection and nondestructive examination of paper machine dryers, 0402-16

High-velocity dryers, 0404-05

Increasing the steam pressure rating of ASME coded paper machine dryers, 0420-14

Paper machine drying rate, 0404-07

Papermaker's formulas, 0502-17

Press fabric record book, 0404-21

Recommended dryer differential pressures, 0404-31

Recommended minimum dryer pocket air requirements, 0404-17

Recommended operation of dryer section hood air systems, 0404-24

Recommended tensions in dryer fabrics, 0404-04

Steam shower applications in the forming section, 0404-58

Troubleshooting cross-machine direction moisture profile problems, 0404-57

Yankee dryer steam condensing rates, 0404-49

Drying

Dryer condensing rates (continuous method), 0404-03

Dryer condensing rates (vertical separator method), 0404-18

Dryer section performance monitoring, 0404-33

Drying and curing techniques for in-line flexographic printing, 0306-06

Paper machine drying rate, 0404-07

Through drying, 0404-25

Drying rate

see Drying

Dry-laid nonwovens

Pilot paper machines, 0502-16

Duplex stainless steel

see Stainless steel

Dust

Paper machine room ventilation guidelines, 0404-50

E-**Economics**

Press section economic evaluation, 0404-22

Economizers

Guideline specification for procurement of an economizer for a recovery boiler, 0416-21

Guidelines for operating and maintenance practices impacting an economizer on a recovery boiler, 0416-22

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Edge crush tests (ECT)

Calibration of flexible beam crush tester, 0304-20

Edge crush test (ECT): its relationship to box compression and its derivation from containerboard edge stiffness, 0304-09

Efficiency

Index of suppliers for press section monitoring, 0404-62

Paper machine performance guidelines, 0404-47

Press section monitoring, 0404-19

Recovery boiler energy efficiency improvements, 0416-16

Water treatment-related opportunities for energy conservation in a paper mill powerhouse, 0416-13

Elliptical technique

Guideline for obtaining high quality radiographic testing of butt welds in boiler tubes, 0402-33

Employee injuries

see Human factors

Energy

Checklist: pulp mill, 0422-01

Paper machine energy conservation, 0404-63

Recovery boiler energy efficiency improvements, 0416-16

Water treatment-related opportunities for energy conservation in a paper mill powerhouse, 0416-13

Energy conservation

Paper machine room ventilation guidelines, 0404-50

Recommended operation of dryer section hood air systems, 0404-24

Enthalpy

Relative enthalpy (heat content) of sodium hydroxide solutions, 0606-08

Environmental factors

see Environments

Environments

Caustic soda (NaOH) safe storage and handling, 0606-27

Chlorine dioxide (ClO₂) safe storage and handling,

- 0606-1
 Gaseous ozone (O₃) safe handling, 0606-28
 Hydrogen peroxide (H₂O₂) safe storage and handling, 0606-24
 Methanol (CH₃OH) safe storage and handling, 0606-25
 Oxygen (O₂) bulk storage and safe handling, 0606-29
 Sodium chlorate (NaClO₃) safe handling and storage
 Sulfuric acid (H₂SO₄) safe storage and handling, 0606-26
- Equations**
 Papermaker's formulas, 0502-17
- Equilibrium**
 Relative humidities over saturated salt solutions, 0808-03
- Equipment**
 Starch adhesive trial, 0304-22
 Quality techniques using existing equipment, 0306-11
- Ergonomics**
see Human factors
- Erosion**
 Nozzle maintenance and clogging, 0420-15
- Evaluation**
see also Performance
 Drainage evaluation by mass measurement, 0502-12
- Evaporation**
see Drying
- Evaporators**
 Energy checklist: pulp mill, 0422-01
 Recommended test procedure for black liquor evaporators, 0416-11
- Exhaust gas**
 Paper machine room ventilation guidelines, 0404-50
- Exhaust hoods**
 Recommended operation of dryer section hood air systems, 0404-24
- F-**
- Fabric**
see Forming fabrics, Dryer felts
- Fan pumps**
 Headbox approach piping guidelines, 0404-54
- Feed section**
see Feeding
- Feedback control**
see Control systems
- Feeders**
 Material handling considerations for flexo folder gluers, 0305-54
- Feedwater**
 Design engineer decisions tree: paper mill boiler feedwater, 0416-04
 Evaluating reverse osmosis for treating makeup to the boiler feedwater in a pulp and paper mill, 0416-07
 Response to contamination of high purity boiler feedwater, 0416-05
 Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03
 Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14
- Felts**
see also Press felts
 Dryer fabric cleaning, 0404-38
 Methods to minimize sheet rewet in the press section, 0404-59
 Porosity measurement of press felts on the paper machine (HSPT), 0404-29
 Press fabric record book, 0404-21
 Troubleshooting cross-machine direction moisture profile problems, 0404-57
 Water permeability of press fabrics, 0404-43
- Fiber length**
 Cotton in nonwovens, 1205-02
- Fiberboards**
see Boxes, Corrugated boards
- Fiberglass-reinforced plastic**
see Plastic
- Field tests**
see Test methods
- Film**
 Quality techniques using existing equipment, 0306-11
- Filters**
 Paper machine room ventilation guidelines, 0404-50
- Fine papers**
 Paper machine drying rate, 0404-07
 Paper machine performance guidelines, 0404-47
- Fingerless singlefacers**
see Singlefacers
- Fingerprints**
 Quality techniques using existing equipment, 0306-11
- Flaps**
 Squaring flap cut (center special) boxes, 0305-45
 Understanding and troubleshooting hot melt adhesives, 0304-74
- Flat boxes**
see Vacuum boxes
- Flat crush tests**
 Calibration of flexible beam crush tester, 0304-20
- Flexibility**
 Calibration of flexible beam crush tester, 0304-20
- Flexible beam crush tester**
 Calibration of flexible beam crush tester, 0304-20
- Flexo folder-gluers**
see Folder gluers, Die cutters, Rotary machines
- Flexo ink**
 Printing section, 0305-38
- Flexography**
 Cleaning anilox rolls: procedures and options, 0306-18
 Guide to proper wipe roll selection for the corrugated box industry, 0306-20
 Identifying anilox roll volume measuring equipment, 0306-15

Ink metering systems for corrugated flexo presses, 0306-09

Quality techniques using existing equipment, 0306-11

Overview of the selection process for a laser engraved ceramic anilox roll, 0306-17

Viscosity reading procedure for flexographic corrugated inks, 0304-18

Flow

Generalized method for determining the pipe friction loss of lowing pulp suspensions, 0410-14

Paper machine shower recommendations, 0404-61

Flow charts

Introduction to the flow chart, 0305-26

Flow measurement

Flow determination by chemical method, 0410-09

Weirs and flumes, 0410-10

Flow rates

see Flow measurement

Flumes

Weirs and flumes, 0410-10

Flutes

An alternative method for designating flute sizes, 0302-04

Fogging

Steam shower applications in the forming section, 0404-58

Folder gluers

Buying, storing, and handling flexo folder gluer/rotary diecutter adhesives, 0305-25

Cleanup procedures for flexo folder gluer/rotary diecutters, 0305-33

Counter ejector section, 0305-44

Extruded glue mechanism supplement, 0305-43

Folding section, 0305-42

Introduction to flexo folder gluer/rotary diecutter TIPs, 0305-04

Installation, 0305-12

Machinery considerations and selection: yoked scoring slotting section, 0305-53

Material handling considerations for flexo folder gluers, 0305-54

Computer assisted mounting systems, 0306-02

Project leader, 0305-13

Proper use of pull bands, 0305-18

Reduction or elimination of ink and/or varnish smear when printing and rotary die cutting in one pass, 0305-40

Squaring flap cut (center special) boxes, 0305-45

Folding

Folding section, 0305-42

Formaldehyde

Understanding formaldehyde management, 0304-25

Formation

Dandy roll applications, 0404-53

Forming

Forming section monitoring, 0502-14

Paper machine shower recommendations, 0404-61

Steam shower applications in the forming section, 0404-58

Forming fabrics

Drainage evaluation by mass measurement, 0502-12

Forming section monitoring, 0502-14

Methods to minimize sheet rewet in the press section, 0404-59

Paper machine clothing cleaning and conditioning for recycled fiber use, 0404-51

Paper machine vacuum selection factors, 0502-01

Physical characterization of press fabrics: basis weight, air permeability, void volume under loading and pressure uniformity, 0404-20

Press fabric dewatering and conditioning – suction box (Uhle box) design and vacuum requirements. 0404-27

Forming sections

Fourdrinier drainage performance evaluation – blow test method, 0410-07

Troubleshooting cross-machine direction moisture profile problems, 0404-57

Fourdrinier machines

Drainage performance evaluation – blow test method, 0410-07

Papermaker's formulas, 0502-17

Free sheet

Paper machine drying rate, 0404-07

Freeness

Interconversion of, 0809-01

Friction

Generalized method for determining the pipe friction loss of lowing pulp suspensions, 0410-14

Friction factor

Statistical process control friction - slide angle, 0304-34

Furnaces

see Recovery furnaces

G-

Gas

Collection and burning of concentrated noncondensable gases: regulations, design and operation, 0416-09

Gauges

see Measuring instruments

Gel temperature

see Gels

Gelatinization temperature

see Gels

Gels

Some questions and answers on gel temperatures and on the gel temperature test for corrugating adhesives, 0304-08

Statistical process control of starch gelatinization temperature, 0304-14

Gin notes

see Cotton

Ginning

see Cotton

Glass fibers

Guidelines for inspecting used fiber-reinforced

plastics (FRP) equipment, 0402-28

Glossaries

see Nomenclature

Glue

Evaluating glue lap adhesives, 0304-16

Extruded glue mechanism supplement, 0305-43

Folding section, 0305-42

Glue lap

see Glued joints

Glue machine

see Gluers

Glue pattern

see Gluing

Glued joints

Troubleshooting a glue lap problem, 0304-10

Gluers

Causes and corrections of common corrugator bonding problems, 0304-32

How to prevent score cracking in a box plant, 0304-37

Improved techniques to measure corrugator glue machine meter gaps, 0304-68

Procedure for setting up a raw material trial on the corrugator, 0304-01

Some questions and answers on gel temperatures and on the gel temperature test for corrugating adhesives, 0304-08

Troubleshooting a glue lap problem, 0304-10

Gluing

Addendum to *Corrugating Defect Terminology Manual* - defects related to the use of fingerless singlefacers, 0304-17

Gluing machines

see Gluers

Grab truck

see Lift trucks

Granite

Roll material and surface requirements, 0404-41

Green liquors

Recausticizing material balance equations relating to digester requirements, 0418-02

Grinders

Grinder pulpstones – cubical contents, 0605-01

Pulpstone speed chart, 0605-02

Grinding

Granite roll material and surface requirements, 0404-41

Grooved rolls

Press roll cover application guidelines, 0404-37

Ground calcium carbonate (GCC)

see Calcium carbonate

Guides

Press fabric guiding, 0404-64

Guide rolls

Press fabric guiding, 0404-64

H-

Halogens

see specific term, e.g., Chlorine

Hardness

Response to contamination of high purity boiler feedwater, 0416-05

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Hazards

Corrugated boxplant-list of potential hazards, 0301-01

Material safety data sheets, what to look for - how to understand them, 0304-38

Hazardous materials

Collection and burning of concentrated noncondensable gases: regulations, design and operation, 0416-09

Formaldehyde management, 0304-25

Material safety data sheets – what to look for, how to understand them, 0304-38

Stripping of kraft pulping process condensates: regulations, design and operation, 0416-10

Understanding hazardous materials warning labels, 0304-41

Headboxes

Flow from a 45° slice, 0410-03

Flow from a nozzle (slice) with inclined upper lip, 0410-04

Flow from a vertical slice, 0410-02

Head of stock behind slice (head/jet relationships), 0410-05

Papermaker's formulas, 0502-17

Heat

Paper machine room ventilation guidelines, 0404-50

Heat content

see Enthalpy

Heat of vaporization

Liquid chlorine, 0606-04

Heat recovery

Paper machine room ventilation guidelines, 0404-50

Heat transfer

Application of dryer bars, 0404-35

Recommended test procedure for black liquor evaporators, 0416-11

Heat transfer coefficient

Recommended test procedure for black liquor evaporators, 0416-11

Heating

Conducting a corrugator temperature audit, 0304-65

Heating equipment

Steam shower applications in the forming section, 0404-58

Heavy metals

see Metals

High density

High density liners...what are they?, 0304-43

High density liners

see Liners

High intensity presses

Terminology for high temperature pressing, 0404-48

High performance liners

see Liners

High temperature

Terminology for high temperature pressing, 0404-48

High vacuum

High vacuum sheet dewatering, 0404-60

Hoods

Recommended operation of dryer section hood air systems, 0404-24

Hot melts

Understanding and troubleshooting hot melt adhesives, 0304-74

Hot pressing

Terminology for high temperature pressing, 0404-48

Housekeeping

see Maintenance, Cleaning

Humidity

Dryer section performance monitoring, 0404-33

Equilibrium relative humidities over saturated salt solutions, 0808-03

Psychrometric charts, 0404-45

Recommended minimum dryer pocket air requirements, 0404-17

Recommended operation of dryer section hood air systems, 0404-24

Relative humidity tables, 0808-06

Testing atmospheres simulating end use conditions, 0808-05

Troubleshooting cross-machine direction moisture profile problems, 0404-57

Humidity measurement

Relative humidity tables, 0808-06

Humidity rooms

Paper test rooms: design considerations, 0808-04

Hydrocyclones

Introduction to centrifugal cleaners, 0508-10

Hydrogen peroxide

Hydrogen peroxide (H₂O₂) safe storage and handling, 0606-24

Hydroxides

Definitions of terms in the sulfite pulping process, 0607-25

Density of aqueous sodium sulfite solution, 0607-18

Density of milk of lime solution, 0607-05

Solubility of sulfur dioxide, Ca(HSO₃)₂ solutions, 0607-07

Sulfur burner gas strength volume, 0607-01

Hypochlorite bleaching

see Hypochlorites, Bleaching

I-

Illumination

Basic guidelines for image analysis measurements, 0804-09

Image analysis

Basic guidelines for image analysis measurements, 0804-09

Image quality

Guideline for obtaining high quality radiographic

testing of butt welds in boiler tubes, 0402-33

Impregnation

Guidelines for inspection of continuous digesters and impregnation vessels, 0402-27

Impulse drying

see Drying

Impurities

Dryer fabric cleaning, 0404-38

Paper machine clothing cleaning and conditioning for recycled fiber use, 0404-51

In-process checklist

see Production

Infiltration

Paper machine room ventilation guidelines, 0404-50

Infrared detectors

Troubleshooting cross-machine direction moisture profile problems, 0404-57

Infrared dryers

Drying and curing techniques for in-line flexographic printing, 0306-06

Ink

Copper in a printing ink, 0304-61

Guideline for direct contact printing of bar code symbols on corrugated, 0306-16

Ink metering systems for corrugated flexo presses, 0306-09

Proofing a flexo printing ink, 0304-60

Quality parameters of a printing ink, 0304-59

Quality techniques using existing equipment, 0306-

11

Reduction or elimination of ink and/or varnish smear when printing and rotary die cutting in one pass, 0305-40

Viscosity reading procedure for flexographic corrugated inks, 0304-18

Inorganic salts

Equilibrium relative humidities over saturated salt solutions, 0808-03

Inspection

Guidelines for inspecting batch digesters, 0402-22

Guidelines for specification and inspection of electric resistance welded (ERW) and seamless boiler tube for critical and noncritical service, 0402-13

Inspecting used fiber-reinforced plastics (FRP) equipment, 0402-28

Inspection and nondestructive examination of paper machine dryers, 0402-16

Inspection of continuous digesters and impregnation vessels, 0402-27

Inspection for cracking of composite tubes in black liquor recovery boilers, 0402-30

Nondestructive examination of suction roll shells, 0402-19

Paper machine reel spool journals: guidelines for the in-service inspection to detect cracking and repair/replacement considerations, 0402-34

Ultrasonic technician performance test for boiler tube inspection, 0402-21

Welding and inspection of stainless alloy piping, 0402-26

Installation

Flexo folder gluers, 0305-12

Project leader, 0305-13

Instrumentation

Index of suppliers for press section monitoring, 0404-62

Press section monitoring, 0404-19

Instruments

Forming section monitoring, 0502-14

Intensity

Conical refining intensity, 0508-07

Internal bond strength

Troubleshooting a glue lap problem, 0304-10

Iron

Response to contamination of high purity boiler feedwater, 0416-05

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

J-

Jet dryers

Methods of evaluating high velocity dryers, 0404-05

Jet velocity

Head of stock behind slice (head/jet relationship), 0410-05

Jets

Flow from a 45° slice, 0410-03

Flow from a nozzle (slice) with inclined upper lip, 0410-04

Flow from a vertical slice, 0410-02

Joints

Troubleshooting a glue lap problem, 0304-10

Jordans

see Conical refiners

Jumbo rolls

Reel diameter for various reel spool and roll core sizes, 0502-03

K-

Kaolin

Kaolin clay pigment index, 0106-06

Kraft papers

Paper machine drying rate, 0404-07

Kraft pulping

Stripping of kraft pulping process condensates: regulations, design and operation, 0416-10

L-

Labels

Understanding hazardous materials warning labels, 0304-41

Laboratories

Paper test rooms: design considerations, 0808-04

Lead

An explanation of the CONEG heavy metal guidelines, 0304-58

Leakage

Collection and burning of concentrated noncondensable gases: regulations, design and operation, 0416-09

Lignosulfonates

Boiling point rise of spent sulfite liquors, 0607-21

Definitions of terms in the sulfite pulping process, 0607-25

Density of aqueous sodium sulfite solution, 0607-18

Density of milk of lime solution, 0607-05

Solubility of sulfur dioxide, Ca(HSO₃)₂ solutions, 0607-07

Sulfur burner gas strength volume, 0607-01

Viscosities of various spent sulfite liquors at 26.7°C, 0607-22

Lime mud

see White liquor mud

Lime-base solutions

see Calcium base liquors

Limestone

Calcium carbonate pigment index, 0106-05

Linerboards

Paper machine drying rate, 0404-07

Liners

Causes and corrections of common corrugator bonding problems, 0304-32

Edge crush test (ECT): its relationship to box compression and its derivation from containerboard edge stiffness, 0304-09

High density liners...what are they?, 0304-43

How to minimize rolling scores on lightweight and high-performance liners in diecutting operations, 0304-64

Paper machine performance guidelines, 0404-47

Procedure for setting up a raw material trial on the corrugator, 0304-01

Splicer defects and cures, 0304-31

Techniques for bonding of densified liners, 0304-40

Linters

Cotton in nonwovens, 1205-02

M-

Machine clothing

Paper machine clothing cleaning and conditioning for recycled fiber use, 0404-51

Machine direction

Calculation and partitioning of variance using paper machine scanning sensor measurements, 1101-01

Machine operation

see also Maintenance

Project leader, 0305-13

Machine rooms

Paper machine room ventilation guidelines, 0404-50

Machine speed

Pulpstone speed chart, 0605-02

Machinery

- Computer-assisted machinery, 0305-02
- Machinery considerations and selection, 0305-06
- Project leader, 0305-13

Magnesia

see Magnesium oxide

Magnesium bisulfite

Solubility of sulfur dioxide in saturated magnesium bisulfite solution, 0607-10

Magnesium bisulfite liquor

see Magnesium base liquors

Magnesium oxide

Physical and chemical properties of magnesia-base pulping solutions, 0607-04

Solubility of sulfur dioxide in magnesium bisulfite solution, 0607-09

Maintenance

- Burst testers, 0304-24
- Calibration and maintenance of the manually operated micrometer, 0304-30
- Checking for coating wear on corrugating rolls, 0304-73
 - Checking the flute depth of corrugating rolls, 0304-75
 - Checking the parallel of corrugating rolls with "NCR" paper, 0304-62
 - Cleaning anilox rolls: procedures and options, 0306-18
 - Cleanup procedures for flexo folder gluer/rotary diecutters, 0305-33
 - Computer-assisted machinery, 0305-02
 - Copper sulfate test for corrugator roll wear, 0304-53
 - Counter ejector section, 0305-44
 - Daily, weekly, and monthly maintenance checklists, 0305-34
 - Extruded glue mechanism supplement, 0305-43
 - Field welding of pin studs in black liquor recovery boilers, 0402-15
 - Guidelines for operating and maintenance practices impacting an economizer on a recovery boiler, 0416-22
 - Housekeeping at order and shift change and weekly, 0305-32
 - Need for planned maintenance, 0305-30
 - Nozzle maintenance and clogging, 0420-15
 - Rotary cutting die maintenance, 0305-23
 - Rotary diecutter urethane anvil maintenance, 0305-35
 - Troubleshooting a glue lap problem, 0304-10
 - Weld repairs on new suction roll shells, 0402-17

Management

- Project leader, 0305-13

Manuals

Suggestions for developing a box plant quality manual, 0304-49

Manufacturers joints

- Evaluating glue lap adhesives, 0304-16
- Folding section, 0305-42
- Go/no go gauge devices for the boxplant, 0304-42

Mass

- Drainage evaluation by mass measurement, 0502-12

Material safety data sheets

see Safety

Materials

Oxygen (O₂) bulk storage and safe handling, 0606-29

Materials balance

Paper machine room ventilation guidelines, 0404-50

Materials handling

- Caustic soda (NaOH) safe storage and handling, 0606-27
- Gaseous ozone (O₃) safe handling, 0606-28
- Hydrogen peroxide (H₂O₂) safe storage and handling, 0606-24
- Material safety data sheets – what to look for, how to understand them, 0304-38
- Methanol (CH₃OH) safe storage and handling, 0606-25
- Oxygen (O₂) bulk storage and safe handling, 0606-29

McKee equation

see Edge crush tests

Measurement

- Conducting a corrugator temperature audit, 0304-65
- Drainage evaluation by mass measurement, 0502-12
- Dryer condensing rates (continuous method), 0404-03
- Troubleshooting cross-machine direction moisture profile problems, 0404-57
- Units of and conversion factors, 0800-01
- Utilizing statistical process control techniques to assist in meeting specification at finishing crush process control points to the paper and paperboard industries, 0304-11

Measuring instruments

Gauge repeatability and reproducibility study, 0304-71

Mechanical papers

Paper machine drying rate, 0404-07

Medium

see Corrugating medium

Melting point

Estimating the first melting temperature of fireside deposits in recovery boilers, 0416-12

Mercury

CONEG heavy metal guidelines, 0304-58

Metals

- An explanation of the CONEG heavy metal guidelines, 0304-58
- Clad-steel plate use, 0402-04
- Field welding of pin studs in black liquor recovery boilers, 0402-15

Metering equipment

Ink metering systems for corrugated flexo presses, 0306-09

Methanol

Methanol (CH₃OH) safe storage and handling, 0606-25

Microbes

see Bacteria

Micrometers

Calibration and maintenance of the manually operated micrometer, 0304-30

Milk of lime solution

see Calcium hydroxide

Moisture

Determination of moisture in containerboard using a hand held moisture meter, 0304-63

Determination of water removal by wet presses, 0404-01

Moisture content of paper: terminology and conversion, 0808-02

Steam shower applications in the forming section, 0404-58

Moisture content

Determination of water removal by wet presses, 0404-01

Psychrometric charts, 0404-45

Troubleshooting cross-machine direction moisture profile problems, 0404-57

Moisture control

Cotton in nonwovens, 1205-02

Troubleshooting cross-machine direction moisture profile problems, 0404-57

Warp in corrugated board, 0304-07

Moisture regain

see Moisture content, Sorption

Monitoring

Index of suppliers for press section monitoring, 0404-62

Press section monitoring, 0404-19

Monitors

Forming section monitoring, 0502-14

Paper test rooms: design considerations, 0808-04

Monosulfite

see Neutral sulfite pulping

Motors

Paper machine room ventilation guidelines, 0404-50

Mounting

Computer assisted mounting systems, 0306-02

Mullen

see Burst strength

Multistage process

see Bleaching

N-

Needle punched

see Needling

Needling

Cotton in nonwovens, 1205-02

Neutral sulfite liquors

Viscosity of a neutral sulfite spent liquor (Ostwald capillary viscometer), 0607-23

Neutral sulfite pulping

Boiling point rise of spent sulfite liquors, 0607-21

Definitions of terms in the sulfite pulping process, 0607-25

Density of aqueous sodium sulfite solution, 0607-18

Density of milk of lime solution, 0607-05

Physical and chemical properties of magnesia-base pulping solutions, 0607-04

Solubility of sulfur dioxide, 0607-06

Solubility of sulfur dioxide, Ca(HSO₃)₂ solutions, 0607-07

Solubility of sulfur dioxide in magnesium bisulfite solution, 0607-09

Sulfur burner gas strength volume, 0607-01

Viscosities of various spent sulfite liquors at 26.7°C, 0607-22

Newsprint

Paper machine drying rate, 0404-07

Paper machine performance guidelines, 0404-47

Weight of newsprint rolls, 0502-11

Nickel

Guidelines for welding and inspection of stainless alloy piping, 0402-26

Nip

Methods to minimize sheet rewet in the press section, 0404-59

Troubleshooting cross-machine direction moisture profile problems, 0404-57

Nip pressure

see Nip

Nomenclature

Recommended pulp bleaching stage designation method, 0606-21

Retention definitions, 0402-13

Moisture content of paper: terminology and conversion, 0808-02

Sulfite pulping process, 0607-25

Terminology for high temperature pressing, 0404-48

Noncondensibles

Collection and burning of concentrated noncondensable gases: regulations, design and operation, 0416-09

Nondestructive tests

Guide to the use of stainless steel pipe specifications, 0402-24

Guidelines for corrosion resistant weld metal overlay of digester vessels in alkaline pulping service, 0402-03

Guidelines for specification and inspection of electric resistance welded (ERW) and seamless boiler tube for critical and noncritical service, 0402-13

Drainage evaluation by mass measurement, 0502-12

Guidelines for evaluating quality of boiler tube butt welds with ultrasonic testing, 0402-31

Inspection of continuous digesters and impregnation vessels, 0402-27

Inspection and nondestructive examination of paper machine dryers, 0402-16

Inspection for cracking of composite tubes in black liquor recovery boilers, 0402-30

Liquid penetrant testing of new suction roll shells, 0402-11

Nondestructive examination of suction roll shells, 0402-19

Paper machine reel spool journals: guidelines for

the in-service inspection to detect cracking and repair/replacement considerations, 0402-34

Ultrasonic technician performance test for boiler tube inspection, 0402-21

Nonwovens

Cotton in, 1205-02

Pilot paper machines, 0502-16

Nonwovens machines

Pilot paper machines, 0502-16

Nozzles

Nozzle maintenance and clogging, 0420-15

Paper machine shower recommendations, 0404-61

NSSC pulping

Viscosity of a neutral sulfite spent liquor (Ostwald capillary viscometer), 0607-23

O-

Opacifiers

Physical data of calcium carbonate-water suspensions, 0106-01

Opacity

Titanium dioxide pigment index, 0106-07

Open time

Troubleshooting a glue lap problem, 0304-10

Openings

Measurement of vacuum pump air flow, 0420-12

Operations

Guidelines for operating and maintenance practices impacting an economizer on a recovery boiler, 0416-22

Machinery considerations and selection, 0305-06

Optical measurement

Basic guidelines for image analysis measurements, 0804-09

Optimization

Press section optimization, 0404-52

Orifices

see Openings

Osmosis

Evaluating reverse osmosis for treating makeup to the boiler feedwater in a pulp and paper mill, 0416-07

Overlays

Guidelines for corrosion resistant weld metal overlay of digester vessels in alkaline pulping service, 0402-03

Guidelines for inspecting batch digesters, 0402-22

Oxygen

Bulk storage and safe handling of, 0606-29

Ozone

Safe handling of gaseous, 0606-28

P-

Packaging

CONEG heavy metal guidelines, 0304-58

Understanding and troubleshooting hot melt adhesives, 0304-74

Palletization

Checklist: preparing die cuts for shipment, 0305-49

Material handling considerations for flexo folder gluers, 0305-54

Paper

Moisture content of paper: terminology and conversion, 0808-02

Paper grade classifications, 0404-36

Through drying, 0404-25

Paper grades

Paper grade classifications, 0404-36

Paper machines

Increasing the steam pressure rating of ASME coded paper machine dryers, 0420-14

Index of suppliers for press section monitoring, 0404-62

Paper machine clothing performance analysis, 0404-26

Paper machine energy conservation, 0404-63

Paper machine performance guidelines, 0404-47

Paper machine reel spool journals: guidelines for the in-service inspection to detect cracking and repair/replacement considerations, 0402-34

Papermaker's formulas, 0502-17

Performance evaluation techniques for paper machine vacuum systems, 0404-55

Pilot paper machines, 0502-16

Press section monitoring, 0404-19

Recommended operation of dryer section hood air systems, 0404-24

Water permeability of press fabrics, 0404-43

Paper mills

Design engineer decisions tree: paper mill boiler feedwater, 0416-04

Paper rolls

see Rolls, Wound rolls

Paper stock

Guidelines for side-entering stock agitators, 0420-13

Papermakers alum

see Aluminum sulfate

Paraffin wax

Common curtain coating problems: causes, detection, and correction, 0304-26

Papermaking

Papermaker's formulas, 0502-17

Parallelism

see Alignment

Parameters

Paper machine performance guidelines, 0404-47

Peel tests

Green peel bond test at the corrugator, 0304-27

Penetrants

Liquid penetrant testing of new suction roll shells, 0402-11

Performance

Dryer section performance monitoring, 0404-33

Paper machine clothing performance analysis, 0404-26

Paper machine room ventilation guidelines, 0404-50

Press fabric record book, 0404-21

Press section economic evaluation, 0404-22

Press section optimization, 0404-52

Recovery boiler performance calculation – short

form, 0416-01

Performance evaluation

Methods of evaluating high velocity dryers, 0404-05

Paper machine performance guidelines, 0404-47

Performance evaluation techniques for paper machine vacuum systems, 0404-55

Performance tests

Performance test procedure for boilers using biomass as fuel, 0416-18

Sampling procedures for biomass fuel for boiler performance testing, 0416-17

Ultrasonic technician performance test for boiler tube inspection, 0402-21

Permeability

Water permeability of press fabrics, 0404-43

Personnel

Project leader, 0305-13

Petroleum wax

see Paraffin wax

pH

Response to contamination of high purity boiler feedwater, 0416-05

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Phosphates

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Physical properties

Chlorine dioxide (ClO₂) safe storage and handling, 0606-10

Chlorine gas curve, 0606-02

Density of chlorine gas, 0606-03

Heat of vaporization of liquid chlorine, 0606-04

Magnesia-base pulping solutions, 0607-04

Relative enthalpy (heat content) of sodium hydroxide solutions, 0606-08

Sodium chlorate (NaClO₃) safe handling and storage

Specific gravity and density of caustic soda solutions, 0606-20

Specific gravity of sodium chloride solutions, 0606-10

Viscosity of liquid chlorine, 0606-05

Viscosity of sodium hydroxide solutions, 0606-11

Pigment

Calcium carbonate pigment index, 0106-05

Kaolin clay pigment index, 0106-06

Physical data of calcium carbonate-water suspensions, 0106-01

Titanium dioxide pigment index, 0106-07

Pilot paper machines

see Paper machines

Pilot plants

Pilot paper machines, 0502-16

Pin adhesion tests

Statistical process control pin adhesion, 0304-23

Pin register

see Register

Pin register mounting

see Register, Mounting

Pin studs

see Welding

Pipelines

Optimum consistency for pumping pulp, 0410-15

Piping

Generalized method for determining the pipe friction loss of lowing pulp suspensions, 0410-14

Guide to the use of stainless steel pipe specifications, 0402-24

Guidelines for welding and inspection of stainless alloy piping, 0402-26

Headbox approach piping guidelines, 0404-54

Planning

Checklist for a properly planned project, 0408-01

Installation, 0305-12

Project leader, 0305-13

Plastics

Guidelines for inspecting used fiber-reinforced plastics (FRP) equipment, 0402-28

Refiner systems, their inspection and maintenance, 0508-06

Plates

see also Printing plates, Refiner disks

Clad-steel plate use, 0402-04

Conducting a corrugator temperature audit, 0304-65

Impact of doublebacker hot plate level on board quality and how to measure it, 0304-66

Plugging

Estimating the first melting temperature of fireside deposits in recovery boilers, 0416-12

Pocket humidity

see Humidity

Polyurethanes

Press roll cover application guidelines, 0404-37

Porosity

Porosity measurement of press felts on the paper machine (HSPT), 0404-29

Water permeability of press fabrics, 0404-43

Potassium

Chloride and potassium measurement and control in the pulping and chemical recovery cycle, 0416-15

Estimating the first melting temperature of fireside deposits in recovery boilers, 0416-12

Power plants

Water treatment-related opportunities for energy conservation in a paper mill powerhouse, 0416-13

Precipitated calcium carbonate (PCC)

see Calcium carbonate

Precipitators

Chloride and potassium measurement and control in the pulping and chemical recovery cycle, 0416-15

Estimating the first melting temperature of fireside deposits in recovery boilers, 0416-12

Prefeeder

see Feeders

Preservatives

Starch adhesive preparation and distribution systems: housekeeping, 0304-06

Press

Methods to minimize sheet rewet in the press section, 0404-59

Multiple-out rotary diecut stacking, 0305-47

Stacking off the rotary diecutter, 0305-46

Press drying

see also Drying

Terminology for high temperature pressing, 0404-48

Press fabrics

Press fabric guiding, 0404-64

Dewatering and conditioning – suction box (Uhle box) design and vacuum requirements, 0404-27

Press felts

see also Felts

Physical characterization of press fabrics: basis weight, air permeability, void volume under loading and pressure uniformity, 0404-20

Porosity measurement of press felts on the paper machine (HSPT), 0404-29

Press fabric guiding, 0404-64

Thickness of wet press fabrics, 0404-28

Water permeability of press fabrics, 0404-43

Press rolls

Granite roll material and surface requirements, 0404-41

Press roll cover application guidelines, 0404-37

Weld repairs on new suction roll shells, 0402-17

Press sections

Determination of water removal by wet presses, 0404-01

Index of suppliers for press section monitoring, 0404-62

Press section economic evaluation, 0404-22

Press section monitoring, 0404-19

Press section optimization, 0404-52

Sheet handling devices, 0404-44

Steam shower applications in the forming and press section, 0404-58

Water permeability of press fabrics, 0404-43

Presses

Papermaker's formulas, 0502-17

Pressing

Physical characterization of press fabrics: basis weight, air permeability, void volume under loading and pressure uniformity, 0404-20

Methods to minimize sheet rewet in the press section, 0404-59

Paper machine shower recommendations, 0404-61

Pressure

Increasing the steam pressure rating of ASME coded paper machine dryers, 0420-14

Pressure control

Increasing the steam pressure rating of ASME coded paper machine dryers, 0420-14

Pressure gradient

Recommended dryer differential pressures, 0404-31

Pressure roll

Paper machine vacuum selection factors, 0502-01

Preventative maintenance

see Maintenance

Print section

Printing section, 0305-38

Printing

Copper in a printing ink, 0304-61

Guide to proper wipe roll selection for the corrugated box industry, 0306-20

Guideline for direct contact printing of bar code symbols on corrugated, 0306-16

Important quality parameters of a printing ink, 0304-59

In-process checklist, 0305-27

Proofing a flexo printing ink, 0304-60

Proper use of pull bands, 0305-18

Quality techniques using existing equipment, 0306-11

Reduction or elimination of ink and/or varnish smear when printing and rotary die cutting in one pass, 0305-40

Overview of the selection process for a laser engraved ceramic anilox roll, 0306-17

Printing cylinders

Cleaning anilox rolls: procedures and options, 0306-18

Identifying anilox roll volume measuring equipment, 0306-15

Overview of the selection process for a laser engraved ceramic anilox roll, 0306-17

Printing ink

see Ink

Printing papers

Paper machine drying rate, 0404-07

Printing plates

Guideline for direct contact printing of bar code symbols on corrugated, 0306-16

Computer assisted mounting systems, 0306-02

Quality techniques using existing equipment, 0306-11

Printing section, 0305-38

Printing proofs

Method to proof a flexo printing ink, 0304-60

Process control

Obtaining combined board caliper off the corrugator for use in statistical procedures, 0304-12

Short-run statistical process control: a basic charting method, 0304-70

Starch viscosity in corrugating adhesives, 0304-15

Statistical of starch gelatinization temperature, 0304-14

Statistical process control friction-slide angle, 0304-34

Statistical process control -- procedures for charting warp, 0304-13

Processes

In-process checklist, 0305-27

Introduction to the flow chart, 0305-26

Product codes

Guideline for direct contact printing of bar code symbols on corrugated, 0306-16

Production

Daily and month-to-date status report, 0305-31

In-process checklist, 0305-27

Papermaker's formulas, 0502-17

Production control

In-process checklist, 0305-27

Profiles

Troubleshooting cross-machine direction moisture profile problems, 0404-57

Steam shower applications in the forming section, 0404-58

Project planning

see Planning

Projects

see Planning

Protective coatings

Guidelines for applying thermal spray coatings to protect pulp mill process equipment against corrosion, 0402-32

Psychrometric charts

see also Humidity

Psychrometric charts, 0404-45

Pull collars

Troubleshooting the diecutting section, 0305-39

Pull rolls

Printing section, 0305-38

Pulp mill equipment

Guidelines for applying thermal spray coatings to protect pulp mill process equipment against corrosion, 0402-32

Pulp mills

Energy checklist, 0422-01

Pulping

Density of chlorine gas, 0606-03

Pulpstones

Grinder pulpstones: cubical contents, 0605-01

Pulpstone speed chart, 0605-02

Pulps

Generalized method for determining the pipe friction loss of lowing pulp suspensions, 0410-14

Optimum consistency for pumping, 0410-15

Paper machine drying rate, 0404-07

Pumping

Generalized method for determining the pipe friction loss of lowing pulp suspensions, 0410-14

Pulp, optimum consistency for, 0410-15

Pumps

Guidelines for procurement of cast stainless steels for large pumps and valves for the pulp and paper industry, 0402-25

Purchase

Buying, storing, and handling flexo folder gluer/rotary diecutter adhesives, 0305-25

Purchase orders

Purchase order, 0305-07

Pyrometry

Dryer surface temperature measurement, 0404-39

Q-

Quality

Box plant quality measurement: why test?, 0304-02

Important quality parameters of a printing ink, 0304-

59

Quality techniques using existing equipment, 0306-

11

Starch adhesive trial, 0304-22

Suggestions for developing a box plant quality manual, 0304-49

Quality control

Calculation and partitioning of variance using paper machine scanning sensor measurements, 1101-01

Guideline for direct contact printing of bar code symbols on corrugated, 0306-16

Guidelines for specification and inspection of electric resistance welded (ERW) and seamless boiler tube for critical and noncritical service, 0402-13

Liquid penetrant testing of new suction roll shells, 0402-11

Method for determining length and other properties in rolls of various diameters and basis weights, 1008-02

Quality manual

see Quality

R-

Radiography

Guideline for obtaining high quality radiographic testing of butt welds in boiler tubes, 0402-33

Raw materials

Procedure for setting up a raw material trial on the corrugator, 0304-01

Recausticizing

see Causticizing

Reclaimed fibers

Paper machine clothing cleaning and conditioning for recycled fiber use, 0404-51

Record books

see Documentation

Recovery

Energy checklist: pulp mill, 0422-01

Recovery boilers

Estimating the first melting temperature of fireside deposits in recovery boilers, 0416-12

Field welding of pin studs in black liquor recovery boilers, 0402-15

Guideline specification for procurement of an economizer for a recovery boiler, 0416-21

Guidelines for operating and maintenance practices impacting an economizer on a recovery boiler, 0416-22

Recovery boiler energy efficiency improvements, 0416-16

Recovery boiler performance calculation – short

form, 0416-01

Recovery boiler sootblowers: practical guidelines, 0416-20

Recovery boiler sootblowers: the basics, 0416-19

Recovery furnaces

Chloride and potassium measurement and control in the pulping and chemical recovery cycle, 0416-15

Field welding of pin studs in black liquor recovery boilers, 0402-15

Inspection for cracking of composite tubes in black liquor recovery boilers, 0402-30

Recovery boiler performance calculation – short form, 0416-01

Ultrasonic technician performance test for boiler tube inspection, 0402-21

Recycled fibers

see Reclaimed fibers

Recycled paperboard

Paper machine performance guidelines, 0404-47

Recycled papers

Paper machine performance guidelines, 0404-47

Reels

Determination of winder sets per reel, 0502-02

Paper machine reel spool journals: guidelines for the in-service inspection to detect cracking and repair/replacement considerations, 0402-34

Reel diameter for various reel spool and roll core sizes, 0502-03

TAPPI Roll number for inventory/tracking systems and bar codes, 1004-01

Refiner plates

see Refiner disks

Refiners

Conical refining intensity, 0508-07

Refiner systems, their inspection and maintenance, 0508-06

Refining

Conical refining intensity, 0508-07

Refiner systems, their inspection and maintenance, 0508-06

Register

Computer assisted mounting systems, 0306-02

Regulating systems

see Control systems

Regulations

CONEG heavy metal guidelines, 0304-58

Relative enthalpy

see Enthalpy

Relative humidity

see Humidity

Relief

Water quality and monitoring requirements for paper mill boilers, operating on high purity feedwater, 0416-03

Removal

Chloride and potassium measurement and control in the pulping and chemical recovery cycle, 0416-15

Repair

see Maintenance

Repeatability

How to perform a gauge repeatability and reproducibility study, 0304-71

Reporting

Daily and month-to-date status report, 0305-31

Press fabric record book, 0404-21

Reproducibility

How to perform a gauge repeatability and reproducibility study, 0304-71

Resolution

Basic guidelines for image analysis measurements, 0804-09

Retention

Definitions, 0502-13

Fourdrinier drainage performance evaluation – blow test method, 0410-07

Reverse osmosis

Evaluating reverse osmosis for treating makeup to the boiler feedwater in a pulp and paper mill, 0416-07

Reverse warp

see Warpage

Rewetting

Methods to minimize sheet rewet in the press section, 0404-59

Rider rolls

Total indicated runout and its impact on combined board quality, 0304-56

Ring crush resistance

Techniques for bonding of densified liners, 0304-40

Ring crush tests

Calibration of flexible beam crush tester, 0304-20

Techniques for bonding of densified liners, 0304-40

Rod coaters

see also Coaters

In-line coating at the corrugator, TIP 0304-39

Roll coaters

see also Coaters

In-line coating at the corrugator, TIP 0304-39

Roll core

see Cores

Roll density

see Rolls

Roll handling

see Materials handling, Jumbo rolls

Roll identification

see Rolls

Roll length

see Rolls

Roll number

see Rolls

Roll stands

Splicer defects and cures, 0304-31

Roll tracking

see Rolls

Roll weight

see Rolls

Rolling contact bearings

see Bearings

Rolling scores

see Scores

Rolls

An alternative method for designating flute sizes, 0302-04

Checking the flute depth of corrugating rolls, 0304-75

Checking for coating wear on corrugating rolls, 0304-73

Copper sulfate test for corrugator roll wear, 0304-53

Corrugator temperature audit, 0304-65

Determination of moisture in containerboard using a hand held moisture meter, 0304-63

Granite roll material and surface requirements, 0404-41

Method for determining length and other properties in rolls of various diameters and basis weights, 1008-02

Parallel of corrugating rolls with "NCR" paper, 0304-62

Press roll cover application guidelines, 0404-37

TAPPI Roll number for inventory/tracking systems and bar codes, 1004-01

Total indicated runout and its impact on combined board quality, 0304-56

Weight of newsprint rolls, 0502-11

Rotary diecutter

see Rotary machines, Die cutters; see also Folder gluers

Rotary filters

Bleaching plant washer efficiency guide, 0606-23

Rotary machines

Buying, storing, and handling flexo folder gluer/rotary diecutter adhesives, 0305-25

Cleanup procedures for flexo folder gluer/rotary diecutters, 0305-33

Introduction to flexo folder gluer/rotary diecutter TIPS, 0305-04

Ordering cutting dies, 0305-21

Project leader, 0305-13

Proper use of pull bands, 0305-18

Rotary cutting die maintenance, 0305-23

Rotary diecutter urethane anvil maintenance, 0305-35

Rotation

Pulpstone speed chart, 0605-02

Roundness

see Shape

Rubbing

see also Abrasion resistance

Runnability

Sheet handling devices, 0404-44

Rutile

Titanium dioxide pigment index, 0106-07

S-

Safety

Caustic soda (NaOH) safe storage and handling, 0606-27

Chlorine dioxide (ClO₂) safe storage and handling, 0606-10

Corrugated boxplant-list of potential hazards, 0301-01

Gaseous ozone (O₃) safe handling, 0606-28

Hydrogen peroxide (H₂O₂) safe storage and handling, 0606-24

Material safety data sheets, 0304-38

Methanol (CH₃OH) safe storage and handling, 0606-25

Oxygen (O₂) bulk storage and safe handling, 0606-29

Sodium chlorate (NaClO₃) safe handling and storage

Sulfuric acid (H₂SO₄) safe storage and handling, 0606-26

Safety equipment

Chlorine dioxide (ClO₂) safe storage and handling, 0606-1

Salt

see Sodium chloride

Sampling

Sampling procedures for biomass fuel for boiler performance testing, 0416-17

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Saturated solutions

see Solutions

Scanners

Calculation and partitioning of variance using paper machine scanning sensor measurements, 1101-01

Scheduling

Checklist for a properly planned project, 0408-01

Housekeeping at order and shift change and weekly, 0305-32

Schopper Riegler freeness

Interconversion of freeness, 0809-01

Score breaks

How to prevent score cracking in a box plant, 0304-37

Score cracking

Troubleshooting the diecutting section, 0305-39

Score cracks

see Score breaks

Scores

Minimizing rolling scores on lightweight and high-performance liners in diecutting operations, 0304-64

Preventing score cracking in a box plant, 0304-37

Scoring

Machinery considerations and selection: yoked scoring slotting section, 0305-53

Seal water

see Sealants, Water

Sealants

Guidelines for measurement of vacuum pump air flow, 0420-12

Seamless materials

Guide to the use of stainless steel pipe specifications, 0402-24

Selection

A guide to proper wipe selection for the corrugated box industry, 0306-20

Machinery considerations and selection, 0305-06

Semichemical pulps

Boiling point rise of spent sulfite liquors, 0607-21

Definitions of terms in the sulfite pulping process, 0607-25

Density of aqueous sodium sulfite solution, 0607-18

Density of milk of lime solution, 0607-05

Solubility of sulfur dioxide, $\text{Ca}(\text{HSO}_3)_2$ solutions, 0607-07

Sulfur burner gas strength volume, 0607-01

Viscosities of various spent sulfite liquors at 26.7°C and other temperatures, 0607-22

Sensitivity

Basic guidelines for image analysis measurements, 0804-09

Sensors

Calculation and partitioning of variance using paper machine scanning sensor measurements, 1101-01

Setting time

Understanding and troubleshooting hot melt adhesives, 0304-74

Shafts

Guidelines for inspection and nondestructive examination of paper machine dryers, 0402-16

Paper machine reel spool journals: guidelines for the in-service inspection to detect cracking and repair/replacement considerations, 0402-34

Shape

Total indicated runout and its impact on combined board quality, 0304-56

Sheet water content

see *Moisture content*

Shells

Guidelines for inspection and nondestructive examination of paper machine dryers, 0402-16

Weld repairs on new suction roll shells, 0402-17

Shipping containers

Guideline for direct contact printing of bar code symbols on corrugated, 0306-16

Shock drying

Terminology for high temperature pressing, 0404-48

Showers

Paper machine clothing cleaning and conditioning for recycled fiber use, 0404-51

Paper machine shower recommendations, 0404-61

Press fabric dewatering and conditioning – suction box (Uhle box) design and vacuum requirements. 0404-27

Steam shower applications in the forming section, 0404-58

Silica

Response to contamination of high purity boiler feedwater, 0416-05

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Singlefacers

Addendum to *Corrugating Defect Terminology Manual* - defects related to the use of fingerless singlefacers, 0304-17

Alternative method for designating flute sizes, 0302-04

Causes and corrections of common corrugator bonding problems, 0304-32

Checking for coating wear on corrugating rolls, 0304-73

Checking the flute depth of corrugating rolls, 0304-75

Parallel of corrugating rolls with "NCR" paper, 0304-62

Preventing score cracking in a box plant, 0304-37

Setting up a raw material trial on the corrugator, 0304-01

Some questions and answers on gel temperatures and on the gel temperature test for corrugating adhesives, 0304-08

Splicer defects and cures, 0304-31

Siphons

Guidelines for inspection and nondestructive examination of paper machine dryers, 0402-16

Recommended dryer differential pressures, 0404-31

Skid

Material handling considerations for flexo folder gluers, 0305-54

Slabbing

Broke loss calculations, 0502-10

Slices

Flow from a 45° slice, 0410-03

Flow from a nozzle (slice) with inclined upper lip, 0410-04

Flow from a stock behind slice (head/jet relationship), 0410-05

Flow from a vertical slice, 0410-02

Slide angle

Statistical process control, friction, 0304-34

Slotting

Machinery considerations and selection: yoked scoring slotting section, 0305-53

Slurry

Physical data of calcined kaolin-water suspensions, 0106-09

Physical data of calcium carbonate-water suspensions, 0106-01

Physical data of hydrous Kaolin-water suspensions, 0106-02

Slushed paper stock

see *Paper stock*

Smearing

Reduction or elimination of ink and/or varnish smear when printing and rotary die cutting in one pass, 0305-40

Sodium

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Sodium bicarbonate

Density of aqueous sodium bicarbonate solution, 0607-13

Sodium bisulfite

Vapor pressure of water and sulfur dioxide above sodium bisulfite solutions (25°C), 0607-12

Sodium borate

Some questions and answers on gel temperatures and on the gel temperature test for corrugating adhesives, 0304-08

Sodium carbonate

Density of aqueous sodium carbonate solution, 0607-14

Specific heat of sodium carbonate solution, 0607-15

Vapor pressure of sodium carbonate solution, 0607-16

Viscosity of sodium carbonate solution, 0607-17

Sodium chlorate

Safe storage of, 0606-31

Sodium chloride

Specific gravity of sodium chloride solutions, 0606-10

Sodium hydroxide

Caustic soda (NaOH) safe storage and handling, 0606-27

Relative enthalpy of solution, 0606-08

Some questions and answers on gel temperatures and on the gel temperature test for corrugating adhesives, 0304-08

Specific gravity and density of caustic soda solutions, 0606-20

Specific heat of caustic soda solutions, 0606-07

Viscosity of sodium hydroxide solutions, 0606-11

Sodium sulfite

Density of aqueous sodium sulfite solution, 0607-18

Solids content

Physical data of calcined kaolin-water suspensions, 0106-09

Physical data of calcium carbonate-water suspensions, 0106-01

Physical data of hydrous Kaolin-water suspensions, 0106-02

Titanium dioxide pigment index, 0106-07

Solubility

Solubility of sulfur dioxide, 0607-06

Solubility of sulfur dioxide, $\text{Ca}(\text{HSO}_3)_2$ solutions, 0607-07

Solubility of sulfur dioxide in magnesium bisulfite solution, 0607-09

Solubility of sulfur dioxide in saturated magnesium bisulfite solution, 0607-10

Solutions

Equilibrium relative humidities over saturated salt solutions, 0808-03

Specific heat of caustic soda solutions, 0606-07

Sorption

Cotton in nonwovens, 1205-02

Soot blowers

Recovery boiler sootblowers: practical guidelines,

0416-20

Recovery boiler sootblowers: the basics, 0416-19

SPC techniques

see Statistical methods

Specialty coating pigment

see Pigment

Specific gravity

see Density

Specific heat

Specific heat of caustic soda solutions, 0606-07

Specific heat of sodium carbonate solution, 0607-15

Specifications

Guideline specification for procurement of an economizer for a recovery boiler, 0416-21

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Speed

see Velocity

Spent sulfite liquors

Density of aqueous sodium sulfite solution, 0607-18

Splicers

Splicer defects and cures, 0304-31

Spools

Paper machine reel spool journals: guidelines for the in-service inspection to detect cracking and repair/replacement considerations, 0402-34

Reel diameter for various reel spool and roll core sizes, 0502-03

Spunlaced fabric

Cotton in nonwovens, 1205-02

Spray coaters

see also Coaters

In-line coating at the corrugator, TIP 0304-39

Squared paper

Squaring flap cut (center special) boxes, 0305-45

Squaring

see Squared papers, Trimming

Stackers

Multiple-out rotary diecut stacking, 0305-47

Stacking off the rotary diecutter, 0305-46

Stacking

Corrugated caliper: why is it so important?, 0304-04

Stacking strength

see Compression strength

Stainless steel

Guide to the use of stainless steel pipe specifications, 0402-24

Guidelines for corrosion resistant weld metal overlay of digester vessels in alkaline pulping service, 0402-03

Guidelines for nondestructive examination of suction roll shells, 0402-19

Guidelines for procurement of cast stainless steels for large pumps and valves for the pulp and paper industry, 0402-25

Guidelines for welding and inspection of stainless alloy piping, 0402-26

Inspection for cracking of composite tubes in black liquor recovery boilers, 0402-30

Post-fabrication cleaning of stainless steel in the pulp

and paper industry, 0402-35

Weld repairs on new suction roll shells, 0402-17

Welding of duplex stainless steels, 0402-23

Standard conditions

Testing atmospheres simulating end use conditions, 0808-05

Starch

Green peel bond test at the corrugator, 0304-27

Proper methods of measuring starch adhesive viscosity, 0304-33

Starch adhesive preparation and distribution systems: housekeeping, 0304-06

Starch adhesive trial, 0304-22

Statistical process control of starch gelatinization temperature, 0304-14

Statistical process control of starch viscosity, 0304-15

Techniques for running "WRA" (water resistant starch adhesive), 0304-46

Understanding wet strength: what are MRA, WRA, and WPA?, 0304-69

Using washup water as the vehicle in starch-based corrugating adhesive, 0304-44

Starch conversion

Statistical process control of starch gelatinization temperature, 0304-14

Statistical analysis

How to perform a gauge repeatability and reproducibility study, 0304-71

Obtaining combined board caliper off the corrugator for use statistical process control procedures, 0304-12

Starch viscosity in corrugating adhesives, 0304-15

Statistical distribution

Calculation and partitioning of variance using paper machine scanning sensor measurements, 1101-01

Statistical methods

Boxplant quality measurement: why test?, 0304-02

Obtaining combined board caliper off the corrugator, 0304-12

Procedures for charting warp, 0304-13

Procedures for utilizing statistical control techniques to monitor the tare weight of a run of boxes, 0304-35

Short-run statistical process control: a basic charting method, 0304-70

Statistical process control: friction - slide angle, 0304-34

Statistical process control of starch gelatinization temperature, 0304-14

Statistical process control of starch viscosity, 0304-15

Statistical process control pin adhesion, 0304-23

Statistical process control techniques to assist in meeting specification at finishing crush process control points to the paper and paperboard industries, 0304-11

Statistical process control

see Statistical methods

Statistical quality control

see Statistical methods

Statistics

Calculation and partitioning of variance using paper machine scanning sensor measurements, 1101-01

Obtaining combined board caliper off the corrugator for use in statistical process control procedures, 0304-12

Starch viscosity in corrugating adhesives, 0304-15

Statistical process control of starch gelatinization temperature, 0304-14

Status reports

see Reporting

Steam

Application of dryer bars, 0404-35

Guidelines for inspection and nondestructive examination of paper machine dryers, 0402-16

Increasing the steam pressure rating of ASME coded paper machine dryers, 0420-14

Response to contamination of high purity boiler feedwater, 0416-05

Steam shower applications in the forming section, 0404-58

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Water quality guidelines and monitoring requirements for paper mill boilers operating with softened makeup water, 0416-14

Yankee dryer steam condensing rates, 0404-49

Steam chests

Terminology for high temperature pressing, 0404-48

Steam pressure

see Pressure gradient

Sterilization

Starch adhesive preparation and distribution systems: housekeeping, 0304-06

Stitch bonding

Cotton in nonwovens, 1205-02

Stock flow

Optimum consistency for pumping pulp, 0410-15

Stock (pulp)

Head of stock behind slice (head/jet relationships), 0410-05

Stones

see Pulpstones

Storage

Buying, storing, and handling flexo folder gluer/rotary diecutter adhesives, 0305-25

Caustic soda (NaOH) safe storage and handling, 0606-27

Chlorine dioxide (ClO₂) safe storage and handling, 0606-10

Hydrogen peroxide (H₂O₂) safe storage and handling, 0606-24

Methanol (CH₃OH) safe storage and handling, 0606-25

Oxygen (O₂) bulk storage and safe handling, 0606-29

Sodium chlorate (NaClO₃) safe handling and storage

Sulfuric acid (H₂SO₄) safe storage and handling, 0606-26

Strapping

Critical properties to consider when unitizing, 0304-72

Material handling considerations for flexo folder gluers, 0305-54

Stress corrosion

Guidelines for inspection of continuous digesters and impregnation vessels, 0402-27

Strippers

Stripping of kraft pulping process condensates: regulations, design and operation, 0416-10

Stripping

Troubleshooting the diecutting section, 0305-39

Stuff boxes

Headbox approach piping guidelines, 0404-54

Suction

see *Vacuum*

Suction press rolls

see *Press rolls*, *Vacuum rolls*

Suction presses

Paper machine vacuum selection factors, 0502-01

Suction rolls

see *Vacuum rolls*

Sulfite liquors

Boiling point rise of spent sulfite liquors, 0607-21

Definitions of terms in the sulfite pulping process, 0607-25

Density of aqueous sodium sulfite solution, 0607-18

Density of milk of lime solution, 0607-05

Solubility of sulfur dioxide, $\text{Ca}(\text{HSO}_3)_2$ solutions, 0607-07

Sulfur burner gas strength volume, 0607-01

Viscosities of various spent sulfite liquors at 26.7°C and other temperatures, 0607-22

Sulfite pulping

Boiling point rise of spent sulfite liquors, 0607-21

Definitions of terms in the sulfite pulping process, 0607-25

Density of aqueous sodium sulfite solution, 0607-18

Density of milk of lime solution, 0607-05

Physical and chemical properties of magnesia-base pulping solutions, 0607-04

Solubility of sulfur dioxide, $\text{Ca}(\text{HSO}_3)_2$ solutions, 0607-07

Solubility of sulfur dioxide, 0607-06

Solubility of sulfur dioxide in magnesium bisulfite solution, 0607-09

Solubility of sulfur dioxide in saturated magnesium bisulfite solution, 0607-10

Sulfur burner gas strength volume, 0607-01

Vapor pressure of sulfur dioxide solutions, 0607-11

Vapor pressure of water and sulfur dioxide above sodium bisulfite solutions (25°C), 0607-12

Viscosities of various spent sulfite liquors at 26.7°C, 0607-22

Sulfite waste liquor

see *Spent sulfite liquors*

Sulfur burners

Sulfur burner gas strength volume, 0607-01

Sulfur dioxide

Boiling point rise of spent sulfite liquors, 0607-21

Definitions of terms in the sulfite pulping process, 0607-25

Physical and chemical properties of magnesia-base pulping solutions, 0607-04

Solubility of sulfur dioxide, 0607-06

Solubility of sulfur dioxide, $\text{Ca}(\text{HSO}_3)_2$ solutions, 0607-07

Solubility of sulfur dioxide in magnesium bisulfite solution, 0607-09

Solubility of sulfur dioxide in saturated magnesium bisulfite solution, 0607-10

Sulfur burner gas strength volume, 0607-01

Vapor pressure of sulfur dioxide solutions, 0607-11

Viscosities of various spent sulfite liquors at 26.7°C, 0607-22

Viscosity of a neutral sulfite spent liquor (Ostwald capillary viscometer), 0607-23

Vapor pressure of water and sulfur dioxide above sodium bisulfite solutions (25°C), 0607-12

Sulfuric acid

Sulfuric acid (H_2SO_4) safe storage and handling, 0606-26

Supervision

Project leader, 0305-13

Surface properties

Granite roll material and surface requirements, 0404-41

Surface speed

see *Retention*, *Machine speed*

Suspended solids

Generalized method for determining the pipe friction loss of lowing pulp suspensions, 0410-14

Symbols

Guideline for direct contact printing of bar code symbols on corrugated, 0306-16

Systems

Chloride and potassium measurement and control in the pulping and chemical recovery cycle, 0416-15

T-**Tare weight**

Statistical control techniques to monitor the tare weight of a run of boxes, 0304-35

Task time

see *Time*

Technical nomenclature

see *Nomenclature*

Temperature

Conducting a corrugator temperature audit, 0304-65

Density of aqueous sodium bicarbonate solution, 0607-13

Density of aqueous sodium carbonate solution, 0607-14

Dryer section performance monitoring, 0404-33

Dryer surface temperature measurement, 0404-39
Recommended operation of dryer section hood air systems, 0404-24

Solubility of sulfur dioxide in magnesium bisulfite solution, 0607-09

Solubility of sulfur dioxide in saturated magnesium bisulfite solution, 0607-10

Some questions and answers on gel temperatures and on the gel temperature test for corrugating adhesives, 0304-08

Specific heat of sodium carbonate solution, 0607-15

Statistical process control of starch gelatinization temperature, 0304-14

Statistical process control of starch viscosity, 0304-15

Testing atmospheres simulating end use conditions, 0808-05

Troubleshooting cross-machine direction moisture profile problems, 0404-57

Vapor pressure of sodium carbonate solution, 0607-16

Vapor pressure of sulfur dioxide solutions, 0607-11

Viscosity of a neutral sulfite spent liquor (Ostwald capillary viscometer), 0607-23

Viscosity of sodium carbonate solution, 0607-17

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Tension

Recommended tensions in dryer fabrics, 0404-04

Terminology

see Nomenclature

Test conditions

Testing atmospheres simulating end use conditions, 0808-05

Test equipment

Paper test rooms: design considerations, 0808-04

Test facilities

Paper test rooms: design considerations, 0808-04

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Test methods

Guidelines for measurement of vacuum pump air flow, 0420-12

Testing

Basic guidelines for image analysis measurements, 0804-09

Drainage evaluation by mass measurement, 0502-12

Forming section monitoring, 0502-14

Paper machine reel spool journals: guidelines for the in-service inspection to detect cracking and repair/replacement considerations, 0402-34

Paper test rooms: design considerations, 0808-04

Recommended test procedure for black liquor evaporators, 0416-11

Water removal by wet presses, 0404-01

Thermal measurement

Recovery boiler performance calculation – short form, 0416-01

Thermal spray

Guidelines for applying thermal spray coatings to protect pulp mill process equipment against corrosion, 0402-32

Guidelines for inspecting batch digesters, 0402-22

Thermobonding

Cotton in nonwovens, 1205-02

Thermography

Troubleshooting cross-machine direction moisture profile problems, 0404-57

Thick stock

see High consistency

Thickness

Corrugated caliper: why is it so important?, 0304-04

Method for determining length and other properties

in rolls of various diameters and basis weights, 1008-02

Method for evaluating thickness of wet press fabrics, 0404-28

Obtaining combined board caliper off the corrugator for use in statistical process control procedures, 0304-12

Statistical process control techniques to assist in meeting specification at finishing crush process control points to the paper and paperboard industries, 0304-11

Through drying

Through drying, 0404-25

Titanium dioxide

Titanium dioxide pigment index, 0106-07

Tolerance

Corrugator bearing clearance checks and their impact, 0304-47

Total indicated runout

see also Combined boards

Total indicated runout and its impact on combined board quality, 0304-56

Total reduced sulfur

Collection and burning of concentrated noncondensable gases: regulations, design and operation, 0416-09

Transport

Checklist: preparing die cuts for shipment, 0305-49

Sodium chlorate (NaClO₃) safe handling and storage

Sulfuric acid (H₂SO₄) safe storage and handling, 0606-26

Trim

Broke loss calculations, 0502-10

Paper machine room ventilation guidelines, 0404-50

Trimming

Machinery considerations and selection: yoked scoring slotting section, 0305-53

Squaring flap cut (center special) boxes, 0305-45

Troubleshooting

Forming section monitoring, 0502-14

Glue lap problem, 0304-10

Index of suppliers for press section monitoring, 0404-62

Press section monitoring, 0404-19

Recommended test procedure for black liquor evaporators, 0416-11

Steam shower applications in the forming section.

0404-58

Tubes

Guidelines for operating and maintenance practices impacting an economizer on a recovery boiler, 0416-22

Keys to successful chemical cleaning of boilers, 0416-06

Inspection for cracking of composite tubes in black liquor recovery boilers, 0402-30

Ultrasonic technician performance test for boiler tube inspection, 0402-21

Tuning

see Control

Twisting

Techniques to minimize twist warp, 0304-50

U-

Uhle boxes

See also Vacuum boxes

Press fabric dewatering and conditioning – suction box (Uhle box) design and vacuum requirements. 0404-27

Ultrafine ground limestone

see Limestone

Ultraviolet radiation

Drying and curing techniques for in-line flexographic printing, 0306-06

Ultrasonic tests

Guidelines for evaluating quality of boiler tube butt welds with ultrasonic testing, 0402-31

Guidelines for inspecting batch digesters, 0402-22

Ultrasonic technician performance test for boiler tube inspection, 0402-21

Unitized handling

Critical properties to consider when unitizing, 0304-72

Units of measurement

Units of measurement and conversion factors, 0800-01

Unloading

Sodium chlorate (NaClO₃) safe handling and storage

Sulfuric acid (H₂SO₄) safe storage and handling, 0606-26

U.P.C.

see Product codes

Urethanes

Rotary diecutter urethane anvil maintenance, 0305-35

V-

Vacuum

High vacuum sheet dewatering, 0404-60

Paper machine vacuum selection factors, 0502-01

Papermaker's formulas, 0502-17

Steam shower applications in the forming section, 0404-58

Vacuum boxes

High vacuum sheet dewatering, 0404-60

Paper machine vacuum selection factors, 0502-01

Performance evaluation techniques for paper

machine vacuum systems, 0404-55

Vacuum equipment

Press fabric dewatering and conditioning – suction box (Uhle box) design and vacuum requirements, 0404-27

Vacuum filters

Bleaching plant washer efficiency guide, 0606-23

Vacuum pumps

Guidelines for measurement of vacuum pump air flow, 0420-12

Performance evaluation techniques for paper machine vacuum systems, 0404-55

Press fabric dewatering and conditioning – suction box (Uhle box) design and vacuum requirements. 0404-27

Vacuum rolls

Guidelines for nondestructive examination of suction roll shells, 0402-19

Liquid penetrant testing of new suction roll shells, 0402-11

Paper machine vacuum selection factors, 0502-01

Press roll cover application guidelines, 0404-37

Weld repairs on new suction roll shells, 0402-17

Vacuum washers

Bleaching plant washer efficiency guide, 0606-23

Valves

Guidelines for procurement of cast stainless steels for large pumps and valves for the pulp and paper industry, 0402-25

Headbox approach piping guidelines, 0404-54

Vapor pressure

Chlorine gas curve, 0606-02

Vapor pressure of sulfur dioxide solutions, 0607-11

Vapor pressure of sodium carbonate solution, 0607-16

Vapor pressure of water and sulfur dioxide above sodium bisulfite solutions (25°C), 0607-12

Variance

Calculation and partitioning of variance using paper machine scanning sensor measurements, 1101-01

Varnish

Reduction or elimination of ink and/or varnish smear when printing and rotary die cutting in one pass, 0305-40

Velocity

see also Machine speed

Pulpstone speed chart, 0605-02

Ventilation

Paper machine room ventilation guidelines, 0404-50

Recommended minimum dryer pocket air requirements, 0404-17

Recommended operation of dryer section hood air systems, 0404-24

Viscosity

Density of aqueous sodium sulfite solution, 0607-18

Liquid chlorine, 0606-05

Proper methods of measuring starch adhesive viscosity, 0304-33

Quality techniques using existing equipment, 0306-

Statistical process control of starch viscosity, 0304-15

Viscosities of spent sulfite liquors at 26.7° C (Oswald capillary viscometer), 0607-22

Viscosity of a neutral sulfite spent liquor (Oswald capillary viscometer), 0607-23

Viscosity of sodium carbonate solution, 0607-17

Viscosity of sodium hydroxide solutions, 0606-11

Viscosity reading procedure for flexographic corrugated inks, 0304-18

Vision

Basic guidelines for image analysis measurements, 0804-09

Volume

Grinder pulpstones – cubical contents, 0605-01

Identifying anilox volume measuring equipment, 0306-15

W-

Warning labels

see Hazardous materials

Warpage

Go/no go gauge devices for the boxplant, 0304-42

Statistical process control -- procedures for charting warp, 0304-13

Techniques to minimize twist warp, 0304-50

Warp in corrugated board, 0304-07

Wash waters

Using washing water as the vehicle in starch based corrugating adhesive, 0304-44

Washers

Bleaching plant washer efficiency guide, 0606-23

Washing

Bleaching plant washer efficiency guide, 0606-23

Recommended pulp bleaching stage designation method, 0606-21

Wastewater treatment equipment

see Effluent treatment

Water

see also Solubility

Design engineer decisions tree: paper mill boiler feedwater, 0416-04

Guidelines for measurement of vacuum pump air flow, 0420-12

Vapor pressure of water and sulfur dioxide above sodium bisulfite solutions (25°C), 0607-12

Water treatment-related opportunities for energy conservation in a paper mill powerhouse, 0416-13

Water content

see Moisture content

Water hardness

Water quality and monitoring requirements for paper mill boilers operating on high purity feedwater, 0416-03

Water permeability

Troubleshooting cross-machine direction moisture profile problems, 0404-57

Water removal

Determination of water removal by wet presses, 0404-01

High vacuum sheet dewatering, 0404-60

Methods to minimize sheet rewet in the press section, 0404-59

Paper machine drying rate, 0404-07

Water resistance

Techniques for running "WRA" (water resistant starch adhesive), 0304-46

Understanding wet strength: what are MRA, WRA, and WPA?, 0304-69

Water treatment

Design engineer decisions tree: paper mill boiler feedwater, 0416-04

Water treatment-related opportunities for energy conservation in a paper mill powerhouse, 0416-13

Water vapor

Paper machine room ventilation guidelines, 0404-50

Wax

Common curtain coating problems: causes, detection, and correction, 0304-26

Curtain coating weight test, 0304-19

Wear resistance

see Abrasion resistance

Webs

see Paper webs

Weight

Physical characterization of press fabrics: basis weight, air permeability, void volume under loading and pressure uniformity, 0404-20

Procedure for utilizing statistical control techniques to monitor the tare weight of a run of boxes, 0304-35

Weight of newsprint rolls, 0502-11

Weirs

Weirs and flumes, 0410-10

Welding

Clad-steel plate use, 0402-04

Duplex stainless steels, 0402-23

Guide to the use of stainless steel pipe specifications, 0402-24

Guidelines for corrosion resistant weld metal overlay of digester vessels in alkaline pulping service, 0402-03

Guidelines for evaluating quality of boiler tube butt welds with ultrasonic testing, 0402-31

Guidelines for inspection of continuous digesters and impregnation vessels, 0402-27

Guidelines for procurement of cast stainless steels for large pumps and valves for the pulp and paper industry, 0402-25

Guidelines for welding and inspection of stainless alloy piping, 0402-26

Field welding of pin studs in black liquor recovery boilers, 0402-15

Wet bulb temperature

Relative humidity tables, 0808-06

Wet ends

Drainage evaluation by mass measurement, 0502-12

Forming section monitoring, 0502-14

How to prevent score cracking in a box plant, 0304-

37

Selection criteria for wet end ceramics, 0502-15

Wet felts

see also Felts

Porosity measurement of press felts on the paper machine (HSPT), 0404-29

Wet presses

Determination of water removal by, 0404-01

Wet pressing

Terminology for high temperature pressing, 0404-48

Wet strength

Understanding wet strength: what are MRA, WRA, and WPA?, 0304-69

Wet-laid nonwovens

Pilot paper machines, 0502-16

White liquors

Recausticizing material balance equations relating to digester requirements, 0418-02

White water

Drainage evaluation by mass measurement, 0502-12

Flow determination by chemical method, 0410-09

Weirs and flumes, 0410-10

Width

Weight of newsprint rolls, 0502-11

Williams freeness

Interconversion of freeness, 0809-01

Winders

Determination of winder sets per reel, 0502-02

Wiperoll

see Flexography

Wood

Calibration technique for the drum style chip thickness classifier, 0602-03

Wood chips

see Chips

Wood containing papers

see Mechanical papers

Wood free papers

Paper machine drying rate, 0404-07

Work place

see Human factors

Working conditions

see Environments

Wound rolls

Method for determining length and other properties in rolls of various diameters and basis weights, 1008-02

Reel diameter for various reel spool and roll core sizes, 0502-03

TAPPI Roll number for inventory/tracking systems and bar codes, 1004-01

Woven fabric

Press fabric record book, 0404-21

Writing papers

Paper machine drying rate, 0404-07

X-Y-Z-**Yankee cylinders**

see Yankee dryers

Yankee dryers

Yankee dryer steam condensing rates, 0404-49