

Rotary Diecutting, Dimensional Accuracy Control

Edited by Kenneth T. Kunkel

Prepared by the Engineering Committee of the Corrugated Containers Division Committee
CA90030201.

1992. 48 pp., 8-1/2" x 11" soft cover
Item Number: 0101R205
ISBN: 0898522749

This publication explains the rotary diecutting process, equipment, set-up, operation, and effects on various board properties. It concludes with a comprehensive troubleshooting guide. Contents include; analysis of the diecutting process; measurement; cutting die; anvil, set-up and impression; pull rolls; equipment; corrugated board; and, troubleshooting.

Table of Contents

A. Analysis of the diecutting process

A.0 Introduction

A.1 Measurement

A.2 Cutting Die

- Rule height

- Die rubber effect on diecut dimensions

- Back of dieboard not clean

- Rule not seated

- Improper die bolt hole location

- Die stretch factor

- Wood thickness

- Die error

- Building dies from diecut sample

A.3 Anvil

- General

- Anvil blankets

- Variable-speed anvils

- Anvil trimming devices

- Free anvils

- Rotary hard anvil

A.4 Setup and impression

- General

- Roll pressures

- Operating speed

- Die mounting

- Impression setting

B.0 General

B.1 Short "Thru" Diecut Length Produced

B.2 Long "Thru" Diecut Length Produced

B.3 Diecut Not Stripping

A.5 Pull Rolls

- General

- Pull roll diameter

- Ink buildup on pull rolls

- Dimensional variation through the sheet

A.6 Equipment

- General

- Feed end

- Print section

- Stacker

- Chevron die

A.7 Corrugated Board

- Moist board

- Dry board

- Hot board

- Litho label board

- Board from recycled paper

- Wax-impregnated board

- High test single wall and double wall

- Flute orientation

- Warped board

- Board caliper

A.8 Conclusion

B. Troubleshooting

B.4 Dangers Produced with Diecut

B.5 Corrugated Board Cracking

B.6 Corrugated Board Crush Marks

B.7 "Across Machine" Diecut Dimensions Not

Rotary Diecutting, Dimensional Accuracy Control
Edited by Kenneth T. Kunkel

Correct

B.8 Narrow Slots Not Stripping

B.9 Die Not Cutting 100%

B.10 Score Impression Not Adequate

Bibliography

Conversion Factors for SI Units

TAPPI Vision Statement

TAPPI PRESS Publications/Corrugated

Containers

List of Figures and Tables

Fig. 1. Cross section of typical flexographic diecutter

Fig. 2. Determination of theoretical distance from die cylinder to print repeat

Fig. 3a. Theoretical scoring rule heights

Fig. 3b. Theoretical cutting rule heights

Fig. 4. Calculation of blanket neutral point thickness

Fig. 5. Troubleshooting flow chart

Table 1. Error attempted by anvil for various diecut sheet sizes

Table 2. Error attempted by impression for various diecut sheet sizes

Table 3. Error attempted by pull roll for various diecut sheet sizes